

ASS. REQ. BY:

REF:

C72/21008714/K6

C


Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s CITY AUTO  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 02 days Res.: Yes or No  
 Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SNN 9159P Yr Regn: 08, 19  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toy P. W. S. C.C. 1797  
 Colour: M. P. W. R. A/C: Insured / Std / NI / NA  
 Sp. Reading: 182174 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JTD 7S3E430 J047063  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modl: NII / S/Rlm / STD A/Rlm or \_\_\_\_\_  
 Tyre Size: F: Mistake 205/80R18  
 R: Fin 178

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

|                       |                         |
|-----------------------|-------------------------|
| Front                 | Rear                    |
| R/Bal. <u>6</u> mm    | R/Bal. <u>8</u> mm      |
| L/Bal. <u>6</u> mm    | L/Bal. <u>8</u> mm      |
| D.O.A. <u>17/8/21</u> | D.O.I. <u>19/8/2021</u> |

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/9 21623.43 Costant

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

S + RS. SI

FURTHER

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)



# CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

CHINA TAIPING INSURANCE (S) PTE LTD

NO. 3  
ANSON RD  
SPRINGLEAF TOWER  
SINGAPORE 079909

Contact : -

Fax No. : 62247175

Estimate : QUOT202108-000576(00)

Date : 19/08/2021

Vehicle No. : SMN9159P

Make/Model : TOYOTA PRIUS PLUS (AUTO)

Mileage (km) : 182173

Chassis No. : JTDZS3EU30J047063

Accident Date : 17/08/2021 00:00:00

Claim No. : GBL3305P

Reference : JO202108-0752

Policy No. : 20-ML000510-R00

*Not Authorized*  
*Running B4 pain*

*2 days*

*81625.45*

| S/No                                                                                             | Particular                             | Quantity | Unit Price | Amount S\$            |
|--------------------------------------------------------------------------------------------------|----------------------------------------|----------|------------|-----------------------|
| <b>LIST ITEMS :</b>                                                                              |                                        |          |            |                       |
| 1                                                                                                | Rear bumper (upper) <i>523.90</i>      | 1.0      | 556.40     | <i>Br/um</i> 556.40 ✓ |
| 2                                                                                                | Rear bumper (lower) <i>76891 47040</i> | 1.0      | 849.90     | <i>Dr/Bu</i> 849.90 ✓ |
| 3                                                                                                | Rear bumper sponge                     | 1.0      | 98.00      | <i>sn</i> 98.00 ✗     |
| 4                                                                                                | Rear bumper reinforcement              | 1.0      | 216.80     | <i>R</i> 216.80 ✗     |
| 5                                                                                                | Rear Bumper clips                      | 12.0     | 2.00       | <i>sn</i> 24.00 ✓     |
| 6                                                                                                | Rear bumper retainer                   | 2.0      | 142.80     | 285.60 ✓              |
| List Total :                                                                                     |                                        |          |            | 2,030.70              |
| 25% Discount S\$                                                                                 |                                        |          |            | 507.67                |
|                                                                                                  |                                        |          |            | 1,523.03              |
| <b>SPECIAL NET :</b>                                                                             |                                        |          |            |                       |
| 1                                                                                                | Reverse sensor                         | 1.0      | 300.00     | <i>sn</i> 300.00 ✗    |
| SPECIAL NET Total S\$:                                                                           |                                        |          |            | 300.00                |
| <b>LABOUR :</b>                                                                                  |                                        |          |            |                       |
| - To install reverse sensor                                                                      |                                        | 1.0      | 60.00      | 60.00 <i>501</i>      |
| -To knock jackout damaged parts, panel beating,welding, align, refix and to renew accident parts |                                        | 1.0      | 400.00     | 400.00 <i>2001</i>    |
| - Spray painting on affected & replace parts                                                     |                                        | 1.0      | 400.00     | 400.00 <i>2201</i>    |
|                                                                                                  |                                        |          |            | 860.00                |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 2,683.03  
GST 7% S\$: 187.81  
Amount Due S\$: 2,870.84

for CITY AUTO PTE LTD