## MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 # 01-61 SINGAPORE 408717

Tel: 67484422 / 67454422 Fax: 6747- 6720 REG NO 200501102H

Fax: 6835 - 7416

Attn: Motor Claim Dept

(Pls arrange vehicle survey & check liability)

## RE: ESTIMATE FOR ACCIDENT REPAIR SME5945K (BMW 520i)

NC.	ESTIMATE FOR ACCIDENT REPAIR	SINIESS4SIC (DINIV	3201)		
Item	Description		_Qty	_Amt	
NO	LIST ITEMS				
1 2 3 4 5 6	Rear Bumper Distorted Rear Bumper Side Holder - LH & RH Rear Bumper Reflector - LH & RH Rear Bumper Reinforcement Rear Bumper Reinforcement Cover Rear Bumper Centre Guide Coulded		1 2 2 1 1	1,628.00 136.00 198.00 863.00 285.00 165.00 117.00	
7	Rear Bumper Centre Garnish Strip				53.00
8	Rear Bumper Tow Cover Rear Bumper Undercover		1		355.00
	S/NETT ITEMS	Less 10%		\$	3,800.00 (380.00) 3,420.00
	Rear Bumper Clips		1 set	\$	50.00
1	Reverse Sensor	570.	2	\$	500.00
3	Rear Bumper Undercover Clips		1 set	\$	20.00
				\$	570.00
		Total Parts		\$	3,990.00
	LABOUR CHARGE - REAR PORTION				
1	To knocking & pull out rear portion & re	o knocking & pull out rear portion & renew above parts		\$	500.00 400°
2	To putty & spray up paint works			\$	500.00 400

## RE: ESTIMATE FOR ACCIDENT REPAIR SME5945K (BMW 520i)

		<b>Grand Total</b>	\$ 5,340.00
		Total Labour	\$ 1,350.00
5	To perform dianogstic test		\$ 200.00 100
4	To remove reverse sensor	590	\$ 100.00 60
3	To check wiring		\$ 50,00 33

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

tolal: 4754.10 HS: 3.8K. 03Days.

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: