



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 8069U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT GRILLE ASSY (CONSISTENT)	NOT NECESSARY	1,259.00	-
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,474.00	-
2	FRONT BUMPER SIDE RETAINER @\$33.00 (CONSISTENT)	SERVICEABLE	66.00	-
10	FRONT BUMPER CLIPS @\$9.00 (CONSISTENT)	SERVICEABLE	90.00	-
1	FRONT BUMPER FOG LAMP COVER GRILLE (CONSISTENT)	MTG CRACKED	107.00	107.00
1	FRONT BUMPER SPOILER (CONSISTENT)	CUT	339.00	339.00
1	FRONT RH FENDER (CONSISTENT)	DENTED	820.80	744.00
1	FRONT RH FENDER DUST GARNISH (CONSISTENT)	NOT NECESSARY	299.00	-
10	FRONT RH FENDER DUST GARNISH CLIPS @\$9.00 (CONSISTENT)	NOT NECESSARY	90.00	-
1	RH REAR FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	1,980.00	-
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,480.00	-
	LESS 10% DISCOUNT		-	-119.00
			8,004.80	1,071.00
<u>SPECIAL NETT ITEMS</u>				
2	SPORT RIM @\$1590.00 (SN) (CONSISTENT)	REAR CUT / BENT / FRONT NOT NECESSARY	3,180.00	800.00
			3,180.00	800.00
<u>LABOUR</u>				
	TO REMOVE & REFIT BALANCING TYRE .		120.00	60.00
	TO REPAIR & RENEW ,STRAIGHTENING KNOCKING ON ALL ACCIDENT AFFECTED AREA .INCLUSIVE OF THE REPAIR OF FRONT BUMPER ,RH REAR FENDER AND REAR BUMPER.		800.00	700.00
	TO CHECK & ADJUST COMPUTER WHEEL ALIGNMENT ,CAMBER & CASTOR.		180.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA.		1,200.00	900.00
			2,300.00	1,720.00
GRAND TOTAL			13,484.80	3,591.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,850.00

Report Ref No. CC4/ASM21008716/Dpa3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.