

## ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538 Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E Email: alfredauto@hotmail.com



Reference No.: 180821

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 18.08.2021

Chang Chih-Tung Charles 44 Woo Mon Chew Road Singapore 455121

Audi T TC 3.2 Quattro S-Tronic

## Estimate Repair Cost for Vehicle Reg. No: SKS 8069 U

1 Pc. Front Grille Assy. ₩		1,259.00 % APA X
1 Pc. Front Bumper Leve		1,474.00 ×
2 Pcs. Front Bumper Side Retainer Svc	@ 33.00	66.00 ×
10 Pcs. Front Bumper Clips 🖫 ८	@ 9.00	90.00 %
1 Pc. Front Bumper Fog Lamp Cover Grille wor	my acute	107.00
1 Pc. Front Bumper Spoiler ℃→		339.00
1 Pc. Front RH Fender Dech		820.80 744.00
1 Pc. Front RH Fender Dust Garnish 🔫		299.00 ×
10 Pcs. Front RH Fender Dust Garnish Clips ың		90.00 🗡
2 Pcs. Sport Rim IPC rear CLUT 184	@ 1,590.00	3,180.00 LL 800.00 SN
Just Hu	and the second	

THE THAT		
	Total (Panels / Parts):	7,724.80 (SGD)
Rea brook X1	Per X	1980.00 X
LABOR CHARGES		
To remove & refit balancing tyre		120.00 60 /-
To repair & renew, straightening Accident affected area.	, knocking on all	800.00 Hos.

To check & adjust computer wheel alignment, camber & castor.	180.00 60 / 1720.00	


To respray painting on all accident affected area. 1,200.00 900 |

しいま 1190・の SM Total (Labor Charges): 2,300.00 (SGD)
1073 1071・の 800・の 3591・の 1(5 2850・の)



Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538 Fax: 6483 4882 Reg. No. 391089/00-E Tel: 6483 4586 Email: alfredauto@hotmail.com



## **TOTAL COST SUMMARY**

PANELS / PARTS LABOR CHARGES 7,724.80 2,300.00

**Grand Total:** 

10,024.80 (SGD)

We shall be glad if you can forward the payment at your early convenience.

For internet banking transfer - OCBC Current Account No. 620-453233-001 or **PAYNOW UEN 39108900E** 

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

19/08/2021 @ 1530h HVA ANTUL 1/5mm 6 days. LKK AND

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature: Date: