

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/04
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088884-2

Estimate

19/08/2021

LONPAC INSURANCE BHD
 300 BEACH ROAD
 #17-04/07 The Concourse
 SINGAPORE 199555.

Page # :- 1

OK 141852

Veh # :- XE952S

Veh Model :- SCANIA P400LA4X2MSZ

Estimate# :- CK422181

Claim # :-

ACC. Date :- 10/08/21

Terms :- C.O.D Days

Remarks :-

Attention :- XA025

No. Description Qty U.Price Amounts S\$

| No. | Description | Qty | U.Price | Amounts S\$ |
|---------------------|---|------|----------|-------------|
| LIST ITEMS : | | | | |
| 1. | FRONT WINDSCREEN GLASS / BR | 1 PC | 1,450.00 | 1,450.00 ✓ |
| 2. | FRONT WINDSCREEN GLASS SIDE MOULDING RH / TN | 1 PC | 180.00 | 180.00 ✓ |
| 3. | SUN VISOR TOP / BR | 1 PC | 900.00 | 900.00 ✓ |
| 4. | SUN VISOR BOTTOM / BR | 1 PC | 850.00 | 850.00 ✓ |
| 5. | SUN VISOR LAMP RH / ? x nn | 1 PC | 75.00 | 75.00 X |
| 6. | BONNET / DD | 1 PC | 2,450.00 | 2,450.00 ✓ |
| 7. | BONNET HINGE RH & LH / DT | 2 PC | 65.00 | 130.00 ✓ |
| 8. | BONNET DAMPER RH & LH / DT | 2 PC | 185.00 | 370.00 ✓ |
| 9. | BONNET INNER BRACKET / DT | 1 PC | 950.00 | 950.00 ✓ |
| 10. | BONNET LOCK RH & LH / DT | 1 PC | 85.00 | 170.00 ✓ |
| 11. | BONNET CATCH RH & LH / DT | 1 PC | 45.00 | 90.00 ✓ |
| 12. | BONNET EMBLEM - SCANIA / DT nrc | 1 PC | 180.00 | 180.00 ✓ |
| 13. | BONNET GRILLE RH / DT | 1 PC | 40.00 | 40.00 ✓ |
| 14. | BONNET OPENER / ? x nn | 1 PC | 75.00 | 75.00 X |
| 15. | BONNET CABLE / ? x nn | 1 PC | 80.00 | 80.00 X |
| 16. | BONNET GRILLE - TOP / DT | 1 PC | 160.00 | 160.00 ✓ |
| 17. | BONNET GRILLE - BOTTOM / DT | 1 PC | 170.00 | 170.00 ✓ |
| 18. | FRONT CORNER GARNISH RH / mis | 1 PC | 420.00 | 420.00 ✓ |
| 19. | FRONT CORNER GARNISH INNER RH / mis | 1 PC | 350.00 | 350.00 ✓ |
| 20. | FRONT CORNER AIR GUIDE RH / mis | 1 PC | 150.00 | 150.00 ✓ |
| 21. | HEADLAMP TOP GARNISH RH / BR | 1 PC | 250.00 | 250.00 ✓ |
| 22. | SIDE LAMP ASSY RH / BR | 1 PC | 100.00 | 100.00 ✓ |
| 23. | FRONT BUMPER SIDE RH / BR x R | 1 PC | 450.00 | 450.00 X |
| 24. | FRONT DOOR PILLAR RH / DD | 1 PC | 980.00 | 980.00 ✓ |
| 25. | FRONT DOOR HINGE TOP RH / DT | 1 PC | 145.00 | 145.00 ✓ |
| 26. | FRONT DOOR HINGE BOTTOM RH / DT | 1 PC | 145.00 | 145.00 ✓ |
| 27. | FRONT DOOR RH / DD | 1 PC | 3,850.00 | 3,850.00 ✓ |
| 28. | FRONT DOOR GLASS RH / BR | 1 PC | 680.00 | 680.00 ✓ |
| 29. | FRONT DOOR GLASS CHANNEL RH / DT | 1 PC | 220.00 | 220.00 ✓ |
| 30. | FRONT DOOR GLASS REGULATOR RH / DT ? x nn | 1 PC | 350.00 | 350.00 ✓ |
| 31. | FRONT DOOR GLASS REGULATOR MOTOR RH / DT | 1 PC | 300.00 | 300.00 X |
| 32. | FRONT DOOR OUTER MOULDING RH / mis | 1 PC | 110.00 | 110.00 ✓ |
| 33. | FRONT DOOR OUTER HANDLE RH / BR | 1 PC | 200.00 | 200.00 ✓ |
| 34. | FRONT DOOR LOCK RH / ? x nn | 1 PC | 210.00 | 210.00 ✓ |
| 35. | FRONT DOOR INNER TRIM RH / BR | 1 PC | 1,450.00 | 1,450.00 ✓ |
| 36. | FRONT DOOR WEATHERSTRIP RH / TN | 1 PC | 285.00 | 285.00 ✓ |
| 37. | FRONT DOOR STEP PANEL TOP RH / BR | 1 PC | 165.00 | 165.00 ✓ |
| 38. | FRONT DOOR STEP GARNISH RH / BR | 1 PC | 325.00 | 325.00 ✓ |
| 39. | FRONT DOOR BODY WEATHERSTRIP RH / BR TN | 1 PC | 425.00 | 425.00 ✓ |
| 40. | FRONT DOOR LOCK STRIKER RH / ? x nn | 1 PC | 35.00 | 35.00 ✓ |
| 41. | FRONT DOOR ARCH GARNISH RH / CR4 | 1 PC | 460.00 | 460.00 ✓ |
| 42. | FRONT DOOR MIRROR BRACKET RH / BR | 1 PC | 120.00 | 120.00 ✓ |
| 43. | FRONT DOOR MIRROR TOP RH / cut | 1 PC | 480.00 | 480.00 ✓ |
| 44. | FRONT DOOR MIRROR BOTTOM RH / cut | 1 PC | 420.00 | 420.00 ✓ |
| 45. | FRONT QUATER PANEL RH / DD | 1 PC | 1,400.00 | 1,400.00 ✓ |
| 46. | FRONT QUATER PANEL GLASS RUBBER RH / CR4 ? x nn | 1 PC | 180.00 | 180.00 ✓ |
| 47. | FRONT QUATER PANEL INNER TRIM RH - CHECK | 1 PC | 440.00 | 440.00 ✓ |
| 48. | FRONT FENDER COWLING RH / BR | 1 PC | 440.00 | 440.00 ✓ |
| 49. | DASHBOARD - CHECK / ? x nn | 1 PC | | |

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 100B,
 Bukit Merah Lane 3,
 #01-04/05/08/09
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

19/08/2021

LONPAC INSURANCE BHD
 300 BEACH ROAD
 #17-04/07 The Concourse
 SINGAPORE 199555.

Attention :- XA025

Page # :- 1 141852
 Veh # :- XE952S
 Veh Model :- SCANIA P400LA4X2MSZ
 Estimate# :- CK422181
 Claim # :-
 ACC. Date :- 10/08/21
 Terms :- C.O.D Days
 Remarks :-

| No. | Description | Qty | U.Price | Amounts S\$ |
|----------------------------|--|------|-------------|-------------|
| | LIST TOTAL S\$ | | | 23,415.00 |
| | 15% COST PLUS S\$ | | | 3,512.25 |
| | | | | 26,927.25 |
| SPECIAL NET ITEMS : | | | | |
| 1. | FRONT WINDSCREEN GLASS SEALANT <i>nec</i> | 1 PC | 40.00 | 40.00 ✓ |
| 2. | E.R.P BRACKET <i>nec</i> | 1 PC | 15.00 | 15.00 ✓ |
| 3. | FRONT DOOR SUN VISOR <i>BR</i> | 1 PC | 120.00 | 120.00 ✓ |
| 4. | FRONT QUATER PANEL GRAPHIC STICKER <i>nec</i> | 1 PC | 350.00 | 350.00 ✓ |
| | SPECIAL NET TOTAL S\$ | | | 525.00 |
| LABOUR : | | | | |
| | TO CUT / WELD FRONT DOOR PILLAR RH, FRONT QUATER PANEL RH, KNOCK AND STRAIGHTEN FRONT BODY MEMBER. REMOVE & REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION | | <i>2500</i> | 2,800.00 |
| | SPRAY PAINT SUN VISOR TOP, BONNET, FRONT CORNER GARNISH RH, FRONT DOOR PILLAR RH, FRONT DOOR RH, FRONT QUATER PANEL RH, FRONT INNER PANEL RH | | <i>1400</i> | 1,800.00 |
| | REMOVE & REPLACE FRONT WINDSCREEN GLASS CHECK WATER LEAKAGE | | <i>200</i> | 250.00 |
| | REMOVE & REPLACE DASHBOARD ASSY, CENTER CONSOLE, GLOVE BOX ASSY AND OTHER ATTACHMENT PARTS <i>(photo)</i> | | <i>300</i> | 400.00 |
| | REMOVE & REPLACE REAR QUATER PANEL INNER TRIM UPHOUSTERY, SIDE GARNISH | | <i>80</i> | 100.00 |
| | REMOVE & REPLACE FRONT SEAT ASSY, FLOOR CARPET, COVERINGS <i>(photo)</i> | | <i>100</i> | 150.00 |
| | REMOVE & REPLACE FRONT QUATER GLASS RH & CHECK WATER LEAKAGE | | <i>80</i> | 100.00 |
| | REMOVE & REPLACE FRONT DOOR INNER TRIM, MECHANISM & CHECK LOCKING | | <i>50</i> | 80.00 |
| | TO DIAGNOSE & RESET SYSTEM AFTER REPAIR | | <i>150</i> | 350.00 |
| | LABOUR TOTAL S\$ | | | 6,030.00 |

Estimate

19/08/2021

LONPAC INSURANCE BHD
 300 BEACH ROAD
 #17-04/07 The Concourse
 SINGAPORE 199555.

Attention :- XA025

Page # :- 1 141852
 Veh # :- XE952S
 Veh Model :- SCANIA P400LA4X2MSZ
 Estimate# :- CK422181
 Claim # :-
 ACC. Date :- 10/08/21
 Terms :- C.O.D Days
 Remarks :-

Main Office:
 Move Building
 No. 22, Jalan Kilang
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/04
 Singapore 159722
 Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

| No. | Description | Qty | U.Price | Amounts S\$ |
|-----|-------------|-----|---------|-------------|
|-----|-------------|-----|---------|-------------|

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$

33,482.25

GST @ 7 %

2,343.76

AMOUNT DUE S\$

35,826.01

 Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Steve (LKK)
20/8/21, 12.00pm

OO-NM AL
EXCESS-?
L/S
M AL Sy
25 dys

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: