

ASS. REC. BY:

REF:

LPC / 210087201K6

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Estem

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLP 44387 Yr Regn: 06, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hande A. Vetei c.c. 1498Colour: M. Blue A/C: Insured / Std / NI / NASp. Reading: 370.987 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: BU 3 1245254Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD / Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Davanti

Front

R/Bal. 8 mm

Rear

R/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 19/8/21D.O.I. 31/8/2021

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / UIC / Rooftop orRear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/11/21 SLP 44387 2600cc Custom

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP

385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP

176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SLP 4438 T

Parts	(a) Cost / List Price Items	\$	<u>3,863.00</u>
	Plus/Less 20%	\$	<u>772.60</u>
	Total of Cost / List	\$	<u><u>3,090.40</u></u>
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	<u>50.00</u>
Total Parts Cost		\$	<u><u>3,140.40</u></u>
Labour		\$	<u><u>2,380.00</u></u>
Total		\$	<u><u>5,520.40</u></u>

The above total will be subjected to 7% G.S.T.

*Not Authorized
L1Pm \$2600p
Resurvey After Repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kennerh
Company : LKK
Survey conducted on : 31/8/21 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : _____

Date: 31/8/21



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. : **SLP 4438 T**
Make & Model : **HONDA VEZEL**
Chassis No : **RU31245254**

Submit By : **SERENCE**
Year Manufacture : **5-Jun-17**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding upper <i>Me</i>	1	\$35.50		—
2	Rear windscreen moulding lower <i>Me</i>	1	\$155.00		—
3	Rear windscreen moulding LH <i>Me</i>	1	\$45.00		—
4	Rear windscreen moulding RH <i>Me</i>	1	\$45.00		✓
5	Rear windscreen sealant <i>Nec</i>	1	\$50.00	S.N	<i>401m</i>
6	Rear bumper <i>762.70</i> <i>Me</i>	1	\$777.90		—
7	Rear bumper clip <i>X NN</i> <i>Me</i>	10	\$35.00		X
8	Rear bumper side retainer LH <i>Me</i>	1	\$27.50		X
9	Rear bumper LH <i>Me</i>	1	\$195.00		X
10	Rear bumper reflector LH <i>Me</i>	1	\$161.00		X
11	Tail door <i>953</i> <i>Me</i>	1	\$1,250.00		✓
12	Tail door emblem <i>Me</i>	1	\$35.70		X
13	Wording "VEZEL" <i>Me</i>	1	\$58.00		—
14	Wording "HYBRID" <i>Me</i>	1	\$60.50		—
15	Tail door trim <i>Me</i>	1	\$195.00		X
16	Tail door trim clip <i>Me</i>	10	\$35.00		X
17	Tail lamp panel LH <i>Me</i>	1	\$155.00		X
18	Tail lamp LH <i>474.60</i> <i>Me</i>	1	\$484.60		✓
19	Boot weatherstrip <i>Me</i>	1	\$112.30		X
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Labour

Vehicle No. : **SLP 4438 T**
Make & Model : **HONDA VEZEL**

Submit By : **Carmen Lim**
Year of Manufacture : **42891**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, REAR BUMPER LH, TAIDOOOR)	\$800.00	400/-
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, REAR BUMPER LH, TAIDOOOR)	\$800.00	400/-
3	To check wiring	\$50.00	20/-
4	To remove & refit rear windscreen.	\$120.00	✓
5	To tuff coat.	\$100.00	30/-
6	To transfer boot mechanism to new boot	\$120.00	60/-
7	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	X
8	To remove & refit reverse sensor	\$120.00	50/-
9	To remove & refit reverse camera <i>nn</i>	\$120.00	X