



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

INV No. AC2107844

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV Date 16/11/2021
Reference CS/EQI21008721/Aqf3e2
Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. GBK 6177C

Insured Veh. SMY 9965X

Claim No. DM21HO01209-JG

Policy No.

Accident Date 19/08/2021

Inspection Date 20/08/2021

Description	Total
Survey Inspection	230.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	230.00
GST (7%)	16.10
Grand Total	246.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CS/EQI21008721/Aqf3e2 Date: 16/11/2021 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMY 9965X	Veh. Inspected	GBK 6177C	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM21HO01209-JG	Excess (\$)	0.00	
Assign From	JOEL GOH	Assign Date	19/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	SUZUKI EVERY	c.c	658	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	DA17V452193	Colour	SILVER	
Odometer	20669 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	145/80 R12	BRIDGESTONE	6 mm	
L/H Front Tyre	145/80 R12	BRIDGESTONE	6 mm	
R/H Rear Tyre	145/80 R12	BRIDGESTONE	6 mm	
L/H Rear Tyre	145/80 R12	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/08/2021	Inspection Date	20/08/2021	
Survey held at	UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBK 6177C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	90.70	90.70
1	REAR TAILGATE PANEL	DISTORTED	1,248.60	899.60
2	REAR TAILGATE HINGES	NOT NECESSARY	192.40	-
1	REAR TAILGATE LOCK ASSY	DAMAGED	215.30	215.30
1	REAR TAILGATE LOCK STRIKER	NOT NECESSARY	43.50	-
1	REAR TAILGATE PULLER GARNISH	NOT NECESSARY	28.30	-
1	REAR TAILGATE WEATHERSTRIP	CUT	293.40	293.40
1	REAR TAILGATE SUZUKI LOGO	NECESSARY	83.60	38.00
1	REAR TAILGATE (EVERY) EMBLEM	NECESSARY	74.50	35.00
1	REAR TAILGATE OUTER HANDLE	NOT NECESSARY	212.30	-
1	REAR TAILGATE INNER TRIM BOARD	DEFORMED	224.60	224.60
1	REAR BUMPER ASSY	DISTORTED	998.40	625.00
2	REAR BUMPER SIDE RETAINER	NECESSARY	124.60	124.60
2	REAR BUMPER BRACKET	DAMAGED	117.60	117.60
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	354.90	-
2	REAR BUMPER SIDE REFLECTOR	CRACKED	465.00	465.00
1	REAR FLOOR INNER PANEL	TO REPAIR SEE LABOUR	532.20	-
1	REAR FLOOR OUTER PANEL	DENTED	445.70	445.70
2	REAR PANEL AIR DUCT	O/S DEFORMED	269.20	134.60
2	REAR FENDER SIDE GARNISH	NOT NECESSARY	126.80	-
1	REAR EXHAUST PIPE	TO REPAIR SEE LABOUR	778.60	-
2	REAR EXHAUST RUBBER MOUNTING	NOT NECESSARY	58.80	-
1	REAR SPARE TYRE HOLDING ASSY	BENT	448.60	195.00
	LESS 10% DISCOUNT		-742.76	-
	LESS 15% DISCOUNT		-	-585.62
			6,684.84	3,318.48
	<u>SPECIAL NETT ITEMS</u>			
1	REAR 70KM/H STICKER (SN)	NECESSARY	15.00	15.00
1	REAR 5 PAX STICKER (SN)	NECESSARY	15.00	15.00

Report Ref No. CS/EQI21008721/Aqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR WINDSCREEN DAM RUBBER (SN)	NECESSARY	60.00	60.00
1	REAR NUMBER PLATE (SN)	BENT	50.00	50.00
			420.00	340.00
	LABOUR			
	TO SPRAY UNDERCOATING IN REPAIR.		180.00	60.00
	TO DISM / REFIX REAR WINDSCREEN GLASS.		180.00	120.00
	TO DISM / RENEW REAR REVERSE SENSOR.		80.00	50.00
	TO DISM / RENEW REAR EXHAUST PIPE AFTER REPAIR.		100.00	80.00
	TO DISM / REWIRE DAMAGED PORTION.		250.00	30.00
	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS. INCLUSIVE OF THE REPAIR OF REAR FLOOR INNER PANEL AND REAR EXHAUST PIPE.		1,400.00	1,000.00
	TO PUTTY AND RESPRAY DAMAGED PORTION.		1,000.00	900.00
			3,190.00	2,240.00
GRAND TOTAL			10,294.84	5,898.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,700.00

Report Ref No. CS/EQI21008721/Aqf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/08/2021 16:29 (SGT)
Date of Accident	19/08/2021 08:30 (SGT)
Exact Location of Accident	Joo Chiat Rd, Singapore
Additional Location Information	TWDS MARINE PARADE ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBK6177C
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	LAM BEE IMPORT & EXPORT COMPANY PTE LTD
Company Reg No	198306125C
Email Address	lambeepteltd@yahoo.com.sg
Mobile Phone No	(Phone) +65-91281700
Alternative Phone No	+65-91281700

VEHICLE PARTICULARS

Manufacturer	Suzuki
Model	Every
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	800

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5119179079
Cover Note Number	-

DRIVER

Name of Driver	EE YONG YEOW
NRIC No	S7101691I

Date Of Birth	08/01/1971
Occupation	Outdoor
Date Of Driving Pass	12/05/2004
Driving experience	17 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91281700
Alt. Phone Number	-
Email Address	ee_yongyeows@yaho.com
Address	32 SEA AVENUE
Address complement	-
Postcode	424253
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	OWNER
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS DRIVING ALONG JOO CHIAT ROAD TURNING TOWARDS MARINE PARADE ROAD STOPPING AT THE DOTTED LINE TO LOOK OUT FOR ONCOMING TRAFFIC. OUT OF SUDDEN, VEHICLE B (SMY9965X) DID NOT STOP AND HIT ONTO MY VAN (GBK6177C) REAR PORTION.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMY9965X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	CHUA SHI HUI
NRIC No	S8537932A

Contact Number

(Phone) +65-96990942

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

VEHICLE B

Vehicle No.	Vehicle Type	Vehicle Make	Vehicle Model	Vehicle Year	Vehicle Color	Vehicle Description
1	1	1	1	1	1	1
2	2	2	2	2	2	2
3	3	3	3	3	3	3
4	4	4	4	4	4	4
5	5	5	5	5	5	5
6	6	6	6	6	6	6
7	7	7	7	7	7	7
8	8	8	8	8	8	8
9	9	9	9	9	9	9
10	10	10	10	10	10	10
11	11	11	11	11	11	11
12	12	12	12	12	12	12
13	13	13	13	13	13	13
14	14	14	14	14	14	14
15	15	15	15	15	15	15
16	16	16	16	16	16	16
17	17	17	17	17	17	17
18	18	18	18	18	18	18
19	19	19	19	19	19	19
20	20	20	20	20	20	20
21	21	21	21	21	21	21
22	22	22	22	22	22	22
23	23	23	23	23	23	23
24	24	24	24	24	24	24
25	25	25	25	25	25	25
26	26	26	26	26	26	26
27	27	27	27	27	27	27
28	28	28	28	28	28	28
29	29	29	29	29	29	29
30	30	30	30	30	30	30
31	31	31	31	31	31	31
32	32	32	32	32	32	32
33	33	33	33	33	33	33
34	34	34	34	34	34	34
35	35	35	35	35	35	35
36	36	36	36	36	36	36
37	37	37	37	37	37	37
38	38	38	38	38	38	38
39	39	39	39	39	39	39
40	40	40	40	40	40	40
41	41	41	41	41	41	41
42	42	42	42	42	42	42
43	43	43	43	43	43	43
44	44	44	44	44	44	44
45	45	45	45	45	45	45
46	46	46	46	46	46	46
47	47	47	47	47	47	47
48	48	48	48	48	48	48
49	49	49	49	49	49	49
50	50	50	50	50	50	50
51	51	51	51	51	51	51
52	52	52	52	52	52	52
53	53	53	53	53	53	53
54	54	54	54	54	54	54
55	55	55	55	55	55	55
56	56	56	56	56	56	56
57	57	57	57	57	57	57
58	58	58	58	58	58	58
59	59	59	59	59	59	59
60	60	60	60	60	60	60
61	61	61	61	61	61	61
62	62	62	62	62	62	62
63	63	63	63	63	63	63
64	64	64	64	64	64	64
65	65	65	65	65	65	65
66	66	66	66	66	66	66
67	67	67	67	67	67	67
68	68	68	68	68	68	68
69	69	69	69	69	69	69
70	70	70	70	70	70	70
71	71	71	71	71	71	71
72	72	72	72	72	72	72
73	73	73	73	73	73	73
74	74	74	74	74	74	74
75	75	75	75	75	75	75
76	76	76	76	76	76	76
77	77	77	77	77	77	77
78	78	78	78	78	78	78
79	79	79	79	79	79	79
80	80	80	80	80	80	80
81	81	81	81	81	81	81
82	82	82	82	82	82	82
83	83	83	83	83	83	83
84	84	84	84	84	84	84
85	85	85	85	85	85	85
86	86	86	86	86	86	86
87	87	87	87	87	87	87
88	88	88	88	88	88	88
89	89	89	89	89	89	89
90	90	90	90	90	90	90
91	91	91	91	91	91	91
92	92	92	92	92	92	92
93	93	93	93	93	93	93
94	94	94	94	94	94	94
95	95	95	95	95	95	95
96	96	96	96	96	96	96
97	97	97	97	97	97	97
98	98	98	98	98	98	98
99	99	99	99	99	99	99
100	100	100	100	100	100	100


Describe Circumstances of the Accident

I WAS DRIVING WITH THE CHINESE BUS TURNING RIGHT
 WITHOUT SIGNAL. WHEN STOPPED AT THE RED LIGHT LINE TO GO OUT
 OF THE LANE. TRAFFIC - ONE OF THE BUS WAS (B) STOPPED & DID
 NOT STOP AND HIT INTO MY LANE AND HIT THE REAR OF THE BUS.

Declaration

We declare the foregoing particulars are true in every respect.


 Lam Bee Imp & Exp Co. Pte Ltd
 9th 3017 Ubi Rd 1 #02-127, Singapore 408700
 Tel: 65418827 & 65418827
 Fax: 67426533
 Business Reg. No. 198306120C


 Lam Bee Imp & Exp Co. Pte Ltd
 9th 3017 Ubi Rd 1 #02-127, Singapore 408700
 Tel: 65418827 & 65418827
 Fax: 67426533
 Business Reg. No. 198306120C

Witnessed by: [Signature]
 Date: [Blank]
 Place: [Blank]

Witnessed by: [Signature]
 Date: [Blank]
 Place: [Blank]

Witnessed by: [Signature]
 Date: [Blank]
 Place: [Blank]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 6177C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 6177C

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBK 6177C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

