

RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -20%	
SN	
Labour	
Total	
Lump Sum	
ERV	

TO: LONGPAC

Vehicle No : SKP 1245 P

Make & Model : HONDA CROSSROAD

DATE: 18/8/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	TAILGATE 1247	1	\$ 1,458.00	\$ 1,458.00 1,458.00
2	TAILGATE WINDSCREEN MOULDING	1	\$ 198.00	\$ 198.00 198.00
3	TAILGATE WINDSCREEN INNER SEAL	1	\$ 50.00	\$ 50.00 50.00
4	TAILGATE WIPER MOTOR 391.50	1	\$ 455.60	\$ 455.60 455.60
5	TAILGATE WIPER ARM	1	\$ 89.00	\$ 89.00 89.00
6	TAILGATE WIPER ARM COVER	1	\$ 34.00	\$ 34.00 34.00
7	TAILGATE WIPER BLADE	1	\$ 110.00	\$ 110.00 110.00
8	TAILGATE BADGE	1	\$ 78.00	\$ 78.00 78.00
9	TAILGATE EMBLEM(CROSSROAD)	1	\$ 97.20	\$ 97.20 97.20
10	TAILGATE OUTER GARNISH 535	1	\$ 675.00	\$ 675.00 675.00
11	TAILGATE NUMBER PLATE LAMP	2	\$ 89.00	\$ 178.00 178.00
12	TAILGATE OPENER SWICTH	1	\$ 217.90	\$ 217.90 217.90
13	TAILGATE STOPPER	2	\$ 25.00	\$ 50.00 50.00
14	TAILGATE INNER TRIM 285	1	\$ 322.00	\$ 322.00 322.00
15	TAILGATE POCKER HANDLE	1	\$ 98.60	\$ 98.60 98.60
16	TAILGATE INNER LOCK 225	1	\$ 298.50	\$ 298.50 298.50
17	TAILGATE LOCK CATCH	1	\$ 46.00	\$ 46.00 46.00
18	TAILGATE WEATHERSTRIP	1	\$ 211.00	\$ 211.00 211.00
19	TAIL LAMP @450 each 400	2	\$ 589.00	\$ 1,178.00 1,178.00
20	REAR BUMPER	1	\$ 688.00	\$ 688.00 688.00
21	REAR BUMPER SIDE RETAINER	2	\$ 120.00	\$ 240.00 240.00
22	REAR BUMPER ATTACHMENT RETAINER	2	\$ 112.00	\$ 224.00 224.00
23	REAR BUMPER SIDE GARNISH @190 each 380	2	\$ 255.50	\$ 511.00 511.00
24	REAR BUMPER TOW COVER	1	\$ 125.00	\$ 125.00 125.00
25	REAR BUMPER REFLECTOR @96.26 each 192.52	2	\$ 177.90	\$ 355.80 355.80
26	REAR BUMPER LOWER BRACKET	1	\$ 122.00	\$ 122.00 122.00

27	REAR BUMPER LOWER SIDE BRACKET	2	\$	137.40	\$ 274.80
28	END PANEL	1	\$	685.00	\$ 685.00
29	END PANEL TOP TRIM TOOL BOX	1	\$	512.00	\$ 512.00
30	REAR FLOOR PANEL	1	\$	890.00	\$ 890.00
31	REAR FLOOR PANEL TOP BOARD	1	\$	376.50	\$ 376.50
32	REAR FENDER INNER TRIM	2	\$	490.658.00	\$ 1,316.00
33	REAR FENDER INNER SHIELD	2	\$	198.70	\$ 397.40
34	REAR FENDER ARCH GARNISH	2	\$	358.00	\$ 716.00
35	REAR EXHAUST SILENSER	1	\$	845.00	\$ 845.00
36	REAR EXHAUST MOUNTING	2	\$	50.00	\$ 100.00
37	REAR EXHAUST GASKET	1	\$	45.00	\$ 45.00
38	REAR EXHAUST HEAT PLATE	1	\$	198.00	\$ 198.00
				8537.32	Subtotal :
				6829.85	Less 20% :
					Parts Total : \$ 11,573.04

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	REAR WINDSCREEN SEALANT ✓ nec	1	\$ 80.00	\$ 80.00
2	REAR WINDSCREEN INNER SEAL ✓ nec	1	\$ 60.00	\$ 60.00
3	TAILGATE INNER TRIM CLIP ✓ nec	1	\$ 40.00	\$ 40.00
4	REAR BUMPER CLIP ✓ nec	1	\$ 50.00	\$ 50.00
5	END PANEL SEALANT ✓ nec	1	\$ 80.00	\$ 80.00
6	END PANEL TOP TRIM CLIP ✓ nec	1	\$ 30.00	\$ 30.00
7	REAR FLOOR PANEL SEALANT	1	\$ 80.00	\$ 80.00
8	REAR FENDER INNER TRIM CLIP ✓ nec	1	\$ 50.00	\$ 50.00
9	REAR FENDER INNER SHIELD CLIP ✓ nec	1	\$ 40.00	\$ 40.00
10	REAR FENDER ARCH GARNISH CLIP	1	\$ 40.00	\$ 40.00
11	REVERSE SENSOR(4 EYE)	1	\$ 550.00	\$ 550.00
12	REVERSE CAMERA	1	\$ 650.00	\$ 650.00
				410
				\$ 1,750.00

LABOUR (REAR)		PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	700	\$ 1,600.00
TO SPRAY PAINT AFFECTED AREA	800	\$ 1,500.00
TO PERFORM LIGHTING & WIRING CHECK	30	\$ 150.00
TO APPLY ANTI-RUST & TUFF KOTE	30	\$ 150.00
REMOVE AND INSTALL REAR WINDSCREEN	120.	\$ 150.00
REMOVE AND INSTALL TAIL GATE MECHANISIM AND PART	60.	\$ 150.00
REMOVE INSTALL AND CHECK REVERSE CAMARA	30	\$ 200.00
REMOVE INSTALL AND CHECK REVERSE SENSOR	30	\$ 200.00

REMOVE AND INSTALL CARPET, TRIM AND INTERIOR	60	\$	400.00
REMOVE AND INSTALL REAR EXHAUST	X m	\$	150.00
	1860		
LABOUR TOTAL		\$	4,650.00
	Total Parts Cost	\$	13,323.04
	Total Labour Cost	\$	4,650.00
	Total Repair Cost	\$	17,973.04

APPROVED DETAILS

NO. OF WORKING DAYS
 PART BY PART OR LUMP SUM
 DATE & TIME OF SURVEY
 SURVEYED BY
 CONTACT NUMBER
 FAX NUMBER

Tanfir 97495749
 WP 20/8/21 R 1515
 To check part prices
 1/5 Resurvey after repair
 Tanfir e/khauto.a.n.
 6 days.

6829.85

410

1860

9099.85

1347300

06 days
 #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: