

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 8823E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	560.00	-
1	FRONT FENDER RH SIGNAL LAMP	CUT	120.00	120.00
1	FRONT FENDER RH LINER	NOT NECESSARY	155.00	-
1	FRONT BUMPER	DISTORTED	750.00	585.00
1	FRONT BUMPER CLIPS (SET)	NECESSARY	50.00	30.00
2	FRONT BUMPER RETAINERS LH & RH @\$45.00	O/S CRACKED	90.00	45.00
1	FRONT BUMPER RH FOG LAMP	NOT NECESSARY	350.00	-
1	FRONT BUMPER RH FOG LAMP GARNISH	CUT	75.00	75.00
1	FRONT BUMPER CENTER GRILLE BASE	NOT NECESSARY	240.00	-
1	FRONT BUMPER CENTER GRILLE CHROME	NOT NECESSARY	260.00	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	180.00	-
1	FRONT BUMPER REINFORCEMENT BAR	NOT NECESSARY	460.00	-
1	FRONT BUMPER UPPER BEAM	NOT NECESSARY	380.00	-
1	FRONT BUMPER MIDDLE BEAM	NOT NECESSARY	120.00	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	830.00	-
1	HEADLAMP RH	CRACKED	1,450.00	1,299.00
1	HEADLAMP RH CHROME	NOT NECESSARY	165.00	-
1	HEADLAMP LOWER BRACKET RH	CRACKED	55.00	55.00
1	WIPER TANK	DEFORMED	80.00	80.00
1	WIPER TANK MOTOR	NOT NECESSARY	110.00	-
	LESS 20% DISCOUNT		-1,296.00	-457.80
			5,184.00	1,831.20
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		800.00	300.00
	SPRAY PAINTING.		800.00	400.00
	RESET HEAD LAMP FOCUS ELECTRONICALLY.		200.00	30.00
	REMOVE & REFIT FRONT BUMPER ATTACHMENTS.	NOT NECESSARY	100.00	-

Report Ref No. CS/AGI21008733/Atf3n2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

2,561.20

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	ANTI RUST COATING.	NOT NECESSARY	150.00	-
			2,050.00	730.00
	GRAND TOTAL		7,234.00	2,561.20

Report Ref No. CS/AGI21008733/Atf3n2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.