

RICO60

AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -20%	
SN	
Labour	
Total	
Lump Sum	
ERV	

TO: FRIST CAPITAL

Vehicle No : SKW 7093 J

Make & Model : HONDA VEZEL

DATE: 19/8/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	TAILGATE 953	1	\$ 1,050.00	\$ bt 1,050.00
2	TAILGATE WINDSCREEN MOULDING 145	1	\$ 198.00	\$ net 198.00
3	TAILGATE WINDSCREEN INNER SEAL	1	\$ 50.00	\$ net 50.00
4	TAILGATE BADGE	1	\$ 60.50	\$ net 60.50
5	TAILGATE EMBLEM(VEZEL)	1	\$ 89.00	\$ net 89.00
6	TAILGATE OUTER GARNISH 225.90	1	\$ 547.40	\$ net X 547.40 Xnn
7	TAILGATE NUMBER PLATE LAMP	2	\$ 89.00	\$ Xnn 178.00
8	TAILGATE OPENER SWICTH	1	\$ 217.90	\$ Xnn 217.90
9	TAILGATE LAMP @ 321 each 642	2	\$ 376.90	\$ net 753.80
10	TAILGATE STOPPER	2	\$ 25.00	\$ Xnn 50.00
11	TAILGATE INNER TRIM 285	1	\$ 477.60	\$ net 477.60
12	TAILGATE POCKER HANDLE	1	\$ 98.60	\$ Xnn 98.60
13	TAILGATE INNER LOCK 174.90	1	\$ 665.00	\$ bt 665.00
14	TAILGATE LOCK CATCH	1	\$ 46.00	\$ Xnn 46.00
15	TAILGATE WEATHERSTRIP 189	1	\$ 298.40	\$ net 298.40
16	TAILGATE LOCK DETECTOR	1	\$ 317.90	\$ net X 317.90
17	TAILGATE HINGE	2	\$ 109.00	\$ Xnn 218.00
18	TAILGATE DAMPER	2	\$ 278.90	\$ Xnn 557.80
19	TAIL LAMP @ 421 each 842	2	\$ 582.40	\$ net X 1,164.80 Xnn
20	TAIL LAMP PANEL	2	\$ 97.50	\$ Xnn 195.00
21	REAR BUMPER 508	1	\$ 598.50	\$ net 598.50
22	REAR BUMPER SIDE RETAINER 90	2	\$ 45 120.00	\$ net 240.00
23	REAR BUMPER SIDE GARNISH @ 195 each 390.	2	\$ 255.50	\$ net 511.00
24	REAR BUMPER REFLECTOR 240	2	\$ 120 177.90	\$ net 355.80
25	REAR BUMPER UNDER COVER 196 259	1	\$ 358.20	\$ net 358.20
26	END PANEL 415.60.	1	\$ 511.90	\$ bt 511.90

O PERFORM LIGHTING & WIRING CHECK	\$ 30 150.00
TO APPLY ANTI-RUST & TUFF KOTE	\$ 30 150.00
REMOVE AND INSTALL REAR WINDSCREEN	\$ 120 150.00
REMOVE AND INSTALL TAIL GATE MECHANISIM AND PART	\$ 60 150.00
REMOVE AND INSTALL REAR BOTH DOOR PARTS	\$ X ^m 300.00
REMOVE INSTALL AND CHECK REVERSE CAMARA	\$ 30 200.00
REMOVE INSTALL AND CHECK REVERSE SENSOR	\$ 30 200.00
REMOVE AND INSTALL CARPET, TRIM AND INTERRIOR	\$ 60 400.00
REMOVE AND INSTALL REAR EXHAUST	\$ X ^m 150.00
TO CHECK AND RESET SYSTEM FAULT AND FUCTION	\$ X ^m 600.00
TO JACK AND REALIGHT REAR CHASSIS FRAME MEMBER	\$ 200 X ^m 600.00
	1860
LABOUR TOTAL	\$ 6,450.00

	Total Parts Cost	\$ 15,842.64
	Total Labour Cost	\$ 6,450.00
	Total Repair Cost	\$ 22,292.64

APPROVED DETAILS

NO. OF WORKING DAYS
 PART BY PART OR LUMP SUM
 DATE & TIME OF SURVEY
 SURVEYED BY
 CONTACT NUMBER
 FAX NUMBER

Tamplin 97415749
 WP' 20/8/21 R 345pm
 To check of report on consistency
 1/5 Resurvey after repair
 To check part price
 tamplin e/kkauton m
 7 days

4418.96
 430
 1860

6708.96

4585350

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: