



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3356D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	CRACKED	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	DEFORMED	451.25	451.25
1	REAR BUMPER BRACKET RH	NOT NECESSARY	55.80	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
1	REAR BUMPER REINFORCEMENT BRACKET RH	NOT NECESSARY	138.10	-
1	REAR BUMPER LOWER CTR MOULDING	CUT	155.00	155.00
1	REAR BUMPER REFLECTOR LAMP RH	NOT NECESSARY	41.45	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	98.80	-
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
1	LICENCE LAMP	NOT NECESSARY	85.30	-
1	BOOTLID	TO REPAIR SEE LABOUR	2,480.40	-
1	BOOTLID HYUNDAI PLATE	NECESSARY	24.30	24.30
1	EMBLEM HYBRID	NECESSARY	24.30	24.30
1	EMBLEM-IONIQ	NECESSARY	31.30	31.30
1	REAR PANEL	NOT NECESSARY	532.00	-
1	REAR PANEL GARNISH	NOT NECESSARY	346.80	-
	LESS 20% DISCOUNT		-1,108.50	-233.51
			4,434.00	934.04
<u>NETT ITEMS</u>				
1	BOOTLID COMFORT TEL NO STICKER (N)	NECESSARY	35.00	35.00
1	BOOTLID COMFORT LOGO STICKER (N)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-	-24.50
			245.00	220.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE WITH TRIM COVER (SN)	NOT NECESSARY	55.00	-
1	BOOTLID COMFORT APP STICKER (SN)	NECESSARY	30.00	30.00

Report Ref No. NS/INC21008739/T1qcn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID ADVERTISEMENT LOGO (SN)	CUT	100.00	100.00
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
			235.00	180.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BOOTLID.		800.00	525.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			1,530.00	1,055.00
GRAND TOTAL			6,444.00	2,389.54
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,900.00

Report Ref No. NS/INC21008739/T1qcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.