

ASS. REC. BY:

Tang JH

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Mrs Loh

Veh No: SHA 3356DYr Regn: 2019, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai

c.c

1580Colour Blue

A/C: Insured / Std / NI / NA

Sp. Reading 343266

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCS51CVK414678

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 18/8/21 05:20Survey held at Comfort Garage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format: _____

Lump Sum / L&L: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. _____

Photos _____

Others _____

TOTAL

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA3356D

Make : HYUNDAI

Model : IONIQ(G2)

Date: 18/08/2021

Insurance: NTUC

MVA: MS. LOKE YY

LIS

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER BRACKET RH			\$55.80
1	REAR BUMPER REINFORCEMENT			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET RH			\$138.10
1	REAR BUMPER LOWER CTR MOULDING			\$155.00
1	REAR BUMPER REFLECTOR LAMP RH			\$41.45
1	REAR BUMPER TOWING COVER			\$98.80
1	REAR BUMPER FOG LAMP			\$201.50
1	LICENCE LAMP			\$85.30
1	BOOTLID			\$2,480.40
1	BOOTLID HYUNDAI PLATE			\$24.30
1	EMBLEM HYBRID			\$24.30
1	EMBLEM - IONIQ			\$31.30
1	REAR PANEL			\$532.00
1	REAR PANEL GARNISH			\$346.80
	SUB TOTAL			\$4,663.70
	LESS 20%			\$932.74
	DISCOUNTED TOTAL			\$3,730.96
1	REAR NUMBER PLATE WITH TRIM COVER			\$55.00
1	BOOTLID COMFORT TEL NO STICKER			\$35.00
1	BOOTLID COMFORT LOGO STICKER			\$30.00
1	BOOTLID COMFORT APP STICKER			\$30.00
1	BOOTLID ADVERTISEMENT LOGO			\$100.00
1	REAR BUMPER ADVERTISEMENT LOGO			\$50.00
1	REAR BUMPER REVERSE SENSOR			\$180.00
	Labour Charge			
	PANEL BEATING			\$800.00
	SPRAY PAINTING CHARGE			\$600.00
	WIRING CHARGE			\$50.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
	TOTAL LABOUR			\$1,530.00
	ESTIMATE TOTAL			\$5,685.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.