

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO : AXA DATE : 19/08/2021
ATTENTION : MOTOR CLAIMS DEPT JOB TYPE : T/P CLAIM
ESTIMATE REPORT :

VEHICLE DETAILS

VEHICLE NO : SGE3636L
MODEL : TOYOTA COROLLA ALTIS 1.6
CHASSIS NO

MR053REH104541001

Xiao Tong

ACCIDENT DETAILS DATE : 19-Aug-21
TIME : 09:35HRS

THIRD PARTY REQUESTOR / CONTACT : JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Dented</i>	1	\$ 830.00	\$ 830.00
2	BOOTLID LOGO	1	\$ 68.60	\$ 68.60
3	BOOTLID EMBLEM 'COROLLA'	1	\$ 55.10	\$ 55.10
4	BOOTLID EMBLEM 'ALTIS'	1	\$ 55.40	\$ 55.40
5	BOOTLID HINGE <i>new</i>	2	\$ 120.00	\$ 240.00
6	BOOTLID LOCK <i>Damaged</i>	1	\$ 320.00	\$ 320.00
7	BOOTLID LAMP <i>new</i>	2	\$ 345.00	\$ 690.00
8	BOOTLID WEATHERSTRIP <i>new</i>	1	\$ 175.10	\$ 175.10
9	REAR BUMPER <i>Dented</i>	1	\$ 580.00	\$ 580.00
10	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 101.00	\$ 202.00
11	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 460.00	\$ 460.00
12	REAR BUMPER ALTERNATIVE <i>new</i>	1	\$ 180.00	\$ 180.00
13	TAILLAMP <i>LH covered</i>	2	\$ 480.00	\$ 960.00
14	TAILLAMP PANEL <i>new</i>	2	\$ 388.20	\$ 776.40
15	TAILLAMP LOWER BRACKET <i>new</i>	2	\$ 58.00	\$ 116.00
16	REAR END PANEL <i>Dented</i>	1	\$ 820.00	\$ 820.00
17	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 350.00	\$ 350.00

85
398
784
590
225

4/6620

3124.65

TOTAL PRICE \$ 6,878.60

LESS 25% \$ 1,719.65

SUB TOTAL PRICE \$ 5,158.95

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
3	REAR TAILLAMP CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
4	REAR END PANEL SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
5	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
6	REVERSE SENSOR <i>changed.</i>	1	\$ 220.00	\$ 220.00

TOTAL \$ 410.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL AND SPARE TYRE PANEL	\$ 1,000.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	800	
3	WIRING	\$ 100.00	30	
4	TUFF COAT	\$ 180.00	60	
5	TO CONDUCT WATER LEAKAGE TEST	\$ 250.00	x	
6	TO REMOVE AND REFIX BOOTLID MECHANISM	\$ 120.00	60	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	

TOTAL \$2,730.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,568.95

TOTAL LABOUR COST : \$ 2,730.00

TOTAL REPAIR COST : \$ 8,298.95

Adrian
 L/S 20/08/21.
 06 days.

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM
NO OF DAYS :LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

FAX :

total: 5224.65
 L/S: 4 IK.

1800

300