

SLX2282X 2018 March.

Kia Cerato K3 1591 cc

TP111

Asher.

KNAFX411MJ5761966

Front Number Plate	30(SN) ✓
Front Number Plate Holder	30(SN) ✓
Front Number Plate Garnish	48.10. ✓
Front Bumper	697.90 ✓
Front Bumper clips	30(SN) ✓
Front Bumper Side Holder x 02	39.1 x 2 = 78.20 ✓
Front Bumper Reinforcement	496 ✓
Front Bumper Sponge	143.20 ✓
Front Bumper Logo	185.70 ✓
Front Bumper Lower Grille	283.2 x 2 = 566.40 ✓
Front Bumper Fog Lamp x 02	91 x 2 = 182 ✓
Front Bumper Side Air Grille x 02	385.50 ✓
Front Grille	20(SN) ✓
Front Grille Chrome Mounting	
Front Grille Clips	

SLX2282X

~~Front Grille Top Apron Cover~~
~~Front Grille Top Apron Cover Logo~~
~~Front Grille Top Apron Cover Clips~~

Headlamp x 02 ^{could}
Dishled

1870 x 2 = 3740 ✓

Front Support Panel.

745.60 ✓

Front Support Panel Top Cover ^{could}

88.60 ✓

Front Support Panel Top Cover Clips. ^{per}

20(SN) ✓

Bonnet ^{Dented}

895.80 ✓

Bonnet Lock ^{Damaged}

86.80 ✓

Bonnet Weatherstripe ^{NP}
_{per}

78.60 +

Bonnet Hinge x 02 ^{Best}

55.5 x 2 = 111 ✓

Bonnet Insulator ^{NP}
_{per}

154.80 +

Bonnet Insulator Clips ^{NP}
_{per}

30(SN) +

Air Con Condenser ^{Dented}

892.10 ✓

SLX 2282 X

Air Con Condenser Side Guide x02 ^{Cracked} 40.8 x 2 = 81.60 ✓

Air Con Condenser Side Guide Clips ^{MC} 20 (SN) ✓

Air Con Liquid Pipe } 187.40 X

Air Con Suction Pipe } AP 210.50 X

Air Con Discharge Pipe. } M 224.90 X

Radiator Dented 692.90 ✓

Radiator Fan Assy Dntd 598.20 ✓

~~Radiator Fan Blade~~

~~Radiator Fan Motor~~

Radiator Spare Tank Leaking 84.10 ✓

Radiator Coolant. MC 40 (SN) ✓

Front Fender x02 Repair 435 X 2 = 870 X.

SLX 2282X.

Rees Number Plate	Dist'd	30(SN) ✓
Rees Number Plate Holder		30(SN) ✓
Rees Number Plate Lap x 02	ny	33.4 x 2 = 66.80 ✓
Rees Bumper	Dist'd	688.90 ✓
Rees Bumper Clips	ny	30(SN) ✓
Rees Bumper Side Holder x 02	ny	38.2 x 2 = 76.40 ✓
Rees Bumper Lower Garnish	Dist'd	367.50 ✓
Rees Bumper Lower Garnish Reflector x 02	Missing	33.1 x 2 = 66.20 ✓
Rees Bumper Reinforcement	Dist'd	363.90 ✓
Rees Bumper Reinforcement Bracket x 05	Dist'd	28 x 5 = 140 ✓
Rees Bumper Reinforcement Stay x 02	Dist'd	89.7 x 2 = 179.40 ✓
Rees Bumper Undercover LH.	torn	68.90 ✓
Rees Bumper Undercover Clips	ny	10(SN) ✓
Reverse Sensor x 04	Missing	197.3 x 4 = 789.20 ✓
Reverse Sensor Wire Harness	Snapped	299.40 ✓
Rees Antenna Lock Sensor	Dist'd	185.30 ✓

SLX2282X

Rear End Panel	Distal	516.50	✓
Rear End Panel Top Cover	Rehd	129.40	✓
Rear End Panel Top Cover Clips.	in	20(SN)	✓
Rear End Panel Sealant.	in	60(SN)	✓
Trillayp x 02	Smashed	$854.9 \times 2 = 1709.80$	✓
Trillayp Panel x 02	Righted	$139.6 \times 2 = 279.20$	✓
Bootlid	Distorted	1297.90	✓
Bootlid Lock	Dead	169.70	✓
Bootlid Weatherstripe	at	168.40	✓
Bootlid Reflector x 02	at	$680.5 \times 2 = 1361$	✓
Bootlid Hinge x 02	Best	$86.2 \times 2 = 172.40$	✓
Bootlid Inner Trim Board	crupled	199.50	✓
Bootlid Inner Trim Board Clips	in	30(SN)	✓

SLX2282X

Kia Logo.

32.50 ✓

Centro Wording.

31.70 ✓

K3 Wording.

38.40 ✓

Cycle and Carriage Logo.

40(SN) ✓

Rear Fender x 02

Buckled

1191.5 x 2 = 2383 ✓

Rear Fender Inner Trim Board x 02

torn

322 x 2 = 644 ✓

Rear Fender Inner Trim Board Clips.

in

60(SN)

Rear Fender Air Vent x 02

Missing

85 x 2 = 170 ✓

Rear Fender Inner Shield x 02

torn

1256 x 2 = 2512 ✓

Rear Fender Inner Shield Clips.

in

40(SN) ✓

Rear Fender Inner Wheel House x 02

Buckled

685 x 2 = 1370 ✓

Rear Windscreen Moulding

145 ✓

Rear Windscreen Sealant.

60(SN) ✓

Spere Tyre Panel

Distorted

795.40 ✓

Spere Tyre Panel Top Board

Del'd

254.60 ✓

Spere Tyre Panel Lock Screw

and

35.20 ✓

Spere Tyre Panel Insulation Pad

in

280(SN) ✓

200(SN)

SLX 2282 X

Spare Tyre

2
14
m

150(SN) X

Spare Tyre Rim.

180(SN). X

Rear Door x 02 ^{Py}

1361 x 2 = 2722 X

Rear Door Lock x 02 ^{AP}

253 x 2 = 506 X

Rear Exhaust Pipe Bent

757.80 ✓

Rear Exhaust Mounting. x2 ^{torn}

38.2 x 2 = 76.40 ✓

Rear Exhaust Heat Shield. ^{Applied}

141.30 ✓

Centre Exhaust Pipe. Bent.

~~1431.80~~ 1123.20

Rear Axle Bent.

1096

Rear Shock Absorber x 02 Bent

281 x 2 = 562 ✓

Rear Wheel Hub c/w Bearing x 02 ^{Dmgd}

297.4 x 2 = 594.80 ✓

Rear Camera. ^{Dmgd}

690.90 ✓

Rear LH Chassis Member ^{Distorted}

983 -

SLX 2282X

Panel Beating (Front)

~~1400~~ 800

Spray Painting (Front)

~~1200~~ 800

Wiring (Front)

~~100~~ 30

To remove condenser and to }
top up air con gas ↓

~~150~~ 60

To remove radiator and to }
top up coolant ↓

~~150~~ 60

To spray tuff coat (Front)

~~120~~ 50

Panel Beating (Rear)

~~3500.~~ 2800

Spray Painting (Rear)

~~2400~~ 1800

Wiring (Rear)

~~100~~ 30

To spray tuff coat (Rear)

~~250~~ 200

SLX2282X

To remove reverse sensor	100 50
To remove rear camera.	100 50
To remove upholstery and rear seat	350 200
To remove rear windscreen.	180 120
To transfer bootlid fittings.	180 80
To remove rear and centre exhaust pipes.	300 80
To transfer rear LH and RH door fittings.	300 X
To remove rear undercarriage	380 250
To perform wheel alignment.	150 80
To remove fuel tank.	150 80
Towing Fees.	60 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

hist: 32023.20 Labour 7680
ten 10% 28820.88 total: 37300.88
S.N: 800 2/s: 29.8k
28 days

29.8k