

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0654/2021/ZK
DATE : 16-Aug-21
WIP : 39635

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/8/21

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MDM CHAN MEI LING ALISON
ADDRESS : 13 PAVILION VIEW
SINGAPORE 658427
TELEPHONE : HP +65 96302833
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700094795-03
VEHICLE NO : **SJH 3033 A**
MODEL CODE : Q2 1.0 TFSI S TRONIC
MODEL YEAR : 5/1/2018
ENGINE NO : CHZ 601132
CHASSIS NO : WAUZZZGA6JA043704
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Aug-21
PLACE OF ACCIDENT : OUTSIDE 13 PAVILION VIEW

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJH 3033 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	X.
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	280 X
3	TO REMOVE AND REINSTALL AIRCON CONDENSER , ADDITIONAL RADIATOR. RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,700.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,000.00	500
5	TO RESPRAY FRONT BUMPER	\$	1,200.00	550
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 7,972.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJH 3033 A

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Distorted</i>	2	\$ 1,042.00	✓	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 347.00	✓	
3	FRONT BUMPER GRILLE - CENTER ?	1	\$ 197.00	?	
4	FRONT BUMPER AIR GUIDE GRILLE - LH <i>could</i>	1	\$ 169.00	✓	
5	FRONT BUMPER AIR GUIDE END CAP - LH ?	1	\$ 59.00	?	
6	FRONT BUMPER SPOILER <i>could</i>	1	\$ 299.00	✓	
7	FRONT BUMPER CLOSING ELEMENT ?	1	\$ 156.00	?	
8	FRONT WHEEL SPOILER - LH ?	1	\$ 34.00	?	
9	FRONT BUMPER ADAPTER - LH ?	1	\$ 36.00	?	
10	FRONT RADIATOR GRILLE <i>cut</i>	1	\$ 1,411.00	✓	
11	FRONT BUMPER STRIKER PLATE ?	1	\$ 124.00	?	
12	FRONT FOAM FILLER PIECE ?	1	\$ 78.00	?	
13	FRONT BUMPER REINFORCEMENT ?	1	\$ 723.00	?	
14	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 36.00	✓	
15	FRONT BUMPER TOP COVER ?	1	\$ 100.00	✓	
16	CAUTION STICKER <i>new</i>	1	\$ 14.00	✓	
17	AIR CONDITIONER STICKER <i>new</i>	1	\$ 8.00	✓	
18	HORN - LH <i>new</i>	1	\$ 286.00	✓	
19	HORN BRACKET - LH <i>new</i>	1	\$ 31.00	✓	
20	FRONT HEADLIGHT MOUNTING <i>new</i>	1	\$ 118.00	✓	
SUB TOTAL SPARE PARTS		:	\$ 5,268.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJH 3033 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT HEADLIGHT - LH <i>not needed</i>	1	\$ 4,915.00	<i>X</i>
22	FRONT HEADLIGHT CYLINDER - LH <i>clean</i>	1	\$ 142.00	<i>+</i>
23	FRONT HEADLIGHT LIFT CYLINDER HOSE	1	\$ 182.00	<i>+</i>
24	FRONT LOCK CARRIER <i>clean</i>	1	\$ 994.00	<i>+</i>
25	COOLANT	6	\$ 142.00	<i>+</i>
26	FRONT BUMPER AIR GUIDE - LH <i>?</i>	1	\$ 31.00	<i>?</i>
27	FRONT BUMPER AIR GUIDE - CENTER <i>?</i>	1	\$ 22.00	<i>?</i>
28	FRONT WHEEL ARCH COVER - LH / RH <i>new</i>	2	\$ 644.00	<i>✓</i>
29	FRONT NO PLATE <i>dented</i>	S/N	\$ 60.00	<i>✓</i>
30	SUNDRIES		\$ 192.00	
TOTAL SPARE PARTS		:	\$ 12,592.00	
TOTAL LABOUR CHARGES		:	\$ 7,972.00	
GRAND TOTAL		:	\$ 20,564.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *19/08/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not Authorised, 03 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT