



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0663/2021/ZK
DATE : 17-Aug-21
WIP : 40164

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/8/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

7 days exclude 1 Sunday

Johnny Boo 27 Sep 21

OWNER'S NAME : DR PHUA NGEE BOON
ADDRESS : 51 MANDALAY ROAD
#07-03
SINGAPORE 308231
TELEPHONE : HP +65 97583427
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900080528-01
VEHICLE NO : **SMK 1877 T**
MODEL CODE : A3 SEDAN 1.0 TFSI
MODEL YEAR : 29/3/2019
ENGINE NO : CHZ C27186
CHASSIS NO : WAUZZZ8V3K1023705
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Aug-21
PLACE OF ACCIDENT : NORTH BUONA VISTA ROAD NEAR MRT STATION

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 1877 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY. <i>(Lock carrier replaced)</i>	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR,RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$	1,400.00	\$	1,400.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,200.00	\$	2,250.00
5	TO RESPRAY FRONT BUMPER , BONNET AND HINGES.	\$	2,500.00	\$	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	\$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 9,002.00	\$	5,552.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 1877 T

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,987.00	\$	1,589.60
2	FRONT BUMPER FIXING PARTS	1	\$ 187.00		
3	FRONT BUMPER GUIDE SECTION RH	1	\$ 39.00		
4	FRONT BUMPER GRILLE - CENTER	1	\$ 160.00		
5	FRONT BUMPER CLOSING ELEMENT - CENTER	1	\$ 536.00		
6	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 297.00		
7	FRONT BUMPER COVER TRIM - RH	1	\$ 163.00		
8	FRONT BUMPER ADAPTER - RH	1	\$ 38.00		
9	FRONT RADIATOR GRILLE	1	\$ 1,406.00	\$	1,124.80
10	FRONT RADIATOR GRILE CLOSING ELEMENT	1	\$ 191.00	\$	152.40
11	FRONT AIR GUIDE GRILLE - RH	1	\$ 188.00		
12	FRONT FOAM FILLER PIECE	1	\$ 189.00	\$	151.20
13	FRONT REINFORMENT BEAM COVER	1	\$ 122.00	\$	97.20
14	FRONT REINFORMENT BEAM	1	\$ 795.00	\$	636.00
15	HORN - RH	1	\$ 200.00		
16	FRONT BONNET	1	\$ 3,134.00	\$	2,507.20
17	FRONT BONNET ATTACHMENT PARTS	1	\$ 165.00		
18	FRONT BONNET HINGE - LH / RH	2	\$ 124.00		
19	FRONT BONNET CATCH HOOK	1	\$ 90.00		
20	FRONT BONNET STRIKER PLATE - RH	1	\$ 110.00		
SUB TOTAL SPARE PARTS			\$ 10,121.00	\$	6,258.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 1877 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 6,258.40
21	FRONT BONNET EDGE PROTECTION	1	\$ 28.00	\$ 22.00
22	FRONT BONNET LOCK WITH MICRO SWITCH - RH	1	\$ 214.00	
23	FRONT BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	
24	FRONT BONNET LOCK CABLE	1	\$ 74.00	
25	FRONT BONNET CATCH HOOK	1	\$ 63.00	
26	FRONT HEADLIGHT - RH	1	\$ 5,455.00	\$ 4,364.00
27	FRONT HEADLIGHT LIFT CYLINDER - RH	1	\$ 142.00	
28	FRONT HEADLIGHT LIFT CYLINDER HOSE	1	\$ 68.00	
29	FRONT LOCK CARRIER	1	\$ 727.00	\$ 581.60
30	COOLANT	6	\$ 266.00	\$ 212.64
31	AIR-CON CONDENSER	1	\$ 530.00	
32	CONDENSER BRACKET	1	\$ 19.00	\$ 14.56
33	FRONT RADIATOR AIR GUIDE - RH	1	\$ 25.00	\$ 19.44
34	FRONT AIR GUIDE - RH OUTER	1	\$ 8.00	
35	FRONT RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 12.00	
36	AIR CONDITIONER STICKER	1	\$ 8.00	\$ 5.68
37	CAUTION STICKER	1	\$ 14.00	\$ 10.88
38	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
39	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS		:	\$ 18,242.00	\$ 11,549.20
TOTAL LABOUR CHARGES		:	\$ 9,002.00	\$ 5,552.00
GRAND TOTAL		:	\$ 27,244.00	\$ 17,101.20

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-23/09/21



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT