



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0663/2021/ZK
DATE : 17-Aug-21
WIP : 40164

Xiao Chan,

\$17101.20

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/8/2021

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : DR PHUA NGEE BOON
ADDRESS : 51 MANDALAY ROAD
#07-03
SINGAPORE 308231
TELEPHONE : HP +65 97583427
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900080528-01
VEHICLE NO : SMK 1877 T
MODEL CODE : A3 SEDAN 1.0 TFSI
MODEL YEAR : 29/3/2019
ENGINE NO : CHZ C27186
CHASSIS NO : WAUZZZ8V3K1023705
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Aug-21
PLACE OF ACCIDENT : NORTH BUONA VISTA ROAD NEAR MRT STATION



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 1877 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X ✓ <i>lls</i>
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250 ✓
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR,RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,400.00	X ✓ <i>lls</i>
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	1000 2250 <i>lls</i>
5	TO RESPRAY FRONT BUMPER , BONNET AND HINGES.	\$ 2,500.00	1100 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK	\$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>9,002.00</u>	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 1877 T

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	1	\$ 1,987.00	✓ 1589.60
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 187.00	+
3	FRONT BUMPER GUIDE SECTION RH <i>new</i>	1	\$ 39.00	+
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 160.00	x
5	FRONT BUMPER CLOSING ELEMENT - CENTER <i>new</i>	1	\$ 536.00	x
6	FRONT BUMPER CLOSING ELEMENT - RH <i>new</i>	1	\$ 297.00	x
7	FRONT BUMPER COVER TRIM - RH <i>new</i>	1	\$ 163.00	+
8	FRONT BUMPER ADAPTER - RH <i>new</i>	1	\$ 38.00	+
9	FRONT RADIATOR GRILLE <i>crushed</i>	1	\$ 1,406.00	✓ 1124.80
10	FRONT RADIATOR GRILE CLOSING ELEMENT <i>crushed</i>	1	\$ 191.00	? 152.40 ✓
11	FRONT AIR GUIDE GRILLE - RH <i>new</i>	1	\$ 188.00	x
12	FRONT FOAM FILLER PIECE <i>Deformed</i>	1	\$ 189.00	? 151.20 ✓
13	FRONT REINFORMENT BEAM COVER <i>form</i>	1	\$ 122.00	? 97.20 ✓
14	FRONT REINFORMENT BEAM <i>Bent.</i>	1	\$ 795.00	? 636.00 ✓
15	HORN - RH <i>new</i>	1	\$ 200.00	x
16	FRONT BONNET <i>Dented</i>	1	\$ 3,134.00	✓ 2507.20
17	FRONT BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 165.00	+
18	FRONT BONNET HINGE - LH / RH <i>new</i>	2	\$ 124.00	+
19	FRONT BONNET CATCH HOOK <i>new</i>	1	\$ 90.00	+
20	FRONT BONNET STRIKER PLATE - RH <i>new</i>	1	\$ 110.00	+
SUB TOTAL SPARE PARTS		:	\$ 10,121.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 1877 T

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
21	FRONT BONNET EDGE PROTECTION <i>cracked</i>	1	S	28.00	✓	22.00
22	FRONT BONNET LOCK WITH MICRO SWITCH - RH <i>new</i>	1	S	214.00	+	
23	FRONT BONNET BOWDEN CABLE - CENTER <i>new</i>	1	S	58.00	+	
24	FRONT BONNET LOCK CABLE <i>new</i>	1	S	74.00	+	
25	FRONT BONNET CATCH HOOK <i>new</i>	1	S	63.00	+	
26	FRONT HEADLIGHT - RH <i>cracked</i>	1	S	5,455.00	✓	4364.00
27	FRONT HEADLIGHT LIFT CYLINDER - RH <i>new</i>	1	S	142.00	+	
28	FRONT HEADLIGHT LIFT CYLINDER HOSE <i>new</i>	1	S	68.00	+	
29	FRONT LOCK CARRIER <i>cracked.</i>	1	S	727.00	+	581.60 ✓
30	COOLANT <i>Nec</i>	6	S	266.00	+	212.64 ✓
31	AIR-CON CONDENSER <i>new</i>	1	S	530.00	+	
32	Temperature Sensor Bracket <i>cracked.</i>	1	S	19.00	+	14.56 ✓
33	FRONT RADIATOR AIR GUIDE - RH <i>torn</i>	1	S	25.00	+	19.44 ✓
34	FRONT AIR GUIDE - RH OUTER <i>Abse Nec</i>	1	S	8.00	+	
35	FRONT RADIATOR AIR GUIDE - UPPER CENTER <i>new</i>	1	S	12.00	+	
36	AIR CONDITIONER STICKER <i>new</i>	1	S	8.00	✓	5.68
37	CAUTION STICKER <i>new</i>	1	S	14.00	✓	10.88
38	FRONT NO PLATE <i>Deleted</i>	S/N	S	60.00	✓	✓
39	SUNDRIES <i>Not Noc.</i>		S	350.00	?	✗
TOTAL SPARE PARTS		:	\$	18,242.00		
TOTAL LABOUR CHARGES		:	\$	9,002.00		
GRAND TOTAL		:	\$	27,244.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Advan King
SURVEYED DATE : 19/08/11
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, ~~04 Days~~ 07 Days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT. *ll.s.*

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT