

Car-in

6/9/21

wip: 40164

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Kiam/
Xiao Chan



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 1877 T

ALG-Adrian
- 4 days

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	1	\$ 1,987.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 187.00	✗
3	FRONT BUMPER GUIDE SECTION RH <i>new</i>	1	\$ 39.00	✗
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 160.00	✗
5	FRONT BUMPER CLOSING ELEMENT - CENTER <i>new</i>	1	\$ 536.00	✗
6	FRONT BUMPER CLOSING ELEMENT - RH <i>new</i>	1	\$ 297.00	✗
7	FRONT BUMPER COVER TRIM - RH <i>new</i>	1	\$ 163.00	✗
8	FRONT BUMPER ADAPTER - RH <i>new</i>	1	\$ 38.00	✗
9	FRONT RADIATOR GRILLE <i>crashed</i>	1	\$ 1,406.00	✓
10	FRONT RADIATOR GRILLE CLOSING ELEMENT <i>crashed</i>	1	\$ 191.00	✓
11	FRONT AIR GUIDE GRILLE - RH <i>new</i>	1	\$ 188.00	✗
12	FRONT FOAM FILLER PIECE <i>Deformed</i>	1	\$ 189.00	✓
13	FRONT REINFORMENT BEAM COVER <i>horn</i>	1	\$ 122.00	✓
14	FRONT REINFORMENT BEAM <i>Bent</i>	1	\$ 795.00	✓
15	HORN - RH <i>new</i>	1	\$ 200.00	✗
16	FRONT BONNET <i>Deformed</i>	1	\$ 3,134.00	✓
17	FRONT BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 165.00	✗
18	FRONT BONNET HINGE - LH / RH <i>new</i>	2	\$ 124.00	✗
19	FRONT BONNET CATCH HOOK <i>new</i>	1	\$ 90.00	✗
20	FRONT BONNET STRIKER PLATE - RH <i>new</i>	1	\$ 110.00	✗
SUB TOTAL SPARE PARTS			\$ 10,121.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMK 1877 T

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	FRONT BONNET EDGE PROTECTION <i>cracked</i>	1	\$	28.00	✓
22	FRONT BONNET LOCK WITH MICRO SWITCH - RH <i>new</i>	1	\$	214.00	+
23	FRONT BONNET BOWDEN CABLE - CENTER <i>new</i>	1	\$	58.00	+
24	FRONT BONNET LOCK CABLE <i>? new</i>	1	\$	74.00	+
25	FRONT BONNET CATCH HOOK <i>? new</i>	1	\$	63.00	+
26	FRONT HEADLIGHT - RH <i>cracked</i>	1	\$	5,455.00	✓
27	FRONT HEADLIGHT LIFT CYLINDER - RH <i>? new</i>	1	\$	142.00	+
28	FRONT HEADLIGHT LIFT CYLINDER HOSE <i>? new</i>	1	\$	68.00	+
29	FRONT LOCK CARRIER <i>cracked</i>	1	\$	727.00	✓
30	COOLANT <i>new</i>	6	\$	266.00	✓
31	AIR-CON CONDENSER <i>new</i>	1	\$	530.00	+
32	CONDENSER BRACKET <i>cracked temperature sensor bracket</i>	1	\$	19.00	✓
33	FRONT RADIATOR AIR GUIDE - RH <i>? torn</i>	1	\$	25.00	✓
34	FRONT AIR GUIDE - RH OUTER <i>? new</i>	1	\$	8.00	+
35	FRONT RADIATOR AIR GUIDE - UPPER CENTER <i>new</i>	1	\$	12.00	✓
36	AIR CONDITIONER STICKER <i>? new</i>	1	\$	8.00	✓
37	CAUTION STICKER <i>? new</i>	1	\$	14.00	✓
38	FRONT NO PLATE <i>Deleted</i>	S/N	\$	60.00	✓
39	SUNDRIES <i>?</i>		\$	350.00	?
TOTAL SPARE PARTS		:	\$	18,242.00	
TOTAL LABOUR CHARGES		:	\$	9,002.00	
GRAND TOTAL		:	\$	<u>27,244.00</u>	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Admin Lj
Resubmtd 07/09/21.
H.S.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMK 1877 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	250
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR,RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OIIT VACUUM AND RFGAS	S/N \$ 1,400.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	1000 + 1250
5	TO RESPRAY FRONT BUMPER , BONNET AND HINGES.	\$ 2,500.00	1100
6	TO CARRY OUT DIAGNOSTIC CHECK	\$ 192.00	-
TOTAL LABOUR CHARGES		\$ 9,002.00	

Add. 3 Days