

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21008749/AVCE2

**Date:** 03/11/2021

### REFERENCE

Insured/Claimant:	LIEW MUN KIONG	Policy No:	7210074983		
Date of Loss:	13/08/2021	Nature of Claim:	OD	Claim No:	8337761644SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ8218T		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC41672
Reg. Date:	28/07/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF30M1128013
Colour:	Red	Odometer:	697 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/65 R17	Rear Tyre Size:	215/65 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,521.00	5,715.44	4,805.56	45.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,332.00	4,402.00	5,930.00	57.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,853.00</b>	<b>10,117.44</b>	<b>10,735.56</b>	<b>51.48</b>
<b>- Excess (S\$)</b>	<b>400.00</b>	<b>400.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>20,453.00</b>	<b>9,717.44</b>	<b>10,735.56</b>	<b>52.49</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,431.71</b>	<b>680.22</b>	<b>751.49</b>	<b>52.49</b>
<b>Nett Amount (S\$)</b>	<b>21,884.71</b>	<b>10,397.66</b>	<b>11,487.05</b>	<b>52.49</b>

### INSPECTION

Date of Assignment:	20/08/2021		
Date Inspected:	19/08/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER SPOILER	Cut	459.00 FS	*367.20 FS
2	2		*REAR WHEEL ARCH COVER LH / RH	N/S Cut / O/S Necessary	1,072.00 FS	*857.60 FS
3	1		*REAR DOOR LH	Dented	2,816.00 FS	*2,252.80 FS
4	1		*REAR DOOR OUTER SEAL LH	Necessary	135.00 FS	*108.00 FS
5	1		*REAR DOOR CATCH LH	Damaged	120.00 FS	*96.00 FS
6	1		*REAR DOOR COVER LH	Cut	349.00 FS	*279.20 FS
7	1		*FRONT DOOR LH	Repair	2,816.00 FS	*- FS
8	1		*FRONT DOOR OUTER SEAL LH	Not Necessary	166.00 FS	*- FS
9	1		*FRONT DOOR CATCH LH	Not Necessary	120.00 FS	*- FS
10	1		*FRONT DOOR COVER LH	Cut	370.00 FS	*296.20 FS
11	1		*FRONT WHEEL ARCH COVER LH	Cut	536.00 FS	*428.80 FS
12	1		*REAR ALUMINIUM RIM LH	Cut	1,262.00 FS	*1,009.60 FS
13	1		*SUNDRIES	Necessary	300.00 FS	*20.04 FS
					<b>Total Parts (S\$)</b>	<b>10,521.00      5,715.44</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION	New	360.00	0.00
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	280.00
3	TO DISMANTLE AND REINSTALL REAR BUMPER. TO RENEW LHS REAR DOOR AND LHS FRONT DOOR. TO REPAIR LHS FRONT FENDER	New	3,600.00	1,000.00
4	TO RESPRAY REAR BUMPER, LHS REAR DOOR, LHS FRONT DOOR, LHS FRONT FENDER, BOTH REAR WHEEL ARCH TRIMS AND LHS FRONT WHEEL ARCH TRIM	New	4,300.00	2,250.00
5	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO RESPRAY BOTH LHS DOOR COVER (Supplementary)	New	800.00	400.00
<b>Gross Labour Cost (\$)</b>			<b>10,332.00</b>	<b>4,402.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >