

anasonic  
CONDITIONER

KV

NOT Authorized  
L1Pmp @ 4250/-  
Resurvey After Paint  
5 days

# ESTIMATE RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722  
Tel : 97619383 Email : rcauto5555@gmail.com  
Reg. No. 53199168K

GBH 9159 B

Date : 23.08.2021

Quantity	Description/Particular	Unit Price	Amount
	FRONT BUMPER <i>571.90</i> <i>1971.00A</i>	NETT	571 90
2 PCS	FRONT BUMPER FOG LAMP@31.80	<i>mi7</i> S,NETT	63 60
2 PCS	FRONT BUMPER FOG LAMP COVER@117.50	<i>mi7</i> NETT	235 00
	FRONT BUMPER REFORCEMENT <i>528</i>	<i>121</i> NETT	775 90
	FRONT BUMPER LOWER GANISH	<i>mi7</i> NETT	95 00
	FRONT GRILLE <i>485</i>	<i>CPM</i> NETT	527 30
2 PCS	FRONT HEADLAMP@391.50 <i>ols mjeem</i>	<i>11820</i> NETT	783 00
	FRONT PANEL <i>1227.50</i>	<i>127</i> NETT	1227 50
2 PCS	FRONT BUMPER RETAINER@181.00	<i>127</i> NETT	362 00
	FRONT BUMPER BEAM	<i>12</i> NETT	235 00
	FRONT RADIATOR-SMALL <i>108</i>	<i>12</i> S,NETT	2121 60
		TOTAL	6965 40
	SPRAY PAINTING		500 00
	TO REMOVE DASHBOARD TO FACILITATE REPAIR		280 00
	LABOUR CHARGES TO REPLACE ABOVE PARTS		800 00
	TOWING FEES		60 00
	FRONT NUMBER PLATE	<i>mi</i>	30 00
	TO CHECK WIRING		20 00
	GRAND TOTAL		8655 40

✓  
✓  
✓  
✓  
✓  
✓  
✓  
✓  
✓  
x  
^  
450/-  
250/-  
600/-  
50/-  
2050/-

Received the above goods in good order and condition for RC AUTO

Received by \_\_\_\_\_

Authorized Signature \_\_\_\_\_

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal trade in parts is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: