

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

CMTD2102497/GPL


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

22/9/21 *have video*
L/S \$500 confirmed with Susan 1 repair day.
 (RED \$376.50; 43%)

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / L/DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rpt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1) 27/9 TYPIST

Date/Time, File Return to?

☐

: Final Report

2)

Report Format: TP

Lump Sum / ~~100~~ (\$500)

Days Of Repair: 1

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) _ \$ + RS _ \$

) Photos

) Others

TOTAL

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931. Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBL2651X210814

Estimate

Customer	
Name: Sompoo Insurance Singapore Private Limited	Date: 19/08/2021
Address: Motor Claims Department	Vehicle No: GBL2651X
50 Raffles Place #05-01 / 06	Model/Make: Nissan NV200
Singapore Land Tower Singapore 048623	1.6 (A) Petrol

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Bumper <i>gross</i>	\$ 541.50	N ✓
2	Bumper Clips 1 Set <i>net</i>	\$ 30.00	N ✓
3	Bumper Side Retainer <i>net</i>	\$ 25.00	N X
	To check all wiring & electrical component for proper function	\$ 30.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 250.00	120

Total Parts & Labour of estimate for damaged vehicle	\$ 876.50
--	-----------

Total amount in Lump Sum Basis for repaired vehicle	
---	--

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

not Authorized
22/8/21

4/5 \$ 500

Whaphoto after repair

1 day

** Submit to insurance*

P- 571.50
10%
P- 514.35
L- 120.00
634.35
202
507.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____