

aka HSI 10 7mg

Not Advised
aka
1/5 @ 6500
20/8/12
5 days.

CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SPORE 417883

VEHICLE No: SJT 5709H

1PC	FRONT BUMPER SPORT	dis/Torn	1300	\$1,850.00	—
1PC	FRONT BUMPER FOG LAMP O/S	one	298	\$620.00	—
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	cut	300	\$485.00	—
2PCS	FRONT BUMPER SIDE RETAINERS @ \$115.00	o/s/cra	62	\$230.00	1PC
1PC	FRONT BUMPER PDC SENSOR	NF		\$235.00	X
1PC	FRONT BUMPER BEAM	R		\$485.00	X
1PC	FRONT BUMPER TOW COVER	cut		\$35.00	—
1SET	FRONT BUMPER CLIPS	all	48.00	\$60.00	—
1PC	FRONT GRILLE	11		\$655.00	X
1PC	HEADLAMP LED O/S	scr/one	1950	\$2,450.00	—
1PC	HEADLAMP LOWER BRACKET O/S	one	148.11	\$322.00	—
1PC	FRONT SUPPORT PANEL	one	822.15	\$1,080.00	—
1PC	WIPER WASHER TANK	de	205.50	\$285.00	—
1PC	FRONT FENDER O/S	RUC	642.23	\$745.00	—
1PC	FRONT FENDER INNER SHIELD O/S	del/torn	186.20	\$315.00	—
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	all		\$50.00	—
1PC	FRONT DOOR O/S	R		\$1,285.00	X
1PC	FRONT SHOCK ABSORBER O/S	11		\$850.00	X
1PC	FRONT lower ARM O/S		399.50	\$422.00	—
1PC	FRONT KNUCKLE ARM BEARING O/S	Daged		\$285.00	—
1PC	FRONT DRIVE SHAFT O/S	11		\$1,450.00	X
1PC	FRONT SPORT RIM O/S	20/wopel	500 S/N	\$1,200.00	—
1PC	FRONT TYRE O/S	11		\$250.00	X
				\$15,644.00	

(102)

- TO CHECK WIRING
- TO DISMANTLE & REPLACED FRT PDC SENSOR
- TO REFILL AIR CON GAS
- TO CONDUCT WHEEL ALIGNMENT
- TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE
- TO SPRAY RUST PROOFING
- TO RESET & REPROGRAMME SYSTEM
- LABOUR FOR PANEL BEATING & REPLACED PARTS
- TO PUTTY & SPRAY PAINTING

	\$50.00	20
11	\$80.00	X
	\$120.00	100
	\$150.00	80
	\$180.00	120
	\$50.00	30
11	\$180.00	X
	\$1,200.00	680
	\$1,500.00	600
TOTAL	\$19,154.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

P-6728-69
102
P-6253-12
S.N-500
L-1630
P183-12