

SMC 807 U  
TP/CHINA

**REPAIR DETAILS**

**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Aug 2021)  
 Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for SMC807U)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

85483.00

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 PC REAR BUMPER	Bj 0.00	0.00	*190.00 F	✓
2	1		*6 PCS REAR BUMPER CLIPS @2/PC	Me 0.00	0.00	*12.00 F	✓
3	1		*1 PC REAR BUMPER LH SIDE RETAINER	Dii 0.00	0.00	*12.00 F	✓
4	1		*1 PC REAR END PANEL	R Bj 0.00	0.00	*290.00 F	✓
5	1		*1 PC REAR END PANEL INNER TOP GARNISH	Dii 0.00	0.00	*48.00 F	✓
6	1		*1 PC TAILGATE	Bj 0.00	0.00	*620.00 F	✓
7	1		*1 PC TAILGATE EMBLEM (VEZEL)	Me 0.00	0.00	*30.00 F	✓
8	1		*1 PC TAILGATE INNER LOCK	Tm 0.00	0.00	*70.00 F	✓
9	1		*1 PC TAILGATE INNER RUBBER	Dii Me 0.00	0.00	*50.00 F	✓
10	1		*1 PC TAILGATE OUTER GARNISH	CM 0.00	0.00	*210.00 F	✓
11	1		*2 PCS TAILGATE REFLECTORS @145/PC	CM 0.00	0.00	*290.00 F	✓
12	1		*1 PC REAR WINDSCREEN GLASS MOULDING	Me 0.00	0.00	*70.00 F	✓
13	1		*1 PC REAR WINDSCREEN GLASS	Shatter 0.00	0.00	*520.00 F	✓
14	1		*1 PC REAR WIPER ARM	Bw 0.00	0.00	*48.00 F	✓
15	1		*1 PC REAR WIPER MOTOR	Tm 0.00	0.00	*110.00 F	✓
16	1		*1 PC REAR WIPER ARM COVER	Mi 0.00	0.00	*8.00 F	✓
17	1		*1 PC REAR SPARE COMPARTMENT	R 0.00	0.00	*320.00 F	✗
18	1		*1 PC REAR SPARE TYRE TOP BOARD	Sm 0.00	0.00	*155.00 F	✗
19	1		*1 PC REAR TOOL BOX	CM 0.00	0.00	*110.00 F	✓
20	1		*1 PC REAR LH FENDER INNER GARNISH	Bul/Dii 0.00	0.00	*290.00 F	✓
21	1		*2 PCS HEADLAMPS @250/PC	CM 0.00	0.00	*500.00 F	✓

F=Franchise part.

Acw wiper blade 35-w ✓ Bw Total Parts (S\$) 3,953.00

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

**Estimates on Miscellaneous Items**

No	Qty	Particulars	Amount	
<b>Miscellaneous Items</b>				
1	1	1 PC REAR WINDSCREEN GLASS GUM	Me 40.00	✓
2	1	1 SET CCTV CAMERA	Sm 380.00	✗
3	1	1 SET REVERSE SENSOR	Me 200.00	✓
Sub Total (S\$)			620.00	


**Estimates on Labour**

Faster  
memory

Precision



Faster



Gigabit

Estimate Report

Page 3 of 3

No	Particulars	Lab.Type	Amount	
<b>Labour Items</b>				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00	✓
2	REMOVE & REFIX REAR SEAT,CARPET,GARNISH,ETC	New	100.00	✓
3	REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,TAILGATE & ATTACHMENT,TO STRAIGHTEN,KNOCK & REPAIR REAR LH FENDER & CHASSIS,CUT,WELD & RENEW REAR COMPARTMENT,REAR END PANEL	New	1,200.00	900
4	PUTTY & RESPRAY ON REAR COMPARTMENT,REAR END PANEL,REAR BUMPER,TAILGATE,OUTER GARNISH,REAR FENDERS & REAR AFFECTED AREAS	New	1,100.00	900
	RUSTPROOFING	New	80.00	60
	REMOVE & REFIX REAR CCTV CARMERA,SMART KEY SENSOR & RESET SYSTEM	New	60.00	✓
			<b>Gross Labour Cost (S\$)</b>	<b>2,640.00</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey ~~before/after~~ spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: