

ASS. REC. BY:

REF: C72/210087711K9c

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / LWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Cheng Hoe

Insured: _____

Policy No. _____


Claims No. SNM21D204618C02

Sum Insured: _____ Excess: _____

(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMC 807U Yr Regn: 06.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____ (A)

Make: Honda Vel c.c. 1491

Colour: M. D. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 90525 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU1-1230951

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/RIm / STD A/RIm or

Tyre Size: F: _____ R: 215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or _____

Front R/Bal. 9 mm Rear R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 19/8/21 D.O.I. 20/8/2021

Survey held at _____

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/08/21 @ 4.24pm	revised to Chee So Chow by email.
	Kenneth confirmed final fig \$5483.00 (Red \$1765, 24%)

Date/Time, File Pass to?

: Prell. Report

1) 29/09 Typist

: Final Report

Date/Time, File Return to?

Days Of Repair: 6

Resurvey No. of Trlp: 2

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Add Fee: : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format :

MER-TP

~~Lump Sum~~ / I.B.I: (\$

5483.00

SMC 807 U

TP/CHINA

REPAIR DETAILS	
Reference	
Part Source: MPM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2021)
Parts: M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMC807U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 PC REAR BUMPER	By 0.00	0.00	*190.00 F	✓
2	1		*6 PCS REAR BUMPER CLIPS @2/PC	Ne 0.00	0.00	*12.00 F	✓
3	1		*1 PC REAR BUMPER LH SIDE RETAINER	0.00	0.00	*12.00 F	?
4	1		*1 PC REAR END PANEL	By 0.00	0.00	*290.00 F	✓
5	1		*1 PC REAR END PANEL INNER TOP GARNISH	Dis 0.00	0.00	*48.00 F	✓
6	1		*1 PC TAILGATE	By 0.00	0.00	*620.00 F	✓
7	1		*1 PC TAILGATE EMBLEM (VEZEL)	Ne 0.00	0.00	*30.00 F	✓
8	1		*1 PC TAILGATE INNER LOCK	Tm 0.00	0.00	*70.00 F	✓
9	1		*1 PC TAILGATE INNER RUBBER	Dis Mat 0.00	0.00	*50.00 F	✓
10	1		*1 PC TAILGATE OUTER GARNISH	CR 0.00	0.00	*210.00 F	✓
11	1		*2 PCS TAILGATE REFLECTORS @145/PC	CR 0.00	0.00	*290.00 F	✓
12	1		*1 PC REAR WINDSCREEN GLASS MOULDING	Ne 0.00	0.00	*70.00 F	✓
13	1		*1 PC REAR WINDSCREEN GLASS	Shotton 0.00	0.00	*520.00 F	✓
14	1		*1 PC REAR WIPER ARM	By 0.00	0.00	*48.00 F	✓
15	1		*1 PC REAR WIPER MOTOR	Tm 0.00	0.00	*110.00 F	✓
16	1		*1 PC REAR WIPER ARM COVER	Dis 0.00	0.00	*8.00 F	✓
17	1		*1 PC REAR SPARE COMPARTMENT	0.00	0.00	*320.00 F	?
18	1		*1 PC REAR SPARE TYRE TOP BOARD	0.00	0.00	*155.00 F	?
19	1		*1 PC REAR TOOL BOX	0.00	0.00	*110.00 F	?
20	1		*1 PC REAR LH FENDER INNER GARNISH	Buld Dis 0.00	0.00	*290.00 F	✓
21	1		*2 PCS HEADLAMPS @250/PC	CR 0.00	0.00	*500.00 F	✓
F=Franchise part.			Tail				
Total Parts (S\$)						3,953.00	

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount	
Miscellaneous Items				
1	1	1 PC REAR WINDSCREEN GLASS GUM	Ne 40.00	✓
2	1	1 SET CCTV CAMERA	380.00	?
3	1	1 SET REVERSE SENSOR	Ne 200.00	✓
Sub Total (S\$)			620.00	

Estimates on Labour

No	Particulars	Lab.Type	Amount
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00 ✓
2	REMOVE & REFIX REAR SEAT,CARPET,GARNISH,ETC	New	100.00 ✓
3	REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,TAILGATE & ATTACHMENT,TO STRAIGHTEN,KNOCK & REPAIR REAR LH FENDER & CHASSIS,CUT,WELD & RENEW REAR COMPARTMENT,REAR END PANEL	New	1,200.00 800
4	PUTTY & RESPRAY ON REAR COMPARTMENT,REAR END PANEL,REAR BUMPER,TAILGATE,OUTER GARNISH,REAR FENDERS & REAR AFFECTED AREAS	New	1,100.00 900
5	RUSTPROOFING	New	80.00 60
6	REMOVE & REFIX REAR CCTV CARMERA,SMART KEY SENSOR & RESET SYSTEM	New	60.00 ✓
Gross Labour Cost (S\$)			2,640.00


Report was unsubmitted during this print-out.
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP/CHINA (GBH5530M)
Policy No:		Date of Loss:	19/08/2021
Vehicle Reg. No.:	SMC807U	Driveable?	
Party At Fault:	UNKNOWN	Driver (Insured):	ANG AH SAN
Driver (TP):	SANIM BIN MAIN	Vehicle Reg. Date:	26/06/2018
Make/Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11230951
Vehicle Colour:	BLACK	Odometer:	0 KM
Engine No:	L15B4430958	<i>Not Authorized</i> <i>1-B. 1, 1/1 Rmp</i> <i>6-7 days</i>	
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.		
Remarks:	VEHICLE CURRENTLY LYING AT YISHUN WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

COST OF CLAIMS

	Amount
Parts	3,953.00
Miscellaneous Items	620.00
Labour	2,640.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,213.00
+ GST 7.00% (S\$)	504.91
Nett Amount (S\$)	7,717.91

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 19/08/2021 18:36 (SGT)
Date of Accident 19/08/2021 16:10 (SGT)
Exact Location of Accident Singapore
Additional Location Information SLIP RD ALONG WOODLANDS AVE 3 TOWARDS WOODLANDS AVE 5
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMC807U

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner SUKHAIMI BIN SUJA
NRIC No SXXXX003F
Email Address waksuk@singnet.com.sg
Mobile Phone No (Phone) +65-98342386
Alternative Phone No +65-98342386

VEHICLE PARTICULARS

Manufacturer Honda
Model VEZEL 1.5X CVT
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1496

INSURANCE COMPANY


Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5101611380-03
Cover Note Number 26/06/2021 -25/06/2022

DRIVER

Name of Driver SANIM BIN MAIN

woodlands Ave 5

Sketch Plan



Woodlands Ave 3

A - SMC 807 U

B - GBH 5530 M

Ang Ah San

S1313199 F

HP: -

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DOA - 19/08/21

Time : 1610hrs

Accident occurred at the dip road along Woodlands Ave 3 towards Woodlands Ave 5. I stopped to look out for vehicles on main road. Out of sudden, I felt a great impact on my rear and realized m/lorry (B) had hit onto my vehicle.

Both drivers alighted to check. Driver of m/lorry (B) apologized and we exchanged particulars.

I have 2 passengers onboard however no one was injured.

Clear & dry weather condition.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

19/8/21

Reporting Centre Personnel's Signature
Name: CWL
NRIC/FIN No.:

Claim Own Policy Claim Third Party Reporting Only