



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PZ 955T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	CUT		
	FRONT LEFT SIDE MIRROR (CONSISTENT)		350.00	350.00
	LESS 10% DISCOUNT		-35.00	-
	LESS 25% DISCOUNT		-	-87.50
			315.00	262.50
	<u>LABOUR</u>			
	TO KNOCK AND ALL NECESSARY PARTS INCLUDING CHANGING OF ALL DAMAGED PART.TO PUTTY AND SPRAY AND PAINTING ON FRONT BUMPER ,FRONT BONNET,FRONT LEFT DOOR PANEL ,FRONT LEFT SIDE MIRROR PANEL.		1,200.00	400.00
			1,200.00	400.00
GRAND TOTAL			1,515.00	662.50
RECOMMENDED COST OF REPAIRS				662.50

Report Ref No. CC4/ASM19001898/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.