



CROWN ASIA BUS BUILDER PTE LTD

44 SUNGEI KADUT AVE, Singapore 729667
Tel : +65 6966 0666
Email : claims@crownasia.com.sg

Company Reg No: 201023449R

AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01
AXA TOWER
SINGAPORE 068811

Attn : Motor claims dept

Dear Sir/Madam,

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

17 AUG 2021

THIRD PARTY CLAIM - REPAIR ESTIMATE FOR PZ 955 T

Traffic accident involving PZ955T and SLA1874R along VICTORIA STREET on 14/01/2019

Vehicle owner : RUI FENG CHARTERED PTE LTD
Vehicle No. : PZ955T
Model : TOYOTA HIACE COMMUTER GL 3.0 AT 2WD 4DR LWB
Date of Damaged : 14/01/2019

We append below the estimate repair cost for PZ955T: -

Part required:-

1 pc	Front left side mirror ✓ cut	\$ 350.00	350
	25%		
	Less 10% trade discount	\$ 35.00	25%
		\$ 315.00	262.50

Labour charges:-

To knock and all necessary part including changing of all damaged part.

To putty and spray and painting on Front bumper, Front bonnet,

Front left door panel, Front left side mirror panel.

~~\$ 1200.00~~ 400
\$ 1515.00

Please arrange for your surveyor to survey the vehicle at 44 Sungei Kadut Ave, S729667. Kindly contact Mr Andy, 8331 5664 to arrange for the surveyor.

Yours faithfully



262.50
400.00
662.50

2 days / P/P