



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3220X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER FRT	TO REPAIR SEE LABOUR	1,052.20	-
10	BUMPER COVER CLIP	NOT NECESSARY	22.00	-
1	PANEL-FENDER RH	TO REPAIR SEE LABOUR	663.00	-
1	BRKT ASSY-FR BPR UPR SIDE	NOT NECESSARY	44.80	-
	LESS 20% DISCOUNT		-356.40	-
			1,425.60	-
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF BUMPER COVER FRT AND PANEL-FENDER RH.		600.00	280.00
	SPRAYPAINT CHARGE.		600.00	500.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	50.00	-
			1,250.00	780.00
GRAND TOTAL			2,675.60	780.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				780.00

Report Ref No. NS/INC21008782/Gvcn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.