

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD620U

AAD2108-

*Not Notified**61 Png B 4200h*

Vehicle No.:

Chassis No.:

19 AUG 2021

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD620U

VF1ABL15AUC283399

RENAULT

LATITUDE

18/08/2021

Chim-
30/11/2017

PART
1 BUMPER COVER REAR
1 BUMPER LOWER REAR
1 BUMPER REFLECTOR RH
1 BUMPER BRACKET CTR REAR
1 BUMPER BRACKET SIDE RH REAR
1 BUMPER RETAINER RH REAR
1 BUMPER BRACKET SIDE LH REAR
1 BUMPER RETAINER LH REAR
1 BUMPER BEAM REAR
1 BUMPER BEAM BRACKET LH REAR
1 BUMPER BEAM BRACKET RH REAR
1 OUTER PANEL REAR (End Panel)
1 OUTER PANEL REAR (End Panel)TRIM
1 FENDER PANEL REAR RH
1 WHEELARCH REAR RH
1 BOOT REFLECTOR LAMP RH
1 TAILLAMP RH
1 EXHAUST REAR
1 BOOT REAR
1 BOOT BADGE 'RENAULT'
1 BOOT BADGE
1 BOOT REFLECTOR LAMP RH
1 BOOT HINGE LH
1 BOOT HINGE RH
1 BOOT STRUT LH
1 BOOT STRUT RH
1 BOOT LOCK
1 BOOT LOCK CATCH

LIST
\$ 561.70 ✓
\$ 411.90 ✓
\$ 16.60 X
\$ 98.10 X
\$ 82.10 ✓
\$ 59.80 ✓
\$ 80.80 X
\$ 54.20 X
\$ 547.80 X
\$ 114.50 X
\$ 114.50 X
\$ 745.80 X
\$ 404.56 X
\$ 1,933.20 ✓
\$ 275.40 X
\$ 277.70 X
\$ 401.40 ✓
\$ 5,263.60
\$ 1,677.20
\$ 82.40
\$ 95.80
\$ 277.70
\$ 254.20
\$ 254.20
\$ 145.10
\$ 145.10
\$ 246.60
\$ 41.70

Trans-cab Auto Services Pte Ltd

AAD2108-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD620U**1 BOOT FINISHER**

\$	344.70	X
\$	15,008.36	
10% \$	1,500.84	
\$	<u>13,507.52</u>	

Special Nett

1 FENDER CLIP	\$	70.00	X
1SET PARKING AID	\$	700.00	4001m
1SET REAR BUMPER CLIP	\$	66.00	✓
1SET BUMPER BRACKET CTR CLIP	\$	33.00	X
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	66.00	✓
1 EXHAUST MOUNTING REAR	\$	17.82	X
1 REAR BOOT STICKER 'Trans-cab'	\$	80.00	X
1 REAR BOOT STICKER '6555-3333'	\$	80.00	X
1 LICENSE PLATE WITH HOLDER FRT	\$	120.00	X
2 WINDSCREEN SEALANT	\$	150.00	405m
1 WINDSCREEN MOULDING	\$	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	305m

TOTAL \$ 1,772.82**TOTAL PARTS \$ 15,280.34****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	660l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	600l
To Rust-Proofing Of The Affected Areas.	\$	170.00	30l
To reinstall rear bumper parking sensor.	\$	170.00	60l

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2108-

SHD620U

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 <i>801</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 <i>1201</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
TOTAL	\$	7,580.00

Over All Total \$ 36,367.87**(LUMP SUM)****Repair Days*****20 DAYS******3 days***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____