



陳林峰呷私人有限公司
TAN LIM MOTOR PTE LTD

Budget Direct Insured's Veh No : SGP4050L

Date of Accident : 19 August 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Messrs BIS Motoring Pte Ltd

Date : 20 August 2021

Estimate To Repair SMD4315R - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : KNAHU815VJ7211729

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	n/s front door	\$ 914.00
02	1 pc	n/s front door top moulding	\$ 125.00
03	1 pc	n/s front door rubber	\$ 105.00
04	1 pc	n/s rear door	\$ 842.00
05	1 pc	n/s rear door top moulding	\$ 125.00
06	1 pc	n/s rear door rubber	\$ 115.00
07	1 pc	n/s rocker panel	\$ 1,729.00
			\$ 3,955.00
		Less 10 %	\$ 395.50
			\$ 3,559.50
		<u>LABOUR & MISC. CHARGES</u>	
01		To rust-proofing of the affected areas.	\$ 250.00
02		To transfer of left both door fittings and perform water seepage test.	\$ 200.00
03		To check electrical lighting concerned.	\$ 80.00
04		Panel beating, knocking and straighten the necessary portion,	\$ 750.00
		remove and renewal of parts, adjust and realign the same.	
05		Putty and spray painting of the affected portion.	\$ 750.00
			\$ 2,030.00
		Total	\$ 5,589.50