

⏪	<	1	of 2 ?	>	⏩	↺	↻	100%	⏴	⏵	Find   Next
---	---	---	--------	---	---	---	---	------	---	---	-------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref: CS3/AIG21008794/G#3	
78 SHENTON WAY #09-16		Date: 23/08/2021	
AIG BUILDING			
SINGAPORE 079120		Code: AIG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	GBA5601D	Veh. Inspected	C001377453
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	DIVYASHNI SUBRAMANIAM	Assign Date	23/08/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/07/2021	Inspection Date	23/08/2021
Survey held at	HUP LEY HUAT MOTOR SPRAY PAINTING SVS BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			