

Hup Ley Huat Motor Spray Painting Services

No.1 Kaki Bukit Ave 6 #01-35 AutoBay, Singapore 417883

TEL: 6746 0674 FAX: 6841 7639

Vehicle No : C001377453

Make: Maserati Gibli

Date: 11/10/2021

Accident Date: 23/07/2021

Spare parts

QTY	List Price	Price	(S\$)	
1	Front Bumper	✓ DE	3069.10	✓
1	Front Bumper Bracket	X NN	55	
1	Front Headlamp	✓ CUT	4871.60	✓
1	Front Bumper Parking Sensor	X NN	1418.83	
1	Front Grille Assembly	X NN	789.80	
1	Front Lower Grille	X NN	320.20	
Spare Parts Subtotal			10524.53	7940.7

Special Nett Items

-10%: 7146.63

Qty

-	-	-
		-

Labour charges

S/N		(S\$)	
1	To tuff coat affected areas	120	X NN
2	To spray paint include polishing and waxing on the changed body parts, repair body portions where consistent to the accident	1200	300
3	To provide labour charges, workmanship to re-align body structure and damaged consistent to the accident	1200	250
4	To remove and refit. Wiring for front sensor	150	40
5	To focus headlamp	150	30
Labour charges: Subtotal		2820	

ESTIMATES PARTS AND LABOR GRAND TOTAL: 13344.53 7766.63

-20%: 6200

2 Days

