

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Estimate

Vehicle No:
Make and model:SMK8659K
Honda Vezel

Qty Spare parts

List price

1	Tailgate	S	✓ 953.30	DDV
1	Tailgate windscreen glass	S	✓ 1,012.30	BRV
1	Tailgate windscreen glass upper rubber moulding	S	✓ 52.00	} NECU
1	Tailgate windscreen glass lower rubber moulding	S	✓ 52.00	
1	Tailgate windscreen glass RH rubber moulding	S	✓ 52.00	
1	Tailgate windscreen glass LH rubber moulding	S	✓ 52.00	
1	Tailgate outer garnish	S	✓ 225.00	BRV
1	Tailgate outer garnish chrome moulding	S	✓ 87.30	BRV
1	Tailgate outer garnish centre emblem	S	✓ 27.00	} NECU
1	Tailgate "Vezel" emblem	S	✓ 56.20	
1	Tailgate RH lamp assy	S	✓ 413.20	} BRV
1	Tailgate LH lamp assy	S	✓ 413.20	
1	Tailgate RH number plate lamp assy	S	45.50	} NDX
1	Tailgate LH number plate lamp assy	S	45.50	
1	Tailgate open button sensor	S	✓ 178.70	JMV
1	Tailgate inner trim board	S	✓ 153.40	BRV
1	Tailgate inner RH side garnish	S	✓ 74.50	} BRV
1	Tailgate inner LH side garnish	S	✓ 74.50	
1	Tailgate inner pull handle	S	✓ 27.50	BRV
1	Tailgate lock	S	✓ 182.00	JMV
1	Tailgate lock catch	S	✓ 27.50	NDX
1	Tailgate weatherstrip	S	✓ 96.80	DIS
1	Tailgate RH absorber stay	S	182.00	} ? NDX
1	Tailgate LH absorber stay	S	182.00	
1	Tailgate wiper motor	S	✓ 235.00	BBTV
1	Tailgate wiper arm	S	✓ 93.60	} MIS
1	Tailgate wiper blade	S	55.10	
1	Rear bumper	S	35.30	508.50
1	Rear bumper lower cover	S	182.93	508.50
1	Rear bumper RH reflector	S	✓ 141.10	BRV
1	Rear bumper LH reflector	S	✓ 141.10	} ? BRV
1	Rear bumper RH side cover	S	92.95	195.00
1	Rear bumper LH side cover	S	92.95	195.00
1	Rear bumper RH side retainer	S	✓ 23.00	} NECU
1	Rear bumper LH side retainer	S	✓ 23.00	
1	RH taillamp assy	S	✓ 474.60	BRV
1	RH taillamp panel	S	145.00	NDX

1	LH taillamp assy	S	✓	474.60	BR✓
1	LH taillamp panel	S		145.00	?NDX
1	End panel	S	✓	415.60	?DDV
1	End panel inner garnish	S	✓	98.00	?BR✓
1	End panel buzzer sensor	S	✓	85.20	?BR✓
1	End panel antenna sensor	S	✓	60.10	?BR✓
1	Rear compartment panel sponge tray	S		260.30	485.20 ?BR✓
1	Rear compartment panel sponge tray top cover board	S		430.50	NDX
1	Rear RH fender arch moulding	S	✓	197.00	BR✓
1	Rear RH fender inner trim board	S	✓	298.00	?TN✓
1	Rear RH fender splash shield	S		147.60	NDX
1	Rear LH fender arch moulding	S	✓	197.00	BR✓
1	Rear LH fender inner trim board	S	✓	298.00	?TN✓
1	Rear LH fender splash shield	S		147.60	NDX
1	Exhaust silencer	S		547.70	?NDX
1	Exhaust silencer gasket	S		48.30	?NDX
		S			11,190.80
		-20%	S		2,238.16
		S			8,952.64

Qty Spare parts

Special Nett price

1	Tailgate in-car camera recorder	S		680.00	NDX
1	Tailgate windscreen glass solar film	S	240.00	220.00	NECV
1	Tailgate windscreen glass sealant	S	40.00	70.00	NECV
1	Tailgate windscreen glass inner seal	S	20.00	50.00	NECV
1	Tailgate reverse camera	S		450.00	NDX
1set	Tailgate outer garnish clips	S	30.00	60.00	NECV
1set	Tailgate inner trim board clips	S	30.00	60.00	NECV
1	Rear number plate	S		70.00	NDX
1	End panel joint sealant	S	30.00	70.00	NDX
1set	Rear RH fender inner trim board clips	S	30.00	60.00	NECV
1set	Rear LH fender inner trim board clips	S	30.00	60.00	NECV
1set	Rear bumper clips	S	30.00	70.00	NECV
1set	RH taillamp clips	S	15.00	30.00	NECV
1set	LH taillamp clips	S	15.00	30.00	NECV

Labour and painting

Labour charges to remove, check, replace and reinstall damaged body parts.

Ex panel beading, cut, weld and re-align all affected panels

S 1,000.00 ✓

Spray painting on affected panels	S	1,000.00 ✓
Check wiring and lighting system	S	70.00 N N X
Apply rust coating chemical on affected panels	S	80.00 N N X
Remove and replace tailgate inner components to new tailgate	S	80.00 100.00 NEC ✓
Replace tailgate windscreen glass and sealants	S	120.00 200.00 ✓
Remove, replace and adjust tailgate in-car camera recorder	S	480.00 N N X
Remove and replace tailgate reverse camera to assist repair	S	400.00 N N X
Remove and replace rear inner trims, garnish and boards to assist repair	S	60.00 200.00 ✓
Remove and replace rear bumper reverse sensors to assist repair	S	60.00 70.00 ✓
Remove and replace exhaust silencer and gasket to assist repair	S	400.00 N N X

Survey
23/8/2021

Resurvey

Total: S 14,132.64 20,605.15

1515 hrs
T. G. in line

Lump Sum repair
Repair days 14

Parts 7998.39
S N 550.80
Labour 2320.00
10,868.39
2173.68
8694.71

LS 8,700 ✓

T. G. in line
4/11/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTO PTE LTD

@ KAKI BUKIT #01-49 SINGAPORE 415875

14457

+65 64524584

eg No: 201929175W

Qty Supplementary

Vehicle No:
Model and make:

SMK8659K
Honda Vezel

1 Rear RH fender

\$ 693.33 884.40

1 Rear LH fender

\$ 693.33 884.04

} DPV ✓

\$ 1,768.44

-20% \$ 353.69

\$ 1,414.75

Qty Special Nett

1 Rear RH fender joint sealant

\$ 20.00 70.00

1 Rear LH fender joint sealant

\$ 20.00 70.00

} NEC ✓

Labour and painting

Cut/weld rear both fenders and panel beating affected areas

* \$ ~~400.00~~ 1,000.00

✓ NNX

Spray painting rear both fenders and all affected areas

* \$ ~~100.00~~ 800.00

✓ NNX

Remove and reinstall roof lining, seats and floor mat to assist repair

\$ 300.00

NNX

Total: \$ 3,654.75

Resurvey

27/8/2021

1955 hrs

Stream in

charged under labour & paintworks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To install damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- For illegal modifications is allowed
- Supplementary charges must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

AUTO PTE LTD

@ KAKI BUKIT #01-49 SINGAPORE 415875

14457

+65 64524584

eg No: 201929175W

Qty	Supplementary	Vehicle No: Model and make:	SMK8659K Honda Vezel
1	Rear compartment panel	S	✓ 662.20 DPV
1	Rear compartment panel cross member no:1	S	180.00 NSX
1	Rear compartment panel cross member no:2	S	280.00
		S	1,122.20
		-20% S	224.44
		S	897.76

Qty Special Nett

1	Rear compartment panel joint sealant	S	40.00	70.00 NEC ✓
---	--------------------------------------	---	-------	-------------

Labour and painting

Cut / weld rear compartment panel and affected areas	S	800.00	} NNX
Re-spray painting rear compartment panel and all joint areas	S	800.00	
Remove and reinstall rear seats and floor mat to assist repair	S	250.00	

Total: S 2,817.76

Resurvey
27/8/2021
1455 hrs
Renee M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer