

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0671/2021/JT 26-Aug-21 CHANG 1 of 1 SMA 4427 S AUDI A5 SB 2.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND RENEW WIRE HARNESS CONNECTOR. S/N	\$ 280.00	✓
Parts			
1	WIRE CONNETOR <i>changed</i>	\$ 9.00	✓ 6.88
2	WIRE CONNETOR	\$ 8.00	✓ 5.92
3	HEADLIGHT WASHER BRACKET - LH <i>changed</i>	\$ 15.00	✓ 11.76
GRAND TOTAL		\$ 312.00	

Adrian Ling
 26/08/21
[Signature]

For Premium Automobiles Pte Ltd



Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

4427

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 4427 S - FRONTAL

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING ATD	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	500
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COLLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$ 1,700.00	✓
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAYING OF BOTH FRONT DOORS.	S/N \$ 560.00	✓
5	TO RENEW ENGINE MAGNET AND OTHER ENGINE COMPONENTS.	S/N \$ 480.00	X
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 6,400.00	1500 (Without lock carrier) 2750 (With lock carrier)
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH FRONT DOORS.	\$ 6,000.00	3300 + 160 + 200
TOTAL LABOUR CHARGES - FRONT		\$ 16,420.00	3500 3460 (inclusive of charges)

Car-in

25/8/21

wip= 40321.

PREMIUM AUTOMOBILES

KIAM



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

HIG - Advan
75 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER Distorted.	1	\$ 2,251.00	✓
2	FRONT BUMPER FIXING PARTS new	1	\$ 407.00	+
3	FRONT BUMPER SECURING STRIP new	1	\$ 72.00	+
4	FRONT BUMPER GRILLE CENTER new	1	\$ 196.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE new	1	\$ 228.00	x
6	FRONT BUMPER AIR GUIDE - LH / RH ?	2	\$ 126.00	?
7	RADIATOR GRILLE Could.	1	\$ 2,326.00	✓
8	RADIATOR GRILLE SENSOR SUPPORT - LH / RH Dmgd	2	\$ 102.00	✓
9	RADIATOR GRILLE COVER - UPPER Could.	1	\$ 189.00	✓
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH new	2	\$ 948.00	+
11	FRONT BUMPER FOAM FILLER PIECE Could	1	\$ 124.00	✓
12	FRONT BUMPER REINFORCEMENT BEAM Distorted	1	\$ 845.00	✓
13	FRONT BUMPER BRACKET LH / RH ?	2	\$ 428.00	?
14	FRONT BUMPER GUIDE SECTION - LH / RH new	2	\$ 72.00	+
15	FRONT BUMPER TOP COVER Distorted	1	\$ 127.00	✓
16	"CAUTION" STICKER ?	1	\$ 14.00	✓
17	"A/C" STICKER new	1	\$ 8.00	✓
18	FRONT LOCK CARRIER UPPER BRACKET Could	1	\$ 137.00	✓
19	FRONT LOCK CARRIER LOWER BRACKET (LH) (RH) new	2	\$ 58.00	✓
20	HORN LH / RH ?	2	\$ 252.00	?
SUB TOTAL SPARE PARTS			\$ 8,910.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN BRACKET -LH / RH ?	2	\$ 58.00	?
22	FRONT PARKING AID SENSOR - INNER ?	2	TBC	?
23	FRONT PARKING AID SENSOR SEAL RING - INNER?	1	\$ 510.00	?
24	FRONT FENDER - LH / RH LH Repair, RH Buckled	2	\$ 2,120.00	1060
25	FRONT FENDER ATTACHMENT PARTS - LH / RH	2	\$ 53.00	+
26	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 148.00	+
27	FRONT FENDER BRACKET - LH / RH	2	\$ 70.00	+
28	FRONT FENDER BRACE - LH (RH) RH Bent	2	\$ 236.00	118.
29	FRONT FENDER CHROME TRIM - LH / RH new	2	\$ 328.00	✓
30	FRONT FENDER LONG FLEDGE COVER - LH / RH ?	2	\$ 72.00	?
31	FRONT FENDER SHORT FLEDGE COVER - LH (RH) RH new	2	\$ 32.00	16.
32	FRONT WHEEL HOUSING LINER - LH / RH new	2	\$ 550.00	+
33	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS new	1	\$ 169.00	+
34	FRONT WHEEL SPOILER - LH / RH new	1	\$ 146.00	+
35	BONNET Distorted	1	\$ 3,312.00	✓
36	BONNET ATTACHMENT PARTS new	1	\$ 123.00	+
37	BONNET HINGE (LH/RH) new Bent	2	\$ 838.00	✓
38	BONNET IMPACT PROTECTION - CENTER ?	1	\$ 28.00	✓
39	BONNET IMPACT PROTECTION - LH / RH new	2	\$ 56.00	✓
40	BONNET SOUND ABSORBER new per	1	\$ 343.00	+
SUB TOTAL SPARE PARTS			\$ 9,192.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
41	BONNET STRIKER - LH / RH ?	2	\$ 100.00	?	
42	BONNET LOCK - LH / RH ?	2	\$ 427.00	?	
43	BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	X	
44	BONNET BOWDEN CABLE COVER - CENTER } new	1	\$ 10.00	X	
45	BONNET BOWDEN CABLE - CENTER } Best	1	\$ 58.00	✓	
46	BONNET RELEASE LEVER } Dend	1	\$ 14.00	✓	
47	BONNET LOCK CABLE } new	1	\$ 74.00	X	
48	PLENUM CHAMBER COVER - CENTER new	1	\$ 97.00	+	
49	PLENUM CHAMBER COVER - LH / RH new	2	\$ 144.00	+	
50	LED HEADLIGHT - LH / RH covered	2	\$ 15,804.00	✓	
51	LED HEADLIGHT POWER MODULE - LH } new	1	\$ 758.00	+	
52	LED HEADLIGHT CONTROL UNIT - LH } new	1	\$ 751.00	+	
53	LED HEAT SINK - LH new	1	\$ 1,153.00	+	
54	LED HEADLIGHT HOSE - LH new	1	\$ 36.00	+	
55	LIFT CYLINDER - LH / RH } new	2	\$ 396.00	+	
56	LIFT CYLINDER HOSE } new	1	\$ 86.00	+	
57	LOCK CARRIER covered	1	\$ 1,016.00	✓	
58	LOCK CARRIER RADIATOR LOWER SUPPORT LH / RH MP	2	\$ 152.00	+	
59	A/C' CONDENSOR Dented	1	\$ 622.00	✓	
60	A/C' PRESSURE SENDER ?	1	\$ 186.00	?	
SUB TOTAL SPARE PARTS		:	\$ 21,942.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

photo

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	"A/C" REFRIGERENT LINE ?	1	\$	167.00	X
62	"A/C" REFRIGERENT LINE	1	\$	340.00	X
63	"A/C" REFRIGERENT LINE	1	\$	248.00	X
64	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$	19.00	✓
65	CHARGE AIR COOLER	1	\$	587.00	X
66	CHARGE AIR COOLER PRESSURE HOSE	1	\$	357.00	X
67	CHARGE AIR COOLER PRESSURE PIPE	1	\$	427.00	X
68	RADIATOR	1	\$	904.00	✓
69	RADIATOR UPPER SECURING PIN	2	\$	5.00	✓
70	RADIATOR LOWER SUPPOER RUBBER BUSH	2	\$	25.00	?
71	RADIATOR COOLANT	6	\$	142.00	✓
72	RADIATOR FAN RING	1	\$	267.00	X
73	RADIATOR FAN WITH CONTROL UNIT	1	\$	2,318.00	X
74	RADIATOR AIR DUCT - LH / RH	2	\$	64.00	✓
75	RADIATOR AIR DUCT - LH / RH	2	\$	32.00	✓
76	RADIATOR AIR DUCT - UPPER	1	\$	16.00	?
77	RADIATOR AIR DUCT - LOWER	1	\$	22.00	?
78	ENGINE AIR FILTER	1	\$	386.00	X
79	AIR INTAKE DUCT	1	\$	22.00	✓
80	AIR INTAKE GUIDE - RH	1	\$	53.00	✓
SUB TOTAL SPARE PARTS			:	\$ 6,401.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
81	AIR INTAKE AIR FLOW SENSOR	1	\$ 567.00	X	
82	AIR INTAKE HOSE	1	\$ 95.00	X	
83	AIR INTAKE HOSE COVER	1	\$ 240.00	X	
84	ENGINE CAM MAGNET	1	\$ 169.00	X	
85	TUBE FOR OIL DIPSTICK	1	\$ 110.00	X	
86	COOLANT TOP HOSE WITH QUICK RELEASE COUPLING	1	\$ 71.00	+	
87	COOLANT HOSE WITH QUICK RELEASE COUPLING	1	\$ 31.00	+	
88	COOLANT PIPE	1	\$ 54.00	+	
89	COOLANT HOSE WITH QUICK RELEASE COUPLING	1	\$ 183.00	+	
90	FRONT DOOR CHROME TRIM - LH / RH	2	\$ 328.00	✓	
91	FRONT WINDOW CHROME SLOT SEAL - LH / RH	2	\$ 798.00	✓	
92	REAR BUMPER	1	\$ 2,504.00	✓	
93	REAR BUMPER FIXING PARTS	1	\$ 165.00	X	
94	REAR BUMPER SECURING STRIP	1	\$ 223.00	?	
95	REAR BUMPER CHROME TRIM	1	\$ 1,016.00	✓	
96	REAR BUMPER LIGHT REFLECTOR - LH / RH	2	\$ 82.00	X	
97	LED TAILLIGHT - LH / RH	2	\$ 2,038.00	X	
98	LED TAILLIGHT TRIM - LH / RH	2	\$ 60.00	+	
99	LED LISENCE PLATE LIGHT - LH / RH	2	\$ 202.00	+	
100	REAR BUMPER REINFORCEMENT BEAM	1	\$ 940.00	✓	
SUB TOTAL SPARE PARTS		:	\$ 9,876.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
101	REAR BUMPER SEAL <i>per</i>	2	\$ 28.00	✓	
102	REAR BUMPER GUIDE SECTION - LH / RH <i>Men.</i>	2	\$ 46.00	x	
103	REAR PARKING AID SENSOR - LH / RH ?	2	TBC	?	
104	REAR PARKING AID SENSOR SEAL RING ?	2	\$ 14.00	?	
105	REAR LID <i>Peris</i>	1	\$ 3,818.00	x	
106	REAR LID HINGE LH / RH	2	\$ 458.00	x	
107	REAR LID ATTACHMENT PARTS <i>Men</i>	1	\$ 153.00	x	
108	REAR LID LOCK WITH MICRO SWITCH	1	\$ 248.00	x	
109	REAR LID LOCK COVER <i>Men</i>	1	\$ 13.00	x	
110	REAR LID GASKET	1	\$ 236.00	x	
111	REAR LID PUSH BUTTON <i>Men</i>	1	\$ 1,389.00	x	
112	REAR LID STRIKER PLATE	1	\$ 66.00	x	
113	REAR LID PACKING ADHESIVE <i>Men</i>	1	\$ 19.00	✓	
114	"AUDI" EMBLEM <i>per</i>	1	\$ 156.00	✓	
115	"A5" EMBLEM	1	\$ 99.00	✓	
116	"TFSI" EMBLEM	1	\$ 99.00	✓	
117	REAR WINDSCREEN	1	\$ 1,168.00	x	
118	REAR WINDSCREEN PRIMER <i>Men</i>	1	\$ 20.00	x	
119	ADDITIONAL BRAKE LIGHT	1	\$ 576.00	x	
120	REAR CROSS PANEL <i>Peris</i>	1	\$ 356.00	x	
SUB TOTAL SPARE PARTS			\$ 8,962.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.