

# PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Supplementary Estimate

*Xiao Chen*

GST Reg No. 19-9902271-W

<b>AIG Asia Pacific Insurance Pte Ltd</b> 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		<b>Estimate No.</b> <b>Date</b> <b>Service Advisor</b> <b>Pages</b> <b>Regn No</b> <b>Model No</b>	PA/OD/0671/2021/JT 26-Aug-21 CHANG 1 of 1 SMA 4427 S AUDI A5 SB 2.0 TFSI
Quantity	Description	Unit Price	Amount
<b>Labours</b>			
1	TO REMOVE AND RENEW WIRE HARNESS CONNECTOR. S/N	\$ 280.00	✓
<b>Parts</b>			
1	WIRE CONNETOR <i>found</i>	\$ 9.00	✓
2	WIRE CONNETOR	\$ 8.00	✓
3	HEADLIGHT WASHER BRACKET - LH <i>found</i>	\$ 15.00	✓
<b>GRAND TOTAL</b>		<b>\$ 312.00</b>	

For Premium Automobiles Pte Ltd

*Adrian Ling*  
 26/08/21  
*[Signature]*



Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699  
 TEL: 6366 2323 FAX: 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

4427

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 4427 S - FRONTAL**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	500
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COLLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$ 1,700.00	✓
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAYING OF BOTH FRONT DOORS.	S/N \$ 560.00	✓
5	TO RENEW ENGINE MAGNET AND OTHER ENGINE COMPONENTS.	S/N \$ 480.00	X
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 6,400.00	1500 (Without lock carrier) 2750 (With Lock-Carrier)
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH FRONT DOORS.	\$ 6,000.00	3300 + 160 + 200
<b>TOTAL LABOUR CHARGES - FRONT</b>		<b>: \$ 16,420.00</b>	<del>3500</del> 3460 (inclusive of Hinges)

Car-in

25/8/21

wip: 40321.

PREMIUM AUTOMOBILES

Kiam



55 UBI ROAD 1, SINGAPORE 408699  
TEL: 6366 2323 FAX: 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AGI - Advan

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

75 days

S/N	PARTS DESCRIPTION	QTY	S/NETT	DAMAGED PARTS & PRICES	REMARKS
1	FRONT BUMPER Distorted	1	S	2,251.00	✓
2	FRONT BUMPER FIXING PARTS new	1	S	407.00	+
3	FRONT BUMPER SECURING STRIP new	1	S	72.00	+
4	FRONT BUMPER GRILLE CENTER new	1	S	196.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE new	1	S	228.00	x
6	FRONT BUMPER AIR GUIDE - LH / RH ?	2	S	126.00	?
7	RADIATOR GRILLE could	1	S	2,326.00	✓
8	RADIATOR GRILLE SENSOR SUPPORT - LH / RH Dented	2	S	102.00	✓
9	RADIATOR GRILLE COVER - UPPER could	1	S	189.00	-
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH new	2	S	948.00	+
11	FRONT BUMPER FOAM FILLER PIECE could	1	S	124.00	✓
12	FRONT BUMPER REINFORCEMENT BEAM Dented	1	S	845.00	✓
13	FRONT BUMPER BRACKET LH / RH ?	2	S	428.00	?
14	FRONT BUMPER GUIDE SECTION - LH / RH new	2	S	72.00	+
15	FRONT BUMPER TOP COVER Distorted	1	S	127.00	✓
16	"CAUTION" STICKER ?	1	S	14.00	✓
17	"A/C" STICKER new	1	S	8.00	✓
18	FRONT LOCK CARRIER UPPER BRACKET could	1	S	137.00	✓
19	FRONT LOCK CARRIER LOWER BRACKET (LH) (RH) new	2	S	58.00	✓
20	HORN LH / RH ?	2	S	252.00	?
<b>SUB TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$ 8,910.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN BRACKET -LH / RH ?	2	\$ 58.00 ?	
22	FRONT PARKING AID SENSOR - INNER ?	2	TBC ?	
23	FRONT PARKING AID SENSOR SEAL RING - INNER?	1	\$ 510.00 ?	
24	FRONT FENDER - LH / RH LH Repair, RH Buckled	2	\$ 2,120.00 1060	
25	FRONT FENDER ATTACHMENT PARTS - LH / RH ?	2	\$ 53.00 +	
26	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 148.00 +	
27	FRONT FENDER BRACKET - LH / RH	2	\$ 70.00 +	
28	FRONT FENDER BRACE - LH (RH) RH Best	2	\$ 236.00 + 118.	
29	FRONT FENDER CHROME TRIM - LH / RH new	2	\$ 328.00	
30	FRONT FENDER LONG FLEDGE COVER - LH / RH ?	2	\$ 72.00 ?	
31	FRONT FENDER SHORT FLEDGE COVER - LH (RH) RH new	2	\$ 32.00 16.	
32	FRONT WHEEL HOUSING LINER - LH / RH new	2	\$ 550.00 +	
33	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS new	1	\$ 169.00 +	
34	FRONT WHEEL SPOILER - LH / RH new	1	\$ 146.00 +	
35	BONNET Distorted	1	\$ 3,312.00 ✓	
36	BONNET ATTACHMENT PARTS new	1	\$ 123.00 +	
37	BONNET HINGE (LH, RH) new Best	2	\$ 838.00 ✓	
38	BONNET IMPACT PROTECTION - CENTER ?	1	\$ 28.00 ✓	
39	BONNET IMPACT PROTECTION - LH / RH new	2	\$ 56.00 ✓	
40	BONNET SOUND ABSORBER new	1	\$ 343.00 +	
<b>SUB TOTAL SPARE PARTS</b>			<b>\$ 9,192.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	BONNET STRIKER - LH / RH ?	2	\$ 100.00	?
42	BONNET LOCK - LH / RH ?	2	\$ 427.00	?
43	BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	X
44	BONNET BOWDEN CABLE COVER - CENTER } new	1	\$ 10.00	X
45	BONNET BOWDEN CABLE - CENTER } Best	1	\$ 58.00	✓
46	BONNET RELEASE LEVER } Dend	1	\$ 14.00	✓
47	BONNET LOCK CABLE } new	1	\$ 74.00	X
48	PLENUM CHAMBER COVER - CENTER new	1	\$ 97.00	+
49	PLENUM CHAMBER COVER - LH / RH new	2	\$ 144.00	+
50	LED HEADLIGHT - LH / RH covered	2	\$ 15,804.00	✓
51	LED HEADLIGHT POWER MODULE - LH } new	1	\$ 758.00	+
52	LED HEADLIGHT CONTROL UNIT - LH } new	1	\$ 751.00	+
53	LED HEAT SINK - LH new	1	\$ 1,153.00	+
54	LED HEADLIGHT HOSE - LH new	1	\$ 36.00	+
55	LIFT CYLINDER - LH / RH } new	2	\$ 396.00	+
56	LIFT CYLINDER HOSE } new	1	\$ 86.00	+
57	LOCK CARRIER covered	1	\$ 1,016.00	✓
58	LOCK CARRIER RADIATOR LOWER SUPPORT LH / RH } new	2	\$ 152.00	+
59	A/C CONDENSOR Dented	1	\$ 622.00	✓
60	A/C PRESSURE SENDER ?	1	\$ 186.00	?
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 21,942.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

photo.

**PREMIUM AUTOMOBILES**



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
61	"A/C" REFRIGERENT LINE	1	\$	167.00	+
62	"A/C" REFRIGERENT LINE	1	\$	340.00	+
63	"A/C" REFRIGERENT LINE	1	\$	248.00	+
64	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$	19.00	✓
65	CHARGE AIR COOLER	1	\$	587.00	+
66	CHARGE AIR COOLER PRESSURE HOSE	1	\$	357.00	+
67	CHARGE AIR COOLER PRESSURE PIPE	1	\$	427.00	+
68	RADIATOR	1	\$	904.00	✓
69	RADIATOR UPPER SECURING PIN	2	\$	5.00	✓
70	RADIATOR LOWER SUPPOER RUBBER BUSH	2	\$	25.00	?
71	RADIATOR COOLANT	6	\$	142.00	✓
72	RADIATOR FAN RING	1	\$	267.00	x
73	RADIATOR FAN WITH CONTROL UNIT	1	\$	2,318.00	+
74	RADIATOR AIR DUCT - LH / RH	2	\$	64.00	✓
75	RADIATOR AIR DUCT - LH / RH	2	\$	32.00	✓
76	RADIATOR AIR DUCT - UPPER	1	\$	16.00	?
77	RADIATOR AIR DUCT - LOWER	1	\$	22.00	?
78	ENGINE AIR FILTER	1	\$	386.00	x
79	AIR INTAKE DUCT	1	\$	22.00	✓
80	AIR INTAKE GUIDE - RH	1	\$	53.00	✓
<b>SUB TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$ 6,401.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
81	AIR INTAKE AIR FLOW SENSOR	1	\$	567.00	f
82	AIR INTAKE HOSE	1	\$	95.00	f
83	AIR INTAKE HOSE COVER	1	\$	240.00	x
84	ENGINE CAM MAGNET	1	\$	169.00	x
85	TUBE FOR OIL DIPSTICK	1	\$	110.00	x
86	COOLANT TOP HOSE WITH QUICK RELEASE COUPLING	1	\$	71.00	+
87	COOLANT HOSE WITH QUICK RELEASE COUPLING	1	\$	31.00	+
88	COOLANT PIPE	1	\$	54.00	+
89	COOLANT HOSE WITH QUICK RELEASE COUPLING	1	\$	183.00	+
90	FRONT DOOR CHROME TRIM - LH / RH	2	\$	328.00	✓
91	FRONT WINDOW CHROME SLOT SEAL - LH / RH	2	\$	798.00	✓
92	REAR BUMPER	1	\$	2,504.00	✓
93	REAR BUMPER FIXING PARTS	1	\$	165.00	x
94	REAR BUMPER SECURING STRIP	1	\$	223.00	?
95	REAR BUMPER CHROME TRIM	1	\$	1,016.00	✓
96	REAR BUMPER LIGHT REFLECTOR - LH / RH	2	\$	82.00	x
97	LED TAILLIGHT - LH / RH	2	\$	2,038.00	+
98	LED TAILLIGHT TRIM - LH / RH	2	\$	60.00	+
99	LED LISENCE PLATE LIGHT - LH / RH	2	\$	202.00	+
100	REAR BUMPER REINFORCEMENT BEAM	1	\$	940.00	✓
<b>SUB TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$ 9,876.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
101	REAR BUMPER SEAL <i>per</i>	2	\$	28.00	✓
102	REAR BUMPER GUIDE SECTION - LH / RH <i>Me n.</i>	2	\$	46.00	✗
103	REAR PARKING AID SENSOR - LH / RH ?	2		TBC	?
104	REAR PARKING AID SENSOR SEAL RING ?	2	\$	14.00	?
105	REAR LID <i>Regr</i>	1	\$	3,818.00	✗
106	REAR LID HINGE LH / RH	2	\$	458.00	+
107	REAR LID ATTACHMENT PARTS <i>per</i>	1	\$	153.00	✗
108	REAR LID LOCK WITH MICRO SWITCH	1	\$	248.00	✗
109	REAR LID LOCK COVER <i>per</i>	1	\$	13.00	✗
110	REAR LID GASKET	1	\$	236.00	✗
111	REAR LID PUSH BUTTON <i>per</i>	1	\$	1,389.00	✗
112	REAR LID STRIKER PLATE	1	\$	66.00	✗
113	REAR LID PACKING ADHESIVE <i>per</i>	1	\$	19.00	✓
114	"AUDI" EMBLEM <i>per</i>	1	\$	156.00	✓
115	"A5" EMBLEM <i>per</i>	1	\$	99.00	✓
116	"TFSI" EMBLEM <i>per</i>	1	\$	99.00	✓
117	REAR WINDSCREEN <i>per</i>	1	\$	1,168.00	+
118	REAR WINDSCREEN PRIMER <i>per</i>	1	\$	20.00	✗
119	ADDITIONAL BRAKE LIGHT <i>per</i>	1	\$	576.00	✗
120	REAR CROSS PANEL <i>Regr</i>	1	\$	356.00	✗
<b>SUB TOTAL SPARE PARTS</b>			<b>:</b>	<b>\$ 8,962.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.