



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0671/2021/JT
DATE : 19-Aug-21
WIP : 40321

Xiao Chan.

\$41587.04

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY 19/8/2021

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LIM THOU YEE
ADDRESS : 10 FLORA DRIVE #04-08
FERRARIA DRIVE
SINGAPORE 506942
TELEPHONE : HP +65 98787325
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800052485-03
VEHICLE NO : SMA ⁴⁴⁷¹~~4472~~S
MODEL CODE : A5 SB 2.0 TFSI
MODEL YEAR : 7/6/2018
ENGINE NO : CVK 061652
CHASSIS NO : WAUZZZF54JA099662
MILEAGE :
DATE IN :
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Aug-21
PLACE OF ACCIDENT : ALONG CTE AFTER ANG MO KIO
AVE 1 TOWARDS CITY



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 4472 S - FRONTAL

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING LTD	S/N \$ 480.00	✓✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	500 ✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COLLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$ 1,700.00	✓✓
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAYING OF BOTH FRONT DOORS.	S/N \$ 560.00	✓✓
5	TO RENEW ENGINE MAGNET AND OTHER ENGINE COMPONENTS.	S/N \$ 480.00	X
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 6,400.00	3000 1500 (Without lock carrier) 2750 (With lock carrier)
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS AND BOTH FRONT DOORS.	\$ 6,000.00	3460 3300 + 160 dodge
TOTAL LABOUR CHARGES - FRONT		\$ 16,420.00	= 3460



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 4472 S - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	X.
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID.	S/N \$	480.00	X
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	X
5	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	X
6	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND REPAIR WHERE NECESSARY	S/N \$	480.00	X
7	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. RE-ORGANIZE CRASH MANGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED ✓	\$	4,800.00	750 ✓
8	TO RESPRAY REAR BUMPER, REAR END PANELLING, SPARE WHEEL HOUSING, REAR LID AND HINGES ✓	\$	4,000.00	1100 ✓
9	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	S/N \$	280.00	X
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	✓✓
TOTAL LABOUR CHARGES - REAR		:	\$ 11,664.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$ 2,251.00 ✓	1800.80
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 407.00 +	
3	FRONT BUMPER SECURING STRIP <i>new</i>	1	\$ 72.00 +	
4	FRONT BUMPER GRILLE CENTER <i>new</i>	1	\$ 196.00 +	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 228.00 +	
6	FRONT BUMPER AIR GUIDE - LH / RH <i>Not Nec</i>	2	\$ 126.00 ? X	
7	RADIATOR GRILLE <i>could</i>	1	\$ 2,326.00 ✓	1860.80
8	RADIATOR GRILLE SENSOR SUPPORT - LH / RH <i>new</i>	2	\$ 102.00 ✓	81.60
9	RADIATOR GRILLE COVER - UPPER <i>could</i>	1	\$ 189.00 ✓	150.80
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 948.00 +	
11	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	1	\$ 124.00 ✓	99.20
12	FRONT BUMPER REINFORCEMENT BEAM <i>Dented</i>	1	\$ 845.00 ?	675.60 ✓
13	FRONT BUMPER BRACKET LH / RH <i>Not Nec</i>	2	\$ 428.00 ? X	
14	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 72.00 +	
15	FRONT BUMPER TOP COVER <i>Distorted</i>	1	\$ 127.00 ✓	101.60
16	"CAUTION" STICKER <i>new</i>	1	\$ 14.00 ✓	10.88
17	"A/C" STICKER <i>new</i>	1	\$ 8.00 ✓	5.68
18	FRONT LOCK CARRIER UPPER BRACKET <i>cracked</i>	1	\$ 137.00 ?	109.60 ✓
19	FRONT LOCK CARRIER LOWER BRACKET - LH / RH <i>new</i>	2	\$ 58.00 ?	44.96 ✓
20	HORN LH / RH <i>Not Nec</i>	2	\$ 252.00 ? X	
SUB TOTAL SPARE PARTS		:	\$ 8,910.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	HORN BRACKET -LH / RH <i>Noe Nec</i>	2	\$ 58.00	?	X
22	FRONT PARKING AID SENSOR - INNER <i>Ne Nec</i>	2	TBC	?	X
23	FRONT PARKING AID SENSOR SEAL RING - INNER <i>Noe Nec</i>	1	\$ 510.00	?	X
24	FRONT FENDER - LH / RH <i>LH Repair, RH Buckled</i>	2	\$ 2,120.00	1060	848
25	FRONT FENDER ATTACHMENT PARTS - LH / RH	2	\$ 53.00	+	
26	FRONT FENDER CLOSING ELEMENT - LH / RH	2	\$ 148.00	+	
27	FRONT FENDER BRACKET - LH / RH	2	\$ 70.00	+	
28	FRONT FENDER BRACE - LH / RH <i>RH But</i>	2	\$ 236.00	+	94.40 ✓
29	FRONT FENDER CHROME TRIM - LH / RH <i>Neu</i>	2	\$ 328.00	✓	261.60
30	FRONT FENDER LONG FLEDGE COVER - LH / RH <i>Ne Neu</i>	2	\$ 72.00	?	X
31	FRONT FENDER SHORT FLEDGE COVER - LH / RH <i>RH Nec</i>	2	\$ 32.00	?	12.24 ✓
32	FRONT WHEEL HOUSING LINER - LH / RH <i>Neu</i>	2	\$ 550.00	+	
33	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Neu</i>	1	\$ 169.00	+	
34	FRONT WHEEL SPOILER - LH / RH <i>Neu</i>	1	\$ 146.00	+	
35	BONNET <i>Distorted</i>	1	\$ 3,312.00	✓	2649.60
36	BONNET ATTACHMENT PARTS <i>Neu</i>	1	\$ 123.00	+	
37	BONNET HINGE - LH / RH <i>Neu</i>	2	\$ 838.00	+	670.40 ✓
38	BONNET IMPACT PROTECTION - CENTER	1	\$ 28.00	✓	21.84
39	BONNET IMPACT PROTECTION - LH / RH <i>Neu</i>	2	\$ 56.00	✓	43.84
40	BONNET SOUND ABSORBER <i>Neu</i>	1	\$ 343.00	+	
SUBTOTAL SPARE PARTS		:	\$ 9,192.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET STRIKER - LH / RH <i>new</i>	2	\$ 100.00	? X
42	BONNET LOCK - LH / RH <i>new</i>	2	\$ 427.00	? X
43	BONNET BOWDEN CABLE - CENTER	1	\$ 58.00	X
44	BONNET BOWDEN CABLE COVER - CENTER <i>new</i>	1	\$ 10.00	X
45	BONNET BOWDEN CABLE - CENTER <i>Best</i>	1	\$ 58.00	58 46 ✓
46	BONNET RELEASE LEVER <i>Damaged</i>	1	\$ 14.00	14 10.48 ✓
47	BONNET LOCK CABLE <i>new</i>	1	\$ 74.00	+
48	PLENUM CHAMBER COVER - CENTER <i>new</i>	1	\$ 97.00	X
49	PLENUM CHAMBER COVER - LH / RH <i>new</i>	2	\$ 144.00	+
50	LED HEADLIGHT - LH / RH <i>included</i>	2	\$ 15,804.00	✓ 12643.20
51	LED HEADLIGHT POWER MODULE - LH <i>new</i>	1	\$ 758.00	+
52	LED HEADLIGHT CONTROL UNIT - LH <i>new</i>	1	\$ 751.00	+
53	LED HEAT SINK - LH <i>new</i>	1	\$ 1,153.00	+
54	LED HEADLIGHT HOSE - LH <i>new</i>	1	\$ 36.00	+
55	LIFT CYLINDER - LH / RH <i>new</i>	2	\$ 396.00	+
56	LIFT CYLINDER HOSE <i>new</i>	1	\$ 86.00	+
57	LOCK CARRIER <i>included</i>	1	\$ 1,016.00	✓ 812.80
58	LOCK CARRIER RADIATOR LOWER SUPPORT LH / RH <i>new</i>	2	\$ 152.00	+
59	A/C CONDENSOR <i>Dented</i>	1	\$ 622.00	✓ 497.60
60	A/C PRESSURE SENDER <i>new</i>	1	\$ 186.00	? X
SUB TOTAL SPARE PARTS		:	\$ 21,942.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

photo.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS	
61	"A/C" REFRIGERENT LINE	1	\$	167.00	X	
62	"A/C" REFRIGERENT LINE	1	\$	340.00	X	
63	"A/C" REFRIGERENT LINE	1	\$	248.00	X	
64	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$	19.00	? 14.56 ✓	
65	CHARGE AIR COOLER	1	\$	587.00	X	
66	CHARGE AIR COOLER PRESSURE HOSE	1	\$	357.00	X	
67	CHARGE AIR COOLER PRESSURE PIPE	1	\$	427.00	X	
68	RADIATOR	1	\$	904.00	? 722.80 ✓	
69	RADIATOR UPPER SECURING PIN	2	\$	5.00	? X	
70	RADIATOR LOWER SUPPOER RUBBER BUSH	2	\$	25.00	? X	
71	RADIATOR COOLANT	6	\$	142.00	? 113.28 ✓	
72	RADIATOR FAN RING	1	\$	267.00	X	
73	RADIATOR FAN WITH CONTROL UNIT	1	\$	2,318.00	X	
74	RADIATOR AIR DUCT - LH / RH	2	\$	64.00	? 49.52 ✓	
75	RADIATOR AIR DUCT - LH / RH	2	\$	32.00	? 25.60 ✓	
76	RADIATOR AIR DUCT - UPPER	1	\$	16.00	? X	
77	RADIATOR AIR DUCT - LOWER	1	\$	22.00	? 17.20 ✓	
78	ENGINE AIR FILTER	1	\$	386.00	X	
79	AIR INTAKE DUCT	1	\$	22.00	X	
80	AIR INTAKE GUIDE - RH	1	\$	53.00	? 42.40 ✓	
SUB TOTAL SPARE PARTS			:	\$ 6,401.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS
81	AIR INTAKE AIR FLOW SENSOR	1	\$ 567.00	f	
82	AIR INTAKE HOSE	1	\$ 95.00	f	
83	AIR INTAKE HOSE COVER	1	\$ 240.00	x	
84	ENGINE CAM MAGNET	1	\$ 169.00	x	
85	TUBE FOR OIL DIPSTICK	1	\$ 110.00	x	
86	COOLANT TOP HOSE WITH QUICK RELEASE COUPLING	1	\$ 71.00	+	
87	COOLANT HOSE WITH QUICK RELEASE COUPLING	1	\$ 31.00	+	
88	COOLANT PIPE	1	\$ 54.00	+	
89	COOLANT HOSE WITH QUICK RELEASE COUPLING	1	\$ 183.00	+	
90	FRONT DOOR CHROME TRIM - LH / RH	2	\$ 328.00	✓	261.60
91	FRONT WINDOW CHROME SLOT SEAL - LH / RH	2	\$ 798.00	✓	
92	REAR BUMPER	1	\$ 2,504.00	✓	2003.20
93	REAR BUMPER FIXING PARTS	1	\$ 165.00	x	
94	REAR BUMPER SECURING STRIP	1	\$ 223.00	? X	
95	REAR BUMPER CHROME TRIM	1	\$ 1,016.00	✓	812.80
96	REAR BUMPER LIGHT REFLECTOR - LH / RH	2	\$ 82.00	X	
97	LED TAILLIGHT - LH / RH	2	\$ 2,038.00	+	
98	LED TAILLIGHT TRIM - LH / RH	2	\$ 60.00	f	
99	LED LISENCE PLATE LIGHT - LH / RH	2	\$ 202.00	+	
100	REAR BUMPER REINFORCEMENT BEAM	1	\$ 940.00	?	850.40 ✓
SUB TOTAL SPARE PARTS		:	\$ 9,876.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS
101	REAR BUMPER SEAL <i>NEC</i>	2	S	28.00	? 22.40 ✓
102	REAR BUMPER GUIDE SECTION - LH / RH <i>NEC</i>	2	S	46.00	X
103	REAR PARKING AID SENSOR - LH / RH <i>NEC</i>	2		TBC	? X
104	REAR PARKING AID SENSOR SEAL RING <i>NEC</i>	2	S	14.00	? X
105	REAR LID <i>Regis</i>	1	S	3,818.00	X
106	REAR LID HINGE LH / RH <i>NEC</i>	2	S	458.00	X
107	REAR LID ATTACHMENT PARTS <i>NEC</i>	1	S	153.00	X
108	REAR LID LOCK WITH MICRO SWITCH	1	S	248.00	X
109	REAR LID LOCK COVER <i>NEC</i>	1	S	13.00	X
110	REAR LID GASKET <i>NEC</i>	1	S	236.00	X
111	REAR LID PUSH BUTTON <i>NEC</i>	1	S	1,389.00	X
112	REAR LID STRIKER PLATE <i>NEC</i>	1	S	66.00	X
113	REAR LID PACKING ADHESIVE <i>NEC</i>	1	S	19.00	✓ 14.88
114	"AUDI" EMBLEM <i>NEC</i>	1	S	156.00	✓ 124.40
115	"A5" EMBLEM <i>NEC</i>	1	S	99.00	✓ 79.04
116	"TFSI" EMBLEM <i>NEC</i>	1	S	99.00	✓ 79.04
117	REAR WINDSCREEN <i>NEC</i>	1	S	1,168.00	X
118	REAR WINDSCREEN PRIMER <i>NEC</i>	1	S	20.00	X
119	ADDITIONAL BRAKE LIGHT <i>NEC</i>	1	S	576.00	X
120	REAR CROSS PANEL <i>Regis</i>	1	S	356.00	X
SUB TOTAL SPARE PARTS			:	\$ 8,962.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 4427 D.

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
121	REAR CROSS PANEL REINFORCEMENT <i>Ryis</i>	1	\$	632.00	*
122	REAR CROSS PANEL TRIM <i>new</i>	1	\$	360.00	*
123	FRONT NO PLATE <i>Dented</i>	S/N	\$	60.00	✓
124	<i>Rear</i> FRONT NO PLATE <i>Dented</i>	S/N	\$	60.00	✓
125	REAR WINDSCREEN SEALANT <i>new</i>	S/N	\$	200.00	*
126	ARCYLIX SEALANT	S/N	\$	180.00	*
127	CAVITY WAX	S/N	\$	140.00	*
128	STONE CHIP	S/N	\$	180.00	*
129	METAL FILLER POWDER <i>new</i>	S/N	\$	280.00	*
130	SUNDRIES ?		\$	400.00	? 81.84 ✓
TOTAL SPARE PARTS (FRONT + REAR)		:	\$	67,775.00	
TOTAL LABOUR CHARGES (FRONT + REAR)		:	\$	28,084.00	
GRAND TOTAL		:	\$	95,859.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lij*
 SURVEYED DATE : *20/08/21*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *Not Authorised, 12 Days (Without Lock Center) 15 Days (With Lock Center)*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT. *J.S.*

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT