

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0675/2021/JT
DATE : 19-Aug-21
WIP : 40490

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/8/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days - ok - Johnny Boo

28-Sep-21

OWNER'S NAME : MR MOHAMAD FIROZ BIN AMAN
ADDRESS : BLK 328 TAMPINES STREET 32
#04-366
SINGAPORE 520328
TELEPHONE : HP +65 98518457
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210003361
VEHICLE NO : **SMX4671G**
MODEL CODE : AUDI Q3 1.4 TFSI S
MODEL YEAR : 1/14/2021
ENGINE NO : CZD C22544
CHASSIS NO : WAUZZZF3XM1055975
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Aug-21
PLACE OF ACCIDENT : BLK 201E TAMPINES CARPARK
BEHIND FURNITURE SHOP

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 4671 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	S/N \$	400.00	\$ 280.00
2	TO DISMANTLE AND RENEW RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	\$ 500.00
3	TO RESPRAY RHS FRONT DOOR, DOOR COVER AND RHS WING MIRROR COVER.	\$	2,000.00	\$ 950.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	4,192.00	\$ 1,922.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4671 G

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT DOOR - RH	1	\$ 2,816.00	\$	2,252.80
2	FRONT DOOR OUTER SEAL - RH	1	\$ 166.00	\$	132.80
3	FRONT DOOR CATCH - RH	1	\$ 120.00		
4	FRONT DOOR COVER - RH	1	\$ 370.00	\$	296.00
5	FRONT DOOR DATA PLATE FOR TYRE PRESSURE	1	\$ 30.00		
6	FRONT WING MIRROR MOUNTING - RH	1	\$ 2,065.00		
7	FRONT WING MIRROR MOUNTING CAP - RH	1	\$ 191.00		
8	SUNDRIES		\$ 250.00		
TOTAL SPARE PARTS		:	\$ 6,008.00	\$	2,681.60
TOTAL LABOUR CHARGES		:	\$ 4,192.00	\$	1,922.00
GRAND TOTAL		:	\$ 10,200.00	\$	4,603.60

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-23/09/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT