

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Radiator Grille	Snapped	1409.00	1409.00
2	1	Front Bumper Moulding	Snapped	188.00	188.00
3	1	Front Bumper	Deformed	418.30	418.30
4	1	Front Bumper Absorber	Snapped	86.90	86.90
5	1	Front Bumper Moulding	Snapped	93.45	93.45
6	1	Front Bumper Moulding Upper	Snapped	188.00	188.00
7	2	Front Bumper Bracket Rh/Lh	Distorted	56.00	56.00
8	2	Headlamp Rh/Lh	Snapped	3987.30	3987.30
9	1	Front Fender Rh	Dented	490.70	490.70
10	1	Front Fender Garnish Rh	Missing	42.80	42.80
11	1	Front Fender Emblem-Blue Drive Rh	Necessary	26.60	26.60
12	2	Front Day Lamp Rh/Lh	Snapped	1285.00	1285.00
13	1	Radiator Grille Cover	Deformed	48.30	48.30
14	1	Headlamp Support Panel	Snapped	949.30	949.30
15	1	Radiator	Dented	510.50	510.50
16	1	Radiator Invertor	Dented	884.80	884.80
17	1	Radiator Blower	Snapped	576.00	576.00
18	1	A/C Condenser	Dented	663.60	663.60
19	1	A/C Liquid Tube	Dented	148.50	148.50
20	2	Active Flap	Deformed	712.00	712.00
21	1	Rear Bumper Moulding	Deformed	451.25	451.25
22	1	Rear Bumper Lower Moulding	Deformed	47.50	47.50
23	1	Smart Antenna	Snapped	40.50	40.50
Subtotal				: 13304.30	13304.30
Less 20 %				2660.86	2660.86
TOTAL				: 10643.44	10643.44

SPECIAL NETT ITEM

1	1	Front Number Plate <i>Frt</i>	Cracked	50.00	50.00
2	1	Rear Number Plate <i>Rear</i>	Cracked	50.00	50.00
TOTAL				: 100.00	100.00

TOTAL FOR SPARE PARTS : 10743.44 10743.44

SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Labour charges <i>Front - \$640</i>	1000.00	960.00
2	Spray painting charges <i>Rear - \$320</i> <i>Frt - \$400</i>	700.00	600.00
3	Wiring charges <i>frt</i> <i>Rear - \$200</i>	30.00	20.00
4	Tuff kote (waived)	30.00	0.00
5	Remove/ refix a/c condenser & refill gas <i>Frt</i>	120.00	100.00
TOTAL FOR LABOUR AND SPRAY PAINTING :		1880.00	1680.00
		1680	

Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS :	10743.44	10743.44
TOTAL FOR LABOUR AND SPRAY PAINTING :	1880.00	1680.00
TOTAL REPAIR COST :	12623.44	12423.44
		\$12,423.44
		5 days

Front - 3 days
Rear - 2 days

Repair cost fair and reasonable.