AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S:

TONG PAU ENG ANNA

97C UPPER THOMSON RD #08-10

Estimate No:

MC1902117

Date:

20 Aug 2021

SINGAPORE 574329

Policy No:

P10255209R01

Veh Reg No:

SMF7222U

ATTN:

Not Mailes Runny B& paint

Make/Model:

HYUNDAI ELANTRA

AD 1.6 GLS AT (AMS)

Your Ref No:

Third Party

81953.68

Claim Type: Accident Date:

Thank You

17/08/2021

Estimate Repair Cost to Vehicle No: SMF7222U

	Description	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
	SPARE PARTS 1782-30			
1	REAR DOOR RH	1 PC	1,878.30	
2	REAR DOOR HINGE TOP & LOWER	2 PC	91.80	
3	REAR DOOR CHECKER	1 PC	47.30	X
4	REAR DOOR POWER WINDOW MOTOR	1 PC	160.50	
5	REAR DOOR POWER WINDOW REGULATOR	1 PC	223.40	×
6	REAR DOOR INNER LOCK	1 PC	191.50	4
7	REAR DOOR RUBBER (AT DOOR)	1 PC	$\int_{105.80}$	X
8	REAR DOOR OUTER HANDLE	1 PC	n s 59.80	
9	REAR DOOR OUTER HANDLE SMALL COVER	1 PC	17.10	X
			2,775.50	
		Less 20%	555.10	2,220.40
	LABOUR			_
10	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	80.00	60L
11	TO DISMANTLE ALL DAMAGED PARTS. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	300.00	2001
12	TO SPRAY REAR DOOR RH	1 PC	300.00	2201
			680.00	680.00
		<u> </u>	Total	S\$ 2,900.40

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before after spray painting

TOTAL: SINGAPORE DOLLAR THE BEST SENSON OF THE SELVEN DRED AND THREE AND CENTS FORTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible that pany survey is on a willout Please basis

• No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Add GST @ 7% 203.03 Total Amount Payable S\$ 3,103.43

For AH LIM MOTOR COMPANY