




28	FRONT DOOR CHECKER RH <i>new</i>	1	\$	137.50	\$	137.50	+
29	FRONT DOOR OUTER HANDLE RH <i>Repair</i>	1	\$	153.70	\$	153.70	+
30	FRONT DOOR OUTER HANDLE SIDE COVER RH <i>Repair</i>	1	\$	40.00	\$	40.00	+
31	FRONT DOOR INNER LOCK RH <i>new</i>	1	\$	410.80	\$	410.80	+
32	FRONT DOOR FRIM WEATHERSTRIP RH <i>Repair</i>	1	\$	265.00	\$	265.00	+
33	FRONT DOOR LOWER RUBBER SEAL RH	1	\$	87.50	\$	87.50	+
34	FRONT DOOR CHANNEL RH	1	\$	86.70	\$	86.70	+
35	FRONT DOOR CHANNEL SEAL RH	1	\$	169.70	\$	169.70	+
36	FRONT DOOR REGULATOR MOTOR RH <i>Repair</i>	1	\$	453.20	\$	453.20	+
37	FRONT DOOR REGULATOR GEAR RH	1	\$	216.70	\$	216.70	+
38	FRONT DOOR INNER TRIM RH	1	\$	845.00	\$	845.00	+
39	SIDE SKIRT RH <i>Repair</i>	1	\$	980.00	\$	980.00	+
40	SIDE SKIRT RETAINER	6	\$	55.00	\$	330.00	+
41	REAR DOOR RH <i>Repair</i>	1	\$	899.50	\$	899.50	+
42	REAR DOOR RH INNER LOCK	1	\$	586.00	\$	586.00	+
43	REAR DOOR FRAME BLACK STCKER RH	2	\$	80.00	\$	160.00	+
44	REAR DOOR OUTER MOULDING RH	1	\$	198.00	\$	198.00	+
45	REAR DOOR WEATHERSTRIP RH	1	\$	223.80	\$	223.80	+
46	REAR DOOR LOWER RUBBER SEAL RH	1	\$	87.50	\$	87.50	+
47	REAR DOOR SIDE RUBBER SEAL RH	1	\$	98.10	\$	98.10	+

6053.30
4842.64
S.N: 120.

Subtotal : \$ 20,372.70
Less 20% \$ 4,074.54
Parts Total : \$ 16,298.16

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE	
1	FRONT BUMPER CLIPS SET <i>new</i>	1	\$ 50.00	\$ 50.00	30
2	FRONT FENDER INNER SHIELD CLIP <i>new</i>	1	\$ 40.00	\$ 40.00	30
3	FRONT FENDER SEALANT	1	\$ 40.00	\$ 40.00	+
4	FRONT GRILLE CLIPS SET	1	\$ 50.00	\$ 50.00	+
5	FRONT SUPPORT TOP GARNISH CLIPS SET	1	\$ 50.00	\$ 50.00	+
6	FRONT DOOR SEALANT	1	\$ 60.00	\$ 60.00	+
7	FRONT DOOR INNER PILLAR SEALANT	1	\$ 80.00	\$ 80.00	+
8	FRONT DOOR OUTER PILLAR SEALANT	1	\$ 80.00	\$ 80.00	+
9	FRONT DOOR INNER TRIM CLIP SET	1	\$ 50.00	\$ 50.00	+
10	REAR DOOR INNER TRIM CLIP	1	\$ 60.00	\$ 60.00	+
11	DOOR SUN VISOR SET <i>new</i>	1	\$ 600.00	\$ 600.00	80
12	DOOR SIDE SEAL <i>Repair</i>	1	\$ 400.00	\$ 400.00	+
13	SIDE SKIRT CLIP	1	\$ 60.00	\$ 60.00	+
14	WHEEL SPORT RIM <i>new</i>	1	\$ 1,200.00	\$ 1,200.00	400
15	TYRE	1	\$ 400.00	\$ 400.00	+
				\$ 3,220.00	

LABOUR	
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00 600
TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00 800
TO PERFORM LIGHTING & WIRING CHECK	\$ 150.00 30
TO APPLY ANTI-RUST & TUFF KOTE	\$ 250.00 60
REMOVE AND INSTALL FRONT DOOR PART	\$ 180.00 80 1570
REMOVE AND INSTALL REAR DOOR PART	\$ 180.00 +
REMOVE AND INSTALL CARPET, SEAT AND INTERIOR	\$ 450.00 +
REMOVE AND INSTALL FRONT UNDER CARRIAGE	\$ 650.00 +
TO CHECK FOUR WHEEL ALIGNMENT	\$ 150.00 +
ABS SYSTEM LIGHT RESET	\$ 350.00 +
LABOUR TOTAL	
	\$ 5,760.00

Total Parts Cost	\$ 19,518.16
Total Labour Cost	\$ 5,760.00
Total Repair Cost	\$ 25,278.16

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

Adrian L
 2/8 05 Days.

Colled: 7072-64

2/8 5.6k ✓

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: