

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008806/RQCN2**Date:** 23/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00051292101
Claimant Vehicle No :	SMR3855G	Insured Vehicle No :	YL3958H
Date of Loss:	19/08/2021	Nature of Claim:	TP
		Claim No:	SNM21D204655/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR3855G	Engine No:	2ZR0E79803
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDZS3EUX0J052454
Reg. Date:	31/12/2019 (Man. Year: 2019)	Odometer:	65539 km
Colour:	Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R15	Rear Tyre Size:	205/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,251.50	3,952.50	16,299.00	80.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,440.00	2,330.00	2,110.00	47.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	24,691.50	6,282.50	18,409.00	74.56
Approved Total (Overridden) (\$\$)		4,800.00		
(\$\$)	24,691.50	4,800.00	19,891.50	80.56
+ GST 7.00/7.00% (\$\$)	1,728.41	336.00	1,392.41	80.56
Nett Amount (\$\$)	26,419.91	5,136.00	21,283.91	80.56

INSPECTION

Date of Assignment:	23/08/2021	
Date Inspected:	23/08/2021 Inspected At:	My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ) 60 Jalan Lam Huat, Carros Centre #05-21 Singapore 737869
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2022)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR3855G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Scratched	879.00 FL	*557.00 FL
2	2		*FRT BUMPER SIDE RETAINER	Not Necessary	90.00 FL	*- FL
3	2		*FRT BUMPER BRACKET	Not Necessary	104.00 FL	*- FL
4	1		*FRT BUMPER LOWER	Not Necessary	612.00 FL	*- FL
5	2		*FRT BUMPER SIDE LAMP	Not Necessary	224.00 FL	*- FL
6	1		*FRT BUMPER SIDE COVER RH	Not Necessary	124.00 FL	*- FL
7	1		*FRT HEADLAMP	Scratched (1 Pc only)	4,514.00 FL	*2,257.00 FL
			(2 Pcs)			
8	2		*FRT HEADLAMP LOWER BRACKET	Not Necessary	150.00 FL	*- FL
9	1		*FRONT FENDER	Bent (1 Pc only)	1,042.00 FL	*521.00 FL
			(2 Pcs)			
10	2		*FRONT FENDER COWLING	Not Necessary	318.00 FL	*- FL
11	2		*FRONT FENDER EMBLEM HYBRID	Necessary	124.00 FL	*124.00 FL
12	1		*WIPER WASHER TANK C/W MOTOR	Deformed	325.00 FL	*199.00 FL
13	1		*SIDE MIRROR RH	Not Necessary	681.00 FL	*- FL
14	2		*FRT SHOCK ABSORBER	Not Necessary	904.00 FL	*- FL
15	1		*FRT LOWER ARM	Bent (1 Pc only)	1,162.00 FL	*288.00 FL
			(2 Pcs)			
16	1		*FRT KNUCKLE ARM	Bent (1 Pc only)	1,164.00 FL	*282.00 FL
			(2 Pcs)			
17	1		*FRT WHEEL BEARING	Necessary (1 Pc only)	396.00 FL	*162.00 FL
			(2 Pcs)			
18	2		*FRT TIE ROD	Not Necessary	424.00 FL	*- FL
19	2		*FRT TIE ROD END	Not Necessary	230.00 FL	*- FL
20	2		*FRT STABILIZER LINK	Not Necessary	418.00 FL	*- FL
21	1		*STEERING RACK AND PINION	Not Necessary	2,514.00 FL	*- FL
22	1		*DRIVE SHAFT RH	Not Necessary	1,211.00 FL	*- FL
23	1		*FRONT DOOR RH	Repair	1,125.00 FL	*- FL
24	2		*FRONT DOOR HINGES RH	Not Necessary	96.00 FL	*- FL
25	2		*SIDE SKIRTING	Repair	1,628.00 FL	*- FL
26	1		*REAR DOOR RH	Repair	1,125.00 FL	*- FL
27	1		*REAR FENDER RH	Repair	612.00 FL	*- FL
28	1		*REAR FENDER COWLING RH	Not Necessary	198.00 FL	*- FL
29	1		*REAR BUMPER RH	Not Necessary	798.00 FL	*- FL
30	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	45.00 FL	*- FL
31	1		*TAILLAMP RH	Not Necessary	525.00 FL	*- FL
32	1		*SET FRT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
33	1		*FRT FENDER INNERSHIELD CLIP SET RH	Necessary	50.00 FS	*30.00 FS
34	1		*FRT FENDER QUARTER GLASS SEALANT RH	Not Necessary	80.00 FS	*- FS
35	1		*SET SIDE SKIRTING CLIPS	Necessary	50.00 FS	*20.00 FS
36	1		*FRONT SPORT RIM	Scratched (1 Pc only)	1,600.00 FS	*350.00 FS
			(2 Pcs)			
37	1		*FRT TYRE (80%)	Punctured (1 Pc only)	500.00 FS	*200.00 FS
			(2 Pcs)			
38	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
39	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 26,192.00 5,050.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 25.00/25.00% (S\$)					5,940.50	1,097.50
Total Parts (S\$)					20,251.50	3,952.50
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	100.00	20.00
2	REMOVE AND REFIT BOTH FRONT UNDERCARRIAGE	New	600.00	150.00
3	WHEEL ALIGNMENT	New	100.00	60.00
4	R&R FRT FENDER QUARTER GLASS RH	New	120.00	0.00
5	REALIGN HEADLAMP	New	120.00	0.00
6	PANEL BEAT EFFECTED AREAS	New	1,600.00	800.00
7	SPRAY PAINT EFFECTED AREAS	New	1,800.00	1,300.00
Gross Labour Cost (\$\$)			4,440.00	2,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >