



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

TPAIG. KNAF W611MA5216397
Gailia.

Page No. 1

Vehicle No. SMF7790X KIA CERATO

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	REAR BOOTLID <i>Quelited.</i>		910.00	<i>850.</i>
2	REAR BOOTLID HINGE LH & RH @\$145.20 <i>new</i>		290.40	<i>+</i>
1	REAR BOOTLID LOGO <i>new</i>		81.00	<i>-</i>
1	REAR BOOTLID INNER LOCK <i>Dmd.</i>		124.30	<i>-</i>
1	REAR BOOTLID WEATHERSTRIP <i>new</i>		320.00	<i>182</i>
1	REAR BUMPER <i>Delmd</i>		895.00	<i>614</i>
2	REAR BUMPER SIDE RETAINER LH & RH @\$83.60 <i>new</i>		167.20	<i>-</i>
1	REAR BUMPER INNER SPONGE <i>could</i>		155.00	<i>-</i>
1	REAR BUMPER LOWER <i>Delmd</i>		115.00	<i>-</i>
1	REAR BUMPER REINFORCEMENT <i>could</i>		295.00	<i>-</i>
2	REAR BUMPER REINFORCEMENT BRACKET LH & RH @\$90.00 <i>new</i>		180.00	<i>3191.50</i>
1	REAR BUMPER TOP & LOWER BRACKET <i>new</i>		220.00	<i>410</i>
1	REAR END PANEL <i>Dented</i>		510.00	<i>2872.35</i>
1	REAR END PANEL TOP GARNISH <i>could</i>		120.00	<i>-</i>
1	REAR EXHAUST SILENCER <i>new</i>		980.00	<i>+</i>
1	REAR EXHAUST SILENCER MOULDING <i>new</i>		98.00	<i>+</i>
1	Rear Bumper Reflector RH <i>could</i>			
			5460.90	
less 10%			546.09	10%
			4914.81	
SPECIAL NETT ITEMS				
1 SET	REVERSE SENSOR <i>Damaged</i>		280.00	<i>200.</i>
1 SET	REAR CAR PLATE WITH HOLDER <i>could</i>		70.00	<i>50</i>
1 SET	REAR BUMPER CLIPS <i>new</i>		80.00	<i>30</i>
1	REAR END PANEL SEALANT <i>new</i>		100.00	<i>60</i>
1 SET	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		80.00	<i>10.</i>
Total Parts			5524.81	



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel: 6702 4282 Fax: 6702 4202

Page No. 2

Vehicle No. SMF7790X KIA CERATO

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	LABOUR		
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	1600.00	500.
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1400.00	500
3	To remove and refix wiring at damaged areas	100.00	30.
4	To perform anti rust treatment on affected areas	200.00	60
5	To remove and replace reverse sensors and check for proper functions	120.00	50
6	To remove and refix rear windscreen	100.00	✓
7	To remove rear bootlid mechanism	210.00	+
8	To conduct water seepage test	150.00	+
Labour Total :		3880.00	
TOTAL (PARTS & LABOUR):		9404.81	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
L/S 23/08/21.

05 Days.

Total: 4462.35

L/S: 3.5K

3.5K