

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21008813/EBS3Q2
Date: 15/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SMJ3708R	Insured Vehicle No :	SMR4285U
Date of Loss:	20/08/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003562

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ3708R		
Make & Model:	VOLKSWAGEN TOURAN, 1.4 TSI (A)	Engine No:	CZDA06088
Reg. Date:	28/02/2019 (Man. Year: 2019)	Chassis No:	WVGZZZ1TZKW034819
Colour:	Blue	Odometer:	40493 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,020.00	1,881.00	3,139.00	62.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,730.00	940.00	790.00	45.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,750.00	2,821.00	3,929.00	58.21
Approved Total (Overridden) (S\$)		2,250.00		

(S\$)	6,750.00	2,250.00	4,500.00	66.67
+ GST 7.00/7.00% (S\$)	472.50	157.50	315.00	66.67
Nett Amount (S\$)	7,222.50	2,407.50	4,815.00	66.67
+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)		321.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,735.95		

INSPECTION

Date of Assignment: 23/08/2021

Date Inspected: 24/08/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Automotive Repair Centre Pte Ltd (HQ)
 38 Woodlands Industrial Park E1, #05-18
 Singapore 757700

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Oct 2021)	
Parts:	N/A	VOLKSWAGEN TOURAN 1.4 TSI (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ3708R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	1,700.00 F	*1,500.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	100.00 F	*30.00 FL
3	1		*REAR BUMPER RETAINER RH	Broken	120.00 F	*120.00 FL
4	1		*REAR BUMPER RETAINER LH	Broken	120.00 F	*120.00 FL
5	1		*REAR TAIL LAMP RH	Broken	880.00 F	*320.00 FL
6	1		*REAR FENDER RH	Repair	2,000.00 F	*- FL
7	10		*REAR FENDER SHIELD CLIPS	Not Necessary	100.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,020.00	2,090.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	209.00
Total Parts (S\$)	5,020.00	1,881.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING (REAR BUMPER ,REAR FENDER RH ,REAR DOOR RH)	New	750.00	400.00
2	REMOVE,REPLACE ,REPAIR AND REFIT ACCIDENT AFFECTED AREAS	New	750.00	400.00
3	REPAIR RIM (REAR RH)	New	100.00	80.00
4	REMOVE AND REFIT REAR REVERSE SENSOR	New	100.00	30.00
5	CHECK AND RECTIFY ELECTRICAL WIRING	New	30.00	30.00
Gross Labour Cost (S\$)			1,730.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >