

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2108-175-TG

DATE : 21-Aug-2021

POLICY NO. : PNCV2019-00000297-02

VEHICLE REG. NO. : SMJ3708R

VEHICLE MAKE : VOLKSWAGEN / TOURAN 1.4 TSI CL 5T1

TO Motor Claim Department

India International Insurance Pte Ltd

64 Cecil Street, #04-#05 IOB Building

Singapore 049711

Tel: 6347 6100 Fax: 6224 4174 / 6225 7743

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 1,700.00	\$ 1,700.00
2	Rear Bumper Clips	10	\$ 10.00	\$ 100.00
3	Rear Bumper Retainer RH	1	\$ 120.00	\$ 120.00
4	Rear Bumper Retainer LH	1	\$ 120.00	\$ 120.00
5	Rear Tail Lamp RH	1	\$ 880.00	\$ 880.00
6	Rear Fender RH	1	\$ 2,000.00	\$ 2,000.00
7	Rear Fender Shield Clips	10	\$ 10.00	\$ 100.00
Total Spare Parts				\$ 5,020.00
	<u>SPECIAL NETT</u>			
				\$ -
Total Special Nett				\$ -
	<u>LABOUR</u>			
8	Spray painting (Rear Bumper, Rear Fender RH, Rear Door RH)	1	\$ 750.00	\$ 750.00
9	Remove, Replace, Repair and Refit Accident Affected Areas	1	\$ 750.00	\$ 750.00
10	Repair Rim (Rear RH)	1	\$ 100.00	\$ 100.00
11	Remove and Refit Rear Reverse Sensor	1	\$ 100.00	\$ 100.00
12	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,730.00
Amount Before Excess				\$ 6,750.00
Add GST @ 7%				472.50
Total Amount Payable				\$ 7,222.50

Estimate prepared by: KenGuan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.