

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 23-Aug-21MODEL: Hyundai IoniqINSURANCE: AIG ASIA *CP/P*VEHICLE NO.: SHA3695AMVA: LIMITS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Rear Door RH <i>X repair</i>	1		\$1,789.90	
	Rear Fender RH <i>due</i>	1		\$1,768.30	✓
	Rear Fender Shield RH <i>X NN</i>	1		\$73.60	
	Rear Bumper <i>X repair</i>	1		\$459.40	
	Rear Bumper Side Retainer RH <i>X scan</i>	1		\$55.80	
	Rear Bumper Cover Clips <i>X</i>	10	\$2.20	\$22.00	
	Rear Wheel Cap RH <i>✓ 24R</i>	1		\$346.40	✓
	SUB TOTAL			\$4,515.40	2114.7
	LESS 20%			\$903.08	
	DISCOUNTED TOTAL			\$3,612.32	1691.76
	Rear Door APPS Sticker RH <i>✓ MC</i>	1		\$80.00	✓
	NETT TOTAL			\$80.00	
	SPARE PARTS TOTAL			\$3,692.32	
	Labour Charge				
	Panel Beating			\$800.00	<i>350.700</i>
	Spray Painting Charge			\$900.00	<i>750</i>
	Remove/Refix Uphostery Etc			\$120.00	<i>60</i>
	R/I Reverse Sensors			\$120.00	<i>40</i>
	Wheel Alignment			\$120.00	<i>60</i>
	Transfer Of Door			\$120.00	<i>X NN</i>
	TOTAL LABOUR			\$2,180.00	
	ESTIMATE TOTAL			\$5,872.32	3381.76

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

5 Days
6/5 P/P before front photos
After repair photos
One Day
apm 23/8/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: