

ASS. FRY:

REF:

CC4/GRB 21008824/Des<sup>3</sup>

## ASSIGNMENT

CUE July 2026

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate Cost: \_\_\_\_\_

OD / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Work to m/s \_\_\_\_\_

of \_\_\_\_\_

Insured \_\_\_\_\_

Policy No \_\_\_\_\_

Claims to \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Check record)

Make of Vh: \_\_\_\_\_

(Police Condition)

Remarks: The vch had commenced its repair at the time of inspection.

Bal. of Market Value: \_\_\_\_\_

IDAC Accident Report \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repair: 10 days Res.: Yes or NoLimit Sum: P/P % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHA 7012UYr Regn: July 2018

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Hyundai Ioniq CC 1580Colour: Blue A/C: Insured / Std / R / NASp. Reading: 296108 T/Radio: Insured / Std / R / NAEng/No: G4LEJU045570C/No: KMHCB851CVJU703379Gen. Cond: Good / Fair / Poor / BurntSteering: In Order / Jammed / Leaked / Burnt orBrake: In Order / Jammed / Leaked / Burnt orModi: Nil / STD A/Rim orTyre Size: F: 195/65 R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUZUKI

TOYO / YOKO or

Westlake

Front

Rear

R/Bal: S mmR/Bal: S mmL/Bal: S mmL/Bal: S mmD.O.A. 19/08/22D.O.I. 24/08/22Survey held at Biprost sin Ming

Des. of Damages: Fnt / Rear / O/S / N/S / W/C / Rooftop or

O/S Rv y O/S Body

The W/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TU SLM 1027G

Damage on TP right door consistent as the advertisement freshly cut. Scene photo is not TP point of impact location as there were debris behind of TP and OI. Contact occurred before TP stopped position.

Increase TP 20,481.76 with 10 days.  
No used part available.. Unable to source.

Date/Time, File Pass to?



: Prel. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

S + RS: \_\_\_\_\_

Photos

Add Fee:



: Site Insp (\$)



: Interview (\$)

Report Format:

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 19-Aug-21

INSURANCE: TH

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHA 7012U

| Description                                                      | Qty | List Price  | Amount      |
|------------------------------------------------------------------|-----|-------------|-------------|
| Boot Lid <i>Dent</i>                                             | 1   | \$ 2,480.40 | \$ 2,480.40 |
| Boot Lid Rubber <i>Hec</i>                                       | 1   | \$ 187.40   | \$ 187.40   |
| Boot Lid Lock Upper <i>Hec</i>                                   | 1   | \$ 224.00   | \$ 224.00   |
| Boot Lid 'H' Emblem <i>Hec</i>                                   | 1   | \$ 28.00    | \$ 28.00    |
| Emblem-Hybrid <i>Hec</i>                                         | 1   | \$ 24.30    | \$ 24.30    |
| Emblem-Ioniq <i>Hec</i>                                          | 1   | \$ 31.30    | \$ 31.30    |
| Boot Lid Lamp(RH) <i>Hec</i>                                     | 1   | \$ 794.40   | \$ 794.40   |
| Boot Lid Trimboard <i>Hec</i>                                    | 1   | \$ 259.70   | \$ 259.70   |
| Boot Lid Trimboard Clips (10pcs) <i>Hec</i>                      | 1   | \$ 11.00    | \$ 11.00    |
| Boot Lid Trimboard, Centre <i>Hec</i>                            | 1   | \$ 159.60   | \$ 159.60   |
| Boot Lid Trimboard SIDE (RH) <i>Hec</i>                          | 1   | \$ 92.50    | \$ 92.50    |
| Boot Lid Trimboard REAR <i>Hec</i>                               | 1   | \$ 124.80   | \$ 124.80   |
| Boot Lid Glass Upper Moulding <i>SR</i>                          | 1   | \$ 186.30   | \$ 186.30   |
| Boot Lid Glass Lower Moulding <i>SR</i>                          | 1   | \$ 145.20   | \$ 145.20   |
| Rear Bumper <i>to be</i>                                         | 1   | \$ 459.40   | \$ 459.40   |
| Rear Bumper Reinforcement <i>crack</i>                           | 1   | \$ 394.80   | \$ 394.80   |
| Rear Bumper Reinforcement Bracket (RH) <i>crack</i>              | 1   | \$ 188.10   | \$ 188.10   |
| Rear Bumper Centre Moulding Assy <i>dislodged</i>                | 1   | \$ 451.25   | \$ 451.25   |
| Rear Bumper Lower Centre Moulding Assy <i>dislodged</i>          | 1   | \$ 47.50    | \$ 47.50    |
| Rear Bumper Stay <i>Hec</i>                                      | 1   | \$ 138.10   | \$ 138.10   |
| Rear Bumper Side retainer (RH) <i>broken</i>                     | 1   | \$ 85.80    | \$ 85.80    |
| Rear Bumper Cover Clips <i>Hec</i>                               | 1   | \$ 22.00    | \$ 22.00    |
| Rear Bumper Under Centre <i>dislodged</i>                        | 1   | \$ 123.85   | \$ 123.85   |
| Rear Bumper Side Under(RH) <i>dislodged</i>                      | 1   | \$ 123.10   | \$ 123.10   |
| Rear Bumper Rear Hook <i>Hec</i>                                 | 1   | \$ 94.60    | \$ 94.60    |
| Rear Bumper Reflector Lamp(RH) <i>dislodged</i>                  | 2   | \$ 82.90    | \$ 165.80   |
| Rear Bumper Towing Cover <i>dislodged</i>                        | 1   | \$ 98.80    | \$ 98.80    |
| Rear Bumper Reserve Light (Parking Brake Light) <i>dislodged</i> | 1   | \$ 328.60   | \$ 328.60   |
| Licence Lamp <i>dislodged</i>                                    | 2   | \$ 193.53   | \$ 387.06   |
| Licence Lamp WIRE <i>SR</i>                                      | 1   | \$ 135.80   | \$ 135.80   |
| Tail Lamp(RH) <i>cut / scratched</i>                             | 1   | \$ 870.40   | \$ 870.40   |
| Tail Lamp Quarter Panel(RH) <i>crack</i>                         | 1   | \$ 208.90   | \$ 208.90   |
| Rear Panel <i>Dent</i>                                           | 1   | \$ 532.00   | \$ 532.00   |
| Rear Panel Garnish <i>Hec</i>                                    | 1   | \$ 346.80   | \$ 346.80   |
| Rear tray tools box RH <i>Hec</i>                                | 1   | \$ 675.30   | \$ 675.30   |
| REAR TRAY LUGGS CENTER <i>Hec</i>                                | 1   | \$ 354.20   | \$ 354.20   |
| Exhaust Pipe Insulator <i>Hec</i>                                | 1   | \$ 235.00   | \$ 235.00   |
| Exhaust Silencer <i>to be</i>                                    | 1   | \$ 943.50   | \$ 943.50   |
| Exhaust Pipe Hanger <i>Hec</i>                                   | 1   | \$ 29.20    | \$ 29.20    |
| Rear Fender(RH) <i>Dent</i>                                      | 1   | \$ 1,768.30 | \$ 1,768.30 |
| Rear Fender SHIELD REAR PIECE (RH) <i>deformed</i>               | 1   | \$ 173.60   | \$ 173.60   |
| Rear Fender SHIELD Frt Piece (RH) <i>Hec</i>                     | 1   | \$ 165.50   | \$ 165.50   |
| Rear Fender Air-Duct (RH) <i>deformed</i>                        | 1   | \$ 87.30    | \$ 87.30    |

|                                               |   |                      |                      |
|-----------------------------------------------|---|----------------------|----------------------|
| Assy BSD Blind Spot Radar (RH) <i>Dem 1st</i> | 1 | \$ 1,625.00          | \$ 1,625.00          |
| Wiring Harness BWS Ext <i>HH</i>              | 1 | \$ 988.90            | \$ 988.90            |
| Rear Tyre Rim (RH) <i>Cnt</i>                 | 1 | \$ 1,124.20          | \$ 1,124.20          |
| Rear Wheel Hub-Cap (RH) <i>HF</i>             | 1 | \$ 346.40            | \$ 346.40            |
| Rear Wheelbearing & Hub assy <i>7 Danc</i>    | 1 | \$ 554.00            | \$ 554.00            |
| Rear Trailing Arm (RH) <i>2 8x</i>            | 1 | \$ 265.40            | \$ 265.40            |
| Rear Assist (RH) <i>2 1st</i>                 | 1 | \$ 227.90            | \$ 227.90            |
| Rear shock Absorber (RH) <i>2 distal</i>      | 1 | \$ 230.50            | \$ 230.50            |
| Rear Shock Absorber Mounting (RH) <i>HH</i>   | 1 | \$ 133.10            | \$ 133.10            |
| Rear Absorber stopper (RH) <i>HH</i>          | 1 | \$ 137.60            | \$ 137.60            |
| Rear Absorber Cover (RH) <i>HH</i>            | 1 | \$ 175.60            | \$ 175.60            |
| Rear Crossmember <i>4x distal 1st</i>         | 1 | \$ 1,468.70          | \$ 1,468.70          |
| Stabilizer Bar <i>HH</i>                      | 1 | \$ 387.30            | \$ 387.30            |
| Stabilizer Link (RH) <i>HH</i>                | 1 | \$ 147.30            | \$ 147.30            |
| Rear Upper Arm (RH) <i>2 distal</i>           | 1 | \$ 239.50            | \$ 239.50            |
| Rear Lower Arm (RH) <i>2 distal</i>           | 1 | \$ 393.10            | \$ 393.10            |
| Rear Knuckle Arm (RH) <i>2 distal</i>         | 1 | \$ 538.10            | \$ 538.10            |
| Frt Door (RH) <i>Demol</i>                    | 1 | \$ 1,797.20          | \$ 1,797.20          |
| Front Door Outer Handle (RH) <i>HH</i>        | 1 | \$ 234.80            | \$ 234.80            |
| Front Door Protector (RH) <i>Hec</i>          | 1 | \$ 186.20            | \$ 186.20            |
| Rear Door (RH) <i>Demol</i>                   | 1 | \$ 1,789.90          | \$ 1,789.90          |
| Rear Door Outer Handle (RH) <i>HH</i>         | 1 | \$ 124.80            | \$ 124.80            |
| Rear Door Protector (RH) <i>Hec</i>           | 1 | \$ <del>186.20</del> | \$ <del>186.20</del> |
| Rocker Panel Outer Garnish <i>HH</i>          | 1 | \$ 715.60            | \$ 715.60            |

SUB TOTAL

\$ 28,380.76

LESS 20%

\$ 5,676.15

DISCOUNTED TOTAL

\$ 22,704.61

166.19

20608.46

16486.76

|                                                        |    |   |           |           |
|--------------------------------------------------------|----|---|-----------|-----------|
| Boot Lid Comfort Logo & Tel No. Sticker <i>Hec</i>     | SN | 1 | \$ 35.00  | \$ 35.00  |
| Boot Lid Comfort Cablink Tel No. Sticker <i>HF</i>     | SN | 1 | \$ 30.00  | \$ 30.00  |
| Boot Lid Advertisement Logo <i>Hec</i>                 | SN | 1 | \$ 100.00 | \$ 100.00 |
| Rear No. Plate + Trim Cover <i>dislodged</i>           | SN | 1 | \$ 45.00  | \$ 45.00  |
| Rear Windscreen Sealant <i>4x Hec</i>                  | SN | 2 | \$ 46.00  | \$ 92.00  |
| Rear Bumper Advertisement Logo <i>Hec</i>              | SN | 1 | \$ 120.00 | \$ 120.00 |
| Rear Bumper Rubber Mat <i>Hec</i>                      | SN | 1 | \$ 50.00  | \$ 50.00  |
| Rear Bumper Reverse Sensor <i>Danc</i>                 | SN | 1 | \$ 180.00 | \$ 180.00 |
| Rear Fender Advertisement Logo (RH) <i>Hec</i>         | SN | 1 | \$ 100.00 | \$ 100.00 |
| Rear Tyre (RH) <i>Cnt / Punctured 50% to def</i>       | SN | 1 | \$ 216.00 | \$ 216.00 |
| Front Door City Cab Logo (RH) <i>Hec HH</i>            | SN | 1 | \$ 75.00  | \$ 75.00  |
| Front Door Comfort Logo (RH) <i>Hec</i>                | SN | 1 | \$ 75.00  | \$ 75.00  |
| Front Door Advertisement Logo (RH) <i>Hec</i>          | SN | 1 | \$ 100.00 | \$ 100.00 |
| Rear Door Advertisement Logo (RH) <i>Hec</i>           | SN | 1 | \$ 100.00 | \$ 100.00 |
| Rear Door Tel No. Sticker (RH) <i>Hec HF</i>           | SN | 1 | \$ 10.00  | \$ 10.00  |
| Rear Door Comfortdelgro & Apps Sticker (RH) <i>Hec</i> | SN | 1 | \$ 80.00  | \$ 80.00  |
| Rocker Panel Outer Garnish Advertisement <i>HH</i>     | SN | 1 | \$ 120.00 | \$ 120.00 |

SUB TOTAL

\$ 1,528.00

# Labour Charge

|                       |   |            |            |
|-----------------------|---|------------|------------|
| Panel Beating         | 1 | \$1,800.00 | \$1,800.00 |
| Spray Painting Charge | 1 | \$1,600.00 | \$1,600.00 |
| Wiring Charge         | 1 | \$100.00   | \$100.00   |
| Tuff Kote             | 1 | \$100.00   | \$100.00   |

1200-1000-

1200-1000-

301-

401-

1185.00

|                                            |   |          |                     |
|--------------------------------------------|---|----------|---------------------|
| Towing Charge                              | 1 | \$80.00  | \$80.00             |
| Remove/Refix Cushion & Upholstery Rear     | 1 | \$150.00 | \$150.00            |
| Remove/Refix Rear Windscreen Glass         | 2 | \$120.00 | \$240.00            |
| Remove/Refix Reverse Sensor                | 1 | \$120.00 | \$120.00            |
| Remove/Refix Undercarriage (RR)            | 1 | \$400.00 | \$400.00            |
| Re-set Rear ABS System                     | 1 | \$400.00 | \$400.00            |
| Remove/Refix Fuel Tank                     | 1 | \$80.00  | \$80.00             |
| Remove/Refix Exhaust Pipe                  | 1 | \$80.00  | \$80.00             |
| Transfer of Door Mechanism FRONT           | 1 | \$80.00  | \$80.00             |
| Re-set Frt Power Window System             | 1 | \$200.00 | \$200.00            |
| Transfer of Door Mechanism REAR            | 1 | \$80.00  | \$80.00             |
| Re-set Rear Power Window System            | 1 | \$200.00 | \$200.00            |
| Four Wheel Alignment                       | 1 | \$120.00 | \$120.00            |
| Diagnostic & Resetting To Erase Fault Code | 1 | \$550.00 | \$550.00            |
| Diagnostic & Resetting ADAS Optical sensor | 1 | \$550.00 | \$550.00            |
|                                            |   |          |                     |
| <b>TOTAL LABOUR</b>                        |   |          | <b>\$6,930.00</b>   |
|                                            |   |          |                     |
| <b>ESTIMATE TOTAL</b>                      |   |          | <b>\$ 31,162.61</b> |

44  
 80/-  
 80/-  
 40/-  
 150/-  
 44  
 44  
 60/- 2810.00  
 60/-  
 44  
 60/-  
 44  
 60/-  
 150/-

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

24/08/2021 e 1100hrs

P/P 20481.76

Net Amount

2/Sept 10 days.

ryan

LKK Auto

8

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: