

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

21-Aug-21

Our ref : TP/5019/21

Artlas Pte Ltd

TP A19.
Xiao Tony

A19

RE : estimate cost for vehicle no : GBK 9475Y

1 pc	tailgate <i>Dented</i>
1 pc	tailgate logo <i>Nil</i>
1 pc	tailgate Toyota Hiace sticker <i>Nil</i>
1 pc	tailgate lock <i>Dented</i>
1 pc	tailgate lock cover <i>Dented</i>
1 pc	rear bumper <i>Dented</i>
2 pcs	rear bumper retainer <i>Nil</i>
4 pcs	rear bumper lower brackets <i>Best</i>
6 pcs	rear bumper clips <i>Nil</i>
1 pc	end panel inner <i>Rys</i>
1 pc	end panel outer <i>Dented</i>
1 pc	step panel <i>Dented</i>
1 pc	spare tyre tray <i>Nil</i>

4079
305925.

1835
2,150.00
75.00
48.00
275.00
58.00
615.00
200.00
240.00
30.00
975.00
568.00
275.00
165.00

less 25%

5,374.00
1,343.50
4,030.50

1 pc	70km/h sticker <i>Nil</i>
1 pc	reverse sensor <i>Dented</i>
1 pc	rear w/screen gum <i>Nil</i>
1 pc	rear w/screen seal <i>Nil</i>
1 pc	rear no plate <i>Remove it</i>

325

35.00	snett
250.00	200
50.00	40
30.00	
40.00	
1,000.00	800
1,000.00	600
30.00	
120.00	
80.00	60

Panel beating.
Spray painting.
Wiring.
Remove & refit rear w/screen.
Transfer tailgate fitting.

1610

6,665.50
466.59
7,132.09

Plus 7% GST

SD : Seven thousand one hundred thirty-two & cents nine only.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
L/S 21/08/21
06 days
total: 495425
L/S: HK