

8833/AV

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

TEL: 63896111 FAX: 62247175
 ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
 Accident Date: 19/08/2021
 TP Veh Reg No: PC2632H

Estimate No: EST2100214
 Date: 20 Aug 2021

Veh Reg No: SMC2379A
 Make/Model: TOYOTA VIOS E AUTO
 Chasis No: MR2B23F3901122803
 Reg. Date: 28/06/2018
 Your Ref No: PC2632H

Justin.

Estimate Repair Cost to Vehicle No :SMC2379A

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID Distorted	899.70 ✓	193
2	1 PC BOOTLID LOGO New	62.80 ✓	
3	1 PC BOOT LID "VIOS" EMBLEM } New	43.60 ✓	
4	1 PC BOOT LID "E" EMBLEM	38.60 ✓	
5	1 PC BOOT LID RUBBER cut	166.40 ✓	
6	2 PCS BOOTLID HINGE Bent	330.40 ✓	
7	1 PC BOOT LID LOCK Dmg	360.40 ✓	
8	1 PC BOOTLID INNER TRIM Delnd	278.90 ✓	
9	1 PC BOOT LID LAMP LH } combined	279.80 ✓	
10	1 PC BOOT LID LAMP RH	279.80 ✓	
11	1 PC REAR PANEL Dented	728.70 ✓	582
12	1 PC REAR PANEL TRIM Delnd	262.30 ✓	
13	1 PC REAR ANTENNA SENSOR Dmg	165.50 ✓	
14	1 PC REAR BUMPER Distorted	482.20 ✓	
15	1 PC REAR BUMPER REINFORCEMENT Bent	316.10 ✓	
16	2 PCS REAR BUMPER BRACKET Dented	183.20 ✓	
17	2 PCS REAR BUMPER SIDE RETAINER (LONG) Dmg	333.00 ✓	
18	2 PCS REAR BUMPER SIDE RETAINER (SHORT) New	145.40 ✓	
19	1 PC REAR BUMPER REFLECTOR - LH New	102.80 +	
20	1 PC REAR BUMPER REFLECTOR - RH combined	102.80 ✓	
21	1 PC REAR FENDER RH Bunched	892.10 ✓	
22	1 PC REAR FENDER INNER TRIM RH torn	355.90 ✓	
23	1 PC TAIL LAMP - RH } cut	397.90 ✓	
24	1 PC TAIL LAMP LH	397.90 ✓	
25	1 PC REAR FENDER INNER TRIM LH New	355.90 +	
26	1 PC REAR SPARE TYRE HARDBOARD torn	206.90 ✓	
27	1 PC SPARE TYRE PANEL LH SPONGE } torn	244.10 ✓	
28	1 PC SPARE TYRE PANEL RH SPONGE	244.10 ✓	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 19/08/2021
TP Veh Reg No: PC2632H

Estimate No: EST2100214

Date: 20 Aug 2021

Veh Reg No: **SMC2379A**
Make/Model: TOYOTA VIOS E AUTO
Chasis No: MR2B23F3901122803
Reg. Date: 28/06/2018
Your Ref No: PC2632H

Estimate Repair Cost to Vehicle No :SMC2379A

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
		8.657.20	
	Less 25%	2.164.30	6.492.97
	Special Net		
29	1 PC BOOT LID NUMBER '612' STICKER <i>neu</i>	35.00 ✓	
30	1 SET BOOT LID TRIM CLIPS <i>neu</i>	50.00 20	
31	1 PC REAR NUMBER PLATE <i>Dented</i>	50.00 ✓	
32	1 SET REAR PANEL TRIM CLIPS <i>neu</i>	40.00 10	
33	1 PC "L" PLATE <i>Bent</i>	70.00 40	
34	2 PCS "L" PLATE BRACKET <i>neu</i>	70.00 50	
35	1 SET REAR BUMPER STICKER <i>neu</i>	280.00 220	
36	1 PC REAR WINDSCREEN RUBBER <i>neu</i>	60.00 ✓	
37	1 PC REAR WINDSCREEN SEALANT <i>neu</i>	60.00 ✓	
38	1 SET REAR FENDER INNER TRIM CLIPS <i>neu</i>	60.00 30	
		775.00	775.00
	Labour		
39	1 TO CHECK WIRING	50.00 30	
40	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00 ✓	
41	1 TO REMOVE AND REFIT SEAT CUSHION	200.00 80	
42	1 TO SPRAY UNDERSEAL	120.00 60	
43	1 TO REPLACE STICKER	100.00 ✓	
44	1 TO REMOVE AND REFIT INNER TRIM	100.00 60	
45	1 (REAR) TO SPRAY PAINTING	1,500.00 1200	
46	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,800.00 1300	
		3.990.00	3.990.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 19/08/2021
TP Veh Reg No: PC2632H

Estimate No: EST2100214
Date: 20 Aug 2021

Veh Reg No: SMC2379A
Make/Model: TOYOTA VIOS E AUTO
Chasis No: MR2B23F3901122803
Reg. Date: 28/06/2018
Your Ref No: PC2632H

Estimate Repair Cost to Vehicle No :SMC2379A

Quantity	Description	List Price	Amount
		SS	SS
		Total	S\$ 11,257.97
		Add GST @ 7%	788.06
		Total Amount Payable	S\$ 12,046.03

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND FORTY SIX AND CENTS THREE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
r/s 20/08/21
09 Days
Tel: 957387
r/s: 7.6K
7.6K