

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 19/08/2021
TP Veh Reg No: PC2632H

Estimate No: EST2100214
Date: 20 Aug 2021

Veh Reg No: **SMC2379A**
Make/Model: TOYOTA VIOS E AUTO
Chasis No: MR2B23F3901122803
Reg. Date: 28/06/2018
Your Ref No: PC2632H

Estimate Repair Cost to Vehicle No :SMC2379A

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BOOT LID	899.70	
2	1 PC BOOTLID LOGO	62.80	
3	1 PC BOOT LID "VIOS" EMBLEM	43.60	
4	1 PC BOOT LID "E" EMBLEM	38.60	
5	1 PC BOOT LID RUBBER	166.40	
6	2 PCS BOOTLID HINGE	330.40	
7	1 PC BOOT LID LOCK	360.40	
8	1 PC BOOTLID INNER TRIM	278.90	
9	1 PC BOOT LID LAMP LH	279.80	
10	1 PC BOOT LID LAMP RH	279.80	
11	1 PC REAR PANEL	728.70	
12	1 PC REAR PANEL TRIM	262.30	
13	1 PC REAR ANTENNA SENSOR	165.50	
14	1 PC REAR BUMPER	482.20	
15	1 PC REAR BUMPER REINFORCEMENT	316.10	
16	2 PCS REAR BUMPER BRACKET	183.20	
17	2 PCS REAR BUMPER SIDE RETAINER (LONG)	333.00	
18	2 PCS REAR BUMPER SIDE RETAINER (SHORT)	145.40	
19	1 PC REAR BUMPER REFLECTOR - LH	102.80	
20	1 PC REAR BUMPER REFLECTOR - RH	102.80	
21	1 PC REAR FENDER RH	892.10	
22	1 PC REAR FENDER INNER TRIM RH	355.90	
23	1 PC TAIL LAMP - RH	397.90	
24	1 PC TAIL LAMP LH	397.90	
25	1 PC REAR FENDER INNER TRIM LH	355.90	
26	1 PC REAR SPARE TYRE HARDBOARD	206.90	
27	1 PC SPARE TYRE PANEL LH SPONGE	244.10	
28	1 PC SPARE TYRE PANEL RH SPONGE	244.10	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 19/08/2021
TP Veh Reg No: PC2632H

Estimate No: EST2100214
Date: 20 Aug 2021

Veh Reg No: **SMC2379A**
Make/Model: TOYOTA VIOS E AUTO
Chasis No: MR2B23F3901122803
Reg. Date: 28/06/2018
Your Ref No: PC2632H

Estimate Repair Cost to Vehicle No :SMC2379A

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		8,657.20	
	Less 25%	<u>2,164.30</u>	6,492.97
	Special Net		
29	1 PC BOOT LID NUMBER '612' STICKER	35.00	
30	1 SET BOOT LID TRIM CLIPS	50.00	
31	1 PC REAR NUMBER PLATE	50.00	
32	1 SET REAR PANEL TRIM CLIPS	40.00	
33	1 PC "L" PLATE	70.00	
34	2 PCS "L" PLATE BRACKET	70.00	
35	1 SET REAR BUMPER STICKER	280.00	
36	1 PC REAR WINDSCREEN RUBBER	60.00	
37	1 PC REAR WINDSCREEN SEALANT	60.00	
38	1 SET REAR FENDER INNER TRIM CLIPS	<u>60.00</u>	
		775.00	775.00
	Labour		
39	1 TO CHECK WIRING	50.00	
40	1 TO REMOVE AND REFIT REAR WINDSCREEN	120.00	
41	1 TO REMOVE AND REFIT SEAT CUSHION	200.00	
42	1 TO SPRAY UNDERSEAL	120.00	
43	1 TO REPLACE STICKER	100.00	
44	1 TO REMOVE AND REFIT INNER TRIM	100.00	
45	1 (REAR) TO SPRAY PAINTING	1,500.00	
46	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	<u>1,800.00</u>	
		3,990.00	3,990.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 19/08/2021
TP Veh Reg No: PC2632H

Estimate No: EST2100214

Date: 20 Aug 2021

Veh Reg No: **SMC2379A**
Make/Model: TOYOTA VIOS E AUTO
Chasis No: MR2B23F3901122803
Reg. Date: 28/06/2018
Your Ref No: PC2632H

Estimate Repair Cost to Vehicle No :SMC2379A

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 11,257.97
	Add GST @ 7%		788.06
	Total Amount Payable		<u>S\$ 12,046.03</u>

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND FORTY SIX AND CENTS THREE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE