

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8454K

19.08.21

MAKE :

MODEL HYU- I40

CHIANG/ CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REFLECTOR LH /RH		\$32.00	\$64.00
1	REAR BUMPER REINFORCEMENT			\$428.40
1	REAR BUMPER UNDER COVER			\$228.00
1	BOOTID COVER			\$2,609.80
1	BOOTLID EMBLEM CRDI			\$52.40
1	BOOTLID H EMBLEM			\$63.10
1	BOOTLID EMBLEM I40			\$52.40
			3905.70	\$4,697.30
	20.00% DISCOUNTED TOTAL		3124.56	\$939.46
				\$3,757.84
1	BOOTLID ADVERTISEMENT			\$50.00
1	REAR BUMPER ADVERTISEMENT			\$50.00
1	REAR BUMPER MAT			\$50.00
1	BOOTID COMFORT & TEL NUMBER STICKER			\$60.00
1	REVERSE SENSOR			\$135.70
			345.70	\$345.70
	Labour Charge			
	Panel Beating			\$600.00
	Spray Painting Charge			\$600.00
	Remove/refix reverse sensor		1150	\$60.00
	Check lighting			\$60.00
	Tuff Kote			\$90.00
	TOTAL LABOUR		4620.26	\$1,410.00
	ESTIMATE TOTAL		61593700	\$6,059.45
			03 days #	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanpak 97495749
 WP 20/8/21 @ 1650
 L/S Resurvey after repair
 Tanpak @ fkh anforion
 - 03 - days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: