

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHC8454K

19.08.21

MAKE :

MODEL HYU- I40

CHIANG/ CHINA

| Qty                                                                                                                                                                                                            | Parts Description/ Labour           | Type | Unit Price | Amount            |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|------|------------|-------------------|
| 1                                                                                                                                                                                                              | REAR BUMPER COVER                   |      |            | \$1,106.00        |
| 2                                                                                                                                                                                                              | REAR BUMPER BRACKET SIDE LH/RH      |      | \$35.60    | \$71.20           |
| 10                                                                                                                                                                                                             | REAR BUMPER CLIPS                   |      | \$2.20     | \$22.00           |
| 1                                                                                                                                                                                                              | REAR BUMPER REFLECTOR LH /RH        |      | \$32.00    | \$64.00           |
| 1                                                                                                                                                                                                              | REAR BUMPER REINFORCEMENT           |      |            | \$428.40          |
| 1                                                                                                                                                                                                              | REAR BUMPER UNDER COVER             |      |            | \$228.00          |
| 1                                                                                                                                                                                                              | BOOTID COVER                        |      |            | \$2,609.80        |
| 1                                                                                                                                                                                                              | BOOTLID EMBLEM CRDI                 |      |            | \$52.40           |
| 1                                                                                                                                                                                                              | BOOTLID H EMBLEM                    |      |            | \$63.10           |
| 1                                                                                                                                                                                                              | BOOTLID EMBLEM I40                  |      |            | \$52.40           |
|                                                                                                                                                                                                                |                                     |      |            | <b>\$4,697.30</b> |
|                                                                                                                                                                                                                | 20.00%                              |      |            | <b>\$939.46</b>   |
|                                                                                                                                                                                                                | <b>DISCOUNTED TOTAL</b>             |      |            | <b>\$3,757.84</b> |
| 1                                                                                                                                                                                                              | BOOTLID ADVERTISEMENT               |      |            | \$50.00           |
| 1                                                                                                                                                                                                              | REAR BUMPER ADVERTISEMENT           |      |            | \$50.00           |
| 1                                                                                                                                                                                                              | REAR BUMPER MAT                     |      |            | \$50.00           |
| 1                                                                                                                                                                                                              | BOOTID COMFORT & TEL NUMBER STICKER |      |            | \$60.00           |
| 1                                                                                                                                                                                                              | REVERSE SENSOR                      |      |            | \$135.70          |
|                                                                                                                                                                                                                |                                     |      |            | <b>\$345.70</b>   |
|                                                                                                                                                                                                                | <b>Labour Charge</b>                |      |            |                   |
|                                                                                                                                                                                                                | Panel Beating                       |      |            | \$600.00          |
|                                                                                                                                                                                                                | Spray Painting Charge               |      |            | \$600.00          |
|                                                                                                                                                                                                                | Remove/refix reverse sensor         |      |            | \$60.00           |
|                                                                                                                                                                                                                | Check lighting                      |      |            | \$60.00           |
|                                                                                                                                                                                                                | Tuff Kote                           |      |            | \$90.00           |
|                                                                                                                                                                                                                | <b>TOTAL LABOUR</b>                 |      |            | <b>\$1,410.00</b> |
|                                                                                                                                                                                                                | <b>ESTIMATE TOTAL</b>               |      |            | <b>\$6,059.45</b> |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. |                                     |      |            |                   |

Tanpak 97485749  
 WP 20/8/21 @ 1650  
 L/S Resurvey after repair  
 Tanpak 97485749  
 03-days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Team: ARC Repair TP(CLSO)1

**JOB CARD**

Sales Order:

JC NO.: 305483731

STOMER

VMS COMFORT TRANSPORTATION PTE LTD  
STOMER NO. 7010045  
DRESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
65508755 (R) (O)  
(P)

COUNT CARD NO.


|                                |                               |
|--------------------------------|-------------------------------|
| REGN NO.: SHC8454K             | MILEAGE                       |
| MAKE: HYUNDAI                  | FUEL E.....1/2.....F          |
| MODEL I-40                     | DATE/TIME IN 20.08.2021 10:20 |
| YR OF MANU. 09.06.2016         | TARGET DATE                   |
| CHASSIS CODE KMHLB41UMGU091331 | COMPLETION DATE/TIME:         |

JOB DESCRIPTION

Accident Date: 19.08.2021

NATURE: 3P 19.08.2021

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC8454K CHIANG

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard